INSTALLED EQUIPMENT

	III/21VEFFD EGOILI	VIEIVI	
ITEM	MANUFACTURER	MODEL	SERIAL NO.
ENGINE	Continental Molors Inc	1310550K	R 1008884
ENGINE			R
PROPELLER	Hartzell Progetter Inc	PHC-53Y1F-1N	115 = 0 : 0
PROPELLER	Jane 18	112 33 1 17 -11	N5791B
ENGINE			
ENGINE			
PROPELLER			
PROPELLER			
ENGINE			
ENGINE			
PROPELLER			
PELLER			

MAJOR ALTERATIONS

DESCRIPTION OF ALTERATION


STC's SA01708SE (Fixed Oxygen System) & SA02013CH (Traffic Advisory System) have been installed on this aircraft. Approval for installation has been granted by the STC holders via Licensing Agreements and the FAA via the Production Certificate / Production Limitation Record. FAA Form 337 not required for these installations.

CDC COO

on 8 / 19/13

Cirrus Design Corporation Duluth, MN USA

PRODUCTION CERTIFICATE NO. 338CE



ORTHINESS DIRECTIVE/FACTORY BU

UK	IHINE22	DIRECTIVE/FA	ICIUNI D	U
ED	DATE & HRS. AT COMP.	METHOD OF COMPLIANCE	TYPE OF A.D. 1 TIME/RECUR.	
	9-23-2013	Searched AD issue 20/3 compliance a	All At this time.	oi- AI
	202.8 Hubbs 169.8 FLT.		ALÁVIAT	
		Search AD's through All AD's are in com		TO SHE WAS A

I certify that the altimeter, static system, transponder, and altitude
reporter test required by FAR's 91.411, 91.413, & 91.217 have
been performed and found within the limits of FAR 43 appendices
E & F and AC 43-6B.
TESTED TO 25,000 FEET ON 08/29/2013
Transponder: Mfg Garmin P/N 24653-002
Model: GTX-33ES S/N 89125523
ADC 1: Model GDC74A P/N 24651-001
S/N 20615714 .
ADC 2: Model GDC74A P/N 24651-001
S/N 20615757.
Altimeter: Mfg United P/N 12731-003
S/N 501268
CDC Quality Assurance on on 129 /29 /2013
Cirrus Design Corporation Duluth, MN USA
PC# 338CE



Date 11/9/2016

W/O# 15647

Airframe Logbook Entry CRS AWKR298C

25170 Aviation Ave., Davis, CA 95616

AIRCRAFT: N 52VS S/N: 0601

Tach

382.9 COMPLIED WITH CIRRUS SB2X-42-10 PERSPECTIVE SW UPDATE TO V0764.23.

SOFTWARE, NEW COCKPIT REFERENCE GUIDE, AND NEW PILOT'S GUIDE.

COMPLIED WITH CIRRUS SA16-06 AND GARMIN SA 1612, UPDATED IGRF MAGNETIC VARIATION.

DATABASE FROM 2010 TO 2015 WITH NO DISCREPANCIES NOTED.

The Aircraft and/or component identified above was repaired and inspected IAW FAA regulations and was found airworthy to return to service only for the work performed. Pertinent details of the repair are on file at this agency:

Shawn Matthies AWKR298C



409.3

Date 11/29/2017

Airframe Logbook Entry
CRS AWKR298C

AIRCRAFT: N 52VS

W/O# 16503

25170 Aviation Ave., Davis, CA 95616

S/N: 0601

Tac

Tach

REMOVED GARMIN GDU 1240A PFD P/N 011-01440-30 (CIRRUS P/N 24655-003), S/N 14Y006042 AND INSTALLED WARRANTY REPLACEMENT GDU 1240A P/N 011-01440-30 (CIRRUS P/N 24655-003), S/N 14Y006278 AFTER BEING OVERHAULED BY GARMIN INTERNATIONAL, CRS# G6XR582Y UNDER SO# 13723630 DATED 6/21/2017. LOADED SOFTWARE, CONFIGURED SYSTEM FOR CUSTOMER'S AIRCRAFT, AND PERFORMED GROUND FUNCTIONAL TESTS WITH NO DISCREPANCIES NOTED. TESTED TRIPLE ALTIMETER, ALTITUDE REPORTING SYSTEM, PITOT/STATIC SYSTEM, AND TRANSPONDER SYSTEM PER FAR 43, APPENDICES E AND F. THOSE SYSTEMS MET REQUIREMENTS OF FAR 91.411 AND 91.413 FOR NON-PRESSURIZED AIRCRAFT TO 25,000 FEET.

The Aircraft and/or component identified above was repaired and inspected IAW FAA regulations and was found airworthy to return to service only for the work performed. Pertinent details of the repair are on file at this agency:

Signed:



Date 6/29/2018

W/O# 16894

Airframe Logbook Entry CRS AWKR298C

AIRCRAFT: N 52VS

S/N: 0601

25170 Aviation Ave., Davis, CA 95616

Tach

420.1 COMPLIED WITH CIRRUS SB2X-42-12 UPDATING CIRRUS PERSPECTIVE SOFTWARE FROM VERSION 0764.23 TO VERSION 0764.35. CONFIGURED SYSTEM FOR CUSTOMER'S AIRCRAFT AND CONFIRMED – NO DISCREPANCIES NOTED.

REMOVED GARMIN GRT 10 P/N 011-01557-00, S/N 14Q002857. INSTALLED GARMIN FLIGHT STREAM — 210 P/N 011-03257-40, S/N 3RE007140 PER CIRRUS AIRCRAFT WIRING MANUAL 34-50-08 AND 31-60-02, AND FLIGHT STREAM 110/210 TSO INSTALLATION MANUAL. LOADED FLIGHT STREAM 210 SOFTWARE — FOR CUSTOMER'S AIRCRAFT. REMOVED ALTIMETER P/N 5934D-3A.249G (CIRRUS P/N 12731-002), S/N 501211, AND MID-CONTINENT ATTITUDE INDICATOR P/N 4300-208, S/N G13-10843. INSTALLED — ENVISION STANDBY INSTRUMENT PANEL. INSTALLED NEW GARMIN G5 ADAHRS P/N 011-03809-00, S/N 4JQ018985 AS A STANDBY INSTRUMENT. THIS INSTALLATION HAS BEEN REVIEWED AND HAS BEEN — DETERMINED TO BE A MINOR ALTERATION. CONFIGURED AND CALIBRATED INSTRUMENT AND PERFORMED GROUND FUNCTIONAL TESTS WITH NO DISCREPANCIES NOTED. INSTALLED 2 NEW — MID-CONTINENT MD93 CLOCK/USB POWER SUPPLIES P/N 6420093-1, S/NS L17-10539 AND L17-11233 IN STANDBY INSTRUMENT SUBPANEL ON EITHER SIDE OF THE GARMIN G5 ADAHRS.

The Aircraft and/or component identified above was repaired and inspected IAW FAA regulations and was found airworthy to return to service only for the work performed. Pertinent details of the repair are on file at this agency:

		Shawn Matthies		
			4	
1	,			
The second secon				

RADIO & ELECTRONIC CHECKS **NEXT CHECK**

EDDOD OR

DATE	TOTAL TIME	EQUIPMENT CHECKED	TYPE OF CHECK	RESULTS	DUE
DAIL	IIME				E. C.
	Complete Com	er de constant de la			-
					displayed and the second secon
			and the second		DATE: 7/17/2018
	MAKE: Cirrus MODEL: SR22T		aft Services, LLC.		A/C TSN: 439.7 TACH: 439.7
	S/N: 0601 REG. NO: N52VS WORK ORDER: Murrieta8963-07-2018	Repair Station No. CR: 37680 Sky Canyon Dri #602	S 2SDR271B ve		t Kna tribut
	Mumetao903-07-2010	Murrieta, CA 92563 Phone: 951-698-4260	Control of the second s		
	Airframe Entries				
	Inspected the following Checked brakes	ng, no defects noted,			

- Check brake reservoir
- Check tire pressures and wear
- Checked brake temp stickers
- Checked brake pads for wear

I Certify that with respect to only the work perfromed on the above identified Aircraft, Engine, Propeller or Appliance was repaired and inspected in accordance with current FAA regulations and is APPROVED for return to service All work performed

DATE	TIME	EQUIPMENT CHECKED	TYPE OF CHECK	LECTRONIC CI ERROR OR RESULTS	NEXT CHECK	CHECKED
				NESUL13	DUE	CHECKED I SIGNATURE — C
						All James and American State of the Control of the
	MAKE: C MODEL:	: SR22T	ryphon Aircraft Services,	LLC.	DATE: 11/1/2	
	WORK O	D: N22CW 376 DRDER: #60	pair Station No. CRS 2SDR271B 380 Sky Canyon Drive 02		A/C TSN: 44 TACH: 4	
	Murrieta9	9092-09-2018 Mui	one: 951-698-4260			
		me Entries				
	40/0, IA	AVV Cirrus MM Chap	panels, arm rest panels and edge oter 24, performed post installation	checks IAW MM Inspected	copilot's outside seat belt and for	ound
reconstruction	assy to r re-racke	retract as far as med ed all GIA'a and trea	chanically possible. System works ated connections with Stabilant-22	properly with no hang ups : - Could not duplicate problem	Swapped GIA's, Removed and Inflated tires to correct press	
Sept.	Checked	ed brake temp sticker	r, Checked brake pads and found ort, operationally checked system for	to be within limits at this time,	estimating 50% life Labeled	
	Market Committee of the	The state of the s	The state of the s	the state of the s	engle of Section - p. co.	<u> </u>
	I Certify	that with respect to	only the work perfromed on the at	bove identified Aircraft, Engine	e, Propeller or Appliance was	
	repaired	d and inspected in a	accordance with current FAA regulations or other approved documents	ations and is APPROVED for ation. Pertinent details of the	return to service. All work perfor	med
	repaired IAW app under W	d and inspected in a	accordance with current FAA regula	ations and is APPROVED for ation. Pertinent details of the	return to service. All work perfor	acility
The state of the s	repaired IAW app under W	d and inspected in a plicable service man Vork Order No. Murr	ccordance with current FAA regulariuals or other approved documentarieta9092-09-2018. FAA CRS #2S SIGNED:	ations and is APPROVED for ation. Pertinent details of the DR271B.	return to service.All work perfor repair are on file at this repair fa	-2018
The state of the s	repaired IAW app under W	d and inspected in a plicable service man Vork Order No. Murr	ccordance with current FAA regularization of the current specific factors of the current speci	ations and is APPROVED for ation. Pertinent details of the DR271B.	return to service. All work perfor repair are on file at this repair fa Work Order: Murrieta 9092-09	-2018
and the second of the second o	repaired IAW app under W	d and inspected in a plicable service man Vork Order No. Murr	ccordance with current FAA regulariuals or other approved documentarieta9092-09-2018. FAA CRS #2S SIGNED:	ations and is APPROVED for ation. Pertinent details of the DR271B.	return to service. All work perfor repair are on file at this repair fa Work Order: Murrieta 9092-09	-2018
The state of the s	repaired IAW app under W	d and inspected in a plicable service man Vork Order No. Murr	ccordance with current FAA regulariuals or other approved documentarieta9092-09-2018. FAA CRS #2S SIGNED:	ations and is APPROVED for ation. Pertinent details of the DR271B.	return to service. All work perfor repair are on file at this repair fa Work Order: Murrieta 9092-09	-2018
The state of the s	repaired IAW app under W	d and inspected in a plicable service man Vork Order No. Murr	ccordance with current FAA regulariuals or other approved documentarieta9092-09-2018. FAA CRS #2S SIGNED:	ations and is APPROVED for ation. Pertinent details of the DR271B. CRS 2SDR271B	return to service. All work perfor repair are on file at this repair fa Work Order: Murrieta 9092-09	-2018
and contain the state of the st	repaired IAW app under W	d and inspected in a plicable service man Vork Order No. Murr	ccordance with current FAA regulariuals or other approved documentarieta9092-09-2018. FAA CRS #2S SIGNED:	ations and is APPROVED for ation. Pertinent details of the DR271B.	return to service. All work perfor repair are on file at this repair fa Work Order: Murrieta 9092-09	-2018
The Control of Control of the Contro	repaired IAW app under W	d and inspected in a plicable service man Vork Order No. Murr	ccordance with current FAA regulariuals or other approved documentarieta9092-09-2018. FAA CRS #2S SIGNED:	ations and is APPROVED for ation. Pertinent details of the DR271B. CRS 2SDR271B	return to service. All work perfor repair are on file at this repair fa Work Order: Murrieta 9092-09	-2018
The Control of the Co	repaired IAW app under W	d and inspected in a plicable service man Vork Order No. Murr	ccordance with current FAA regulariuals or other approved documentarieta9092-09-2018. FAA CRS #2S SIGNED:	ations and is APPROVED for ation. Pertinent details of the DR271B. CRS 2SDR271B	return to service. All work perfor repair are on file at this repair fa Work Order: Murrieta 9092-09	-2018

MAKE: Cirrus	Gryphon Aircraft Services, LLC.	
MODEL: SR22T S/N: 0601	The state of the s	DATE: 12/13/2018
REG. NO: N22CW WORK ORDER: Murrieta9216-11-2018	Repair Station No. CRS 2SDR271B 37680 Sky Canyon Drive #602	A/C TSN: 468.8 TACH: 468.8
Washington Co.	Murrieta, CA 92563 Phone: 951-698-4260	200 mm and
Airframe Entries	THE COLD AND THE PROPERTY OF T	a section in the first that the section of the sect
Complied with SB2X-4	2-15, Update of Garmin Software to v764.36	
DATE: 12/13/2018	SIGNED:	Work Order: Mussista 2010
DATE: 12/13/2018	SIGNED: Glen Kratz Certified Repair Station No. CRS 2SDR271B	Work Order: Murrieta9216-11-2018 Printed by EBis 3 (datcomedia.com)
DATE: 12/13/2018	Glen Kratz	1.7 Me 7 mg
DATE: 12/13/2018	Glen Kratz	1.7 Me 7 mg
DATE: 12/13/2018	Glen Kratz	1.7 Me 7 mg
DATE: 12/13/2018	Glen Kratz	1.7 Me 7 mg
DATE: 12/13/2018	Glen Kratz Certified Repair Station No. CRS 2SDR271B	1.7 Me 7 mg
DATE: 12/13/2018	Glen Kratz	1.7 Me 7 mg
DATE: 12/13/2018	Glen Kratz Certified Repair Station No. CRS 2SDR271B	1.7 Me 7 mg



MAKE: Cirrus MODEL: SR22T S/N: 0601 REG. NO: N22CW WORK ORDER: Murrieta11285-12-2021



Gryphon Aircraft Services, LLC.

37680 Sky Canyon Drive #602 Murrieta, CA 92563 Phone: 951-698-4260

DATE: 1/21/2022

A/C TSN: 727.8 TACH: 727.8 SIGNATURE

Airframe Entries

Completed A ANNUAL INSPECTION per Manufacturer's and Gryphon Aircraft Services Inspection forms - Lubricated airframe per MM - Inspect and test ELT per FAR 91.207(d) and found to meet requirements, replace battery by 08/2027 See AD note update sheet and master list for complete AD note history thru this date and current revision.... CW Instructions For Continued Airworthiness Per Precise flight oxygen systems. Completed altitude checks with no defects noted.... CW SA21-16 Verification of CAPS Electric Ignition Checkout Procedure at Annual Inspection.... Removed and replaced torn nipple for MCU alt #2 lead with new IAW Cirrus AMM.... Removed surface corrosion on nose gear strut, applied LPS 3 to prevent future corrosion... Replaced LH & RH MLG Beringer brake linings with new IAW Beringer MM & Cirrus AMM.... Replaced LH & RH MLG Beringer wheel clips and screws with new IAW Beringer MM & Cirrus AMM... Adjusted pilot and co-pilot door rigging to spec IAW Cirrus AMM... Adjust 50% flap setting IAW Cirrus AMM.... Replaced ELT remote battery with new IAW Cirrus AMM, Replace battery by 2/2027... Complied with SB2X-32-25. Oleo product number not listed in table to change... Complied with SB2X-32-26 Nose Landing Gear Strut Assembly Inspection... Removed oil line inspected, replaced fire sleeve and re-routed oil line IAW SB2X-71-31R1 Oil Line Replacement... Touched up black paint on upper TKS to wing interface and touched up black paint on nose wheel pant, installed nose pant paint protection... Complied with Beringer SB-019 Brake Backstop replacement EA-003X. EA-004X

I Certify that this AIRCRAFT has been inspected IAW and ANNUAL inspection and was determined to be in AIRWORTHY Condition. All work performed IAW applicable service manuals of the repair are on file at this repair facility under Work Order No Murrig 2/12\$5-12-2021. FAA CRS #2SDR271B.

DATE: 1/21/2022

MAKE: Cirrus MODEL: SR22T

S/N: 0601 REG. NO: N22CW

WORK ORDER: Murrieta11535-06-2022 SIGNED:

37680 Sky Canyon Drive

#602

Murrieta, CA 92563 Phone: 951-698-4260

Gryphon Aircraft Services, LLC.

DATE: 7/18/2022 A/C TSN: 763.7

Work Order: Murrieta11285-12-2021

TACH: 763.7

Airframe Entries

Cleaned and reseated GIA#1 with Stabilant 22. Found bent placement Pin on PFD D-sub & Removed.... Re Soldered A/C compressor power wire.

I Certify that with respect to only the work performed on the above identified Aircraft, Engine, Propeller or Appliance was repaired and inspected in accordance with current FAA regulations and is APPROVED for return to service All work performed IRW applicable service manuals or other approved documentation. Pertinent details of the repair are on file at this repair facility under Work Order No. Murrieta11535-06-2022. FAA CRS #281 R271B.

DATE: 7/18/2022

SIGNED:

Work Order: Murrieta11535-06-2022 LL FDia 2 /datcomodi

DESCRIPTION OF WORK PERFORMED

OR APPROVED DATA USED

AIRCRAFT TIME

IN SERVICE

MAKE: Cirrus G5 MODEL: SR 22T S/N: 0601 REG. NO: N52VS WORK ORDER: 3187-11-2013	Houston Aviation Center, LLC 12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800	DATE: 11/21/2013 A/C TSN: 36.4 FLIGHTTIME: 36.4
Airframe Entries		
Lubricated both LH and RH upp	er and lower latches. Lubricated LH door release button. Ope	rational check satisfactory.
Maintenance Release The aircraft and/or component(and was found Airworthy for ret 3187-11-2013. DATE: 11/21/2013	s) on N52VS was repaired and/or inspected in accordance with surn to service. Pertinent details of the repair are on file at Ho	th current requirements of the Federal Aviation Regulations ouston Aviation Center, LLC under Work Order No. Work Order: 3187-11-2013
	Pustejovsky, N, A&P: 3194257	Printed by EBis 3 (datcomedia.com
a particular de la companya de la c		
Fig. X		

AGENCY & CERTIFICATE NO.

WORK PERFORMED/RETURNED TO SERVI

MAKE: Cirrus G5 MODEL: SR 22T S/N: 2218

REG. NO: N52VS

WORK ORDER: 3228-12-2013

Houston Aviation Center, LLC

12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800

DATE: 1/21/2014 AC TSN: 70.1 FLIGHTTIME: 70.1

Airframe Entries

(Flight Meter: 70.1) Removed standby altimeter P/n 12731-003, S/N 501268 and installed new standby altimeter P/n 12102-002 (5931D-3), S/N 501211. Operational check satisfactory.... Removed graphics and prepared LH & RH wingtips for paint. Painted and clear-coated LH & RH wingtips.... Installed new NLG strut protective covering P/n FAK-009/G3/NS/OLE.... Installed new LH & RH wing tip graphics P/n XICUSTOM-WTLH and P/N XICUSTOM-WTRH and Aerotect wing tip protective cover P/n FAK_009/G3/WT.

Maintenance Release

The aircraft and/or component(s) on N52VS was repaired and/or inspected in accordance with current requirements of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at Houston Aviation Center, LLC under Work Order No. 3228-12-2013.

DATE: 1/21/2014

SIGNED:

Work Order: 3228-12-2013

Printed by EBis 3 (datcomedia.com)

		Martin Aaron N	licely, A&P: 3279896		
	All the second of the second o			A. 7. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.	
+					
\dashv		*			
+					

DRNED TO SERVICE	DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WORK P OR APPROVED DATA		AGENCY & CERTIFICATE NO. WORK PERFORMED/RETURNED TO SE	ERVICE
	CONT		ma.			
				DATE: 10-15-2014.	ENG: TSiO-550K(1B)	
		TIDA	LAVIATION	TAIL #: N52VS.	ENG. S#: 1008884.	
		IIDA		A/C S#: 0601	HOBBS: 202.8 Hrs.	
					FLIGHT: 167.8 Hrs.	
		bearing cup P/N Cleveland M.M. C using Cirrus M.M	ke caliper with new o-rings P/N:101-3:214-00300, & bearing cone P/N:214:0001-7.3, R/R L/H & R/H wing-tip recog. (ATA33-40), R/R wing tip leading edge 3263-004, component functional & ope	a-00400, using Cirrus M nition light lens with P/I protection film with P/I rational checks satisfactor	I.M. (ATA32-41) & Parker N:17385-001 & 17385-002, N:FAK-009/G3/WT, R/R R/H	
3				A	άγ #: 3186/86.	4
1)	MO S/N RE W(330	KE: Cirrus G5 DDEL: SR 22T N: 0601 :G. NO: N52VS DRK ORDER: 62-04-2014 irframe Entries	Houston Aviation Cer 12888 Hwy 6 S Ste 113 Sugar Land, TX 77498 USA Phone: 281-494-5800	nter, LLC	DATE: 7/25/2014 A/C TSN: 177.1 FLIGHTTIME: 147.1	
	lns	stalled new LH armrest P/n	n 29275-004, new RH armrest P/n 29273-004. 8-008, and new RH door panel P/n 20349-008 31796-002 C/W SB 2X-33-06 "Recommende	installed new edge trim P/n 5 C/W SB 2X-71-25 Installated Gasket Installation" by inst	1762-001U to LH and RH door panels. Installed tion of Intercooler Flange Stiffeners using talling new LH and RH gasket PIn 17140-101.	_
		aintenance Release				
	ar 35	he aircraft and/or compone nd was found Airworthy for 362-04-2014. DATE: 7/25/2014	ent(s) on N52VS was repaired and/or inspected return to service. Pertinent details of the repaired SIGNED:	in accordance with current re ir are on file at Houston Aviat	equirements of the Federal Aviation Regulations tion Center, LLC under Work Order No. Work Order: 3362-04-201	4
			Pustejovsky, N, A&P: 3194257		Printed by EBis 3 (datcomedia.com	n)





11/24/2015 Airframe Logbook Entry **Date** W/O# 14862

CRS AWKR298C

AIRCRAFT: N 52VS

S/N: 0601

25170 Aviation Ave., Davis, CA 95616

PERFORMED CONCORDE BATTERY CAPACITANCE CHECK. BATTERY PASSED. FULLY 331.7 Tach RECHARGED BATTERY AND REINSTALLED.

TRIMMED NLG WHEEL PANT TO PREVENT CHAFFING ON NLG STRUT. TORQUED AND SAFETIED NLG ATTACHING HARDWARE TO SPECS. SEALED ENGINE BAFFLING AIR GAPS AT INTER-CYLINDER AND AFT WALL BAFFLING WITH


HIGH-TEMP RTV.

INSTALLED NEW NOSE LANDING GEAR STRUT FAIRING SEAL. INSTALLED NEW UPPER COWLING SEAL.

The Aircraft and/or component identified above was repaired and inspected roturn to service only for the

IAW F	AA regula rk perform	and Pertinen	s found airvit details of the great in the second s	rie repair a	e on file at this	s agency:
			Sha	wn Matthies AWKR	298C	
						4
				* 3		

			.n. 73.9		
DATE OF COMPLETION	AIRCRAFT TIME IN SERVICE	DESCRIPTION OF WO OR APPROVED	ORK PERFORMED DATA USED		
		the second section of the second section of	PAIR USED	W	AGENCY & CERT ORK PERFORMED/RET
	- Aviation C	nacialdi -		the second of th	PEKFORMED/RET
	- Aviation Sp	veciaines			
	300 County Airport R. Vacaville Ca 95688	d Hangar A			
	Work Order: 20160429	N. //		Tel: 707-451-	2860
	Date: 04-29-2016:	TACH: 358.1 N#: 52VS	AF: 358.1	Aircraft: SR22T	
	Airframa. The			Aircraft S#: 0601	
	I certify this aircraft a current manufactures Condition only for the	ft identified above was inspected and referred to service with respect to the work oncord 24V Battery and installed and components have been inspected and guidance and Federal Aviation work performed.	d new Concord 24V	battery supplied By Da	vis Air.
N22CW Removed		Airframe L c fuel pump P/N 5217-00-3, S	og S/N 1943 per Cirrus	Flt T	ime 526.9
Administra	onent listed above was ration and is approved for	epaired or inspected in accord return to service.	dance with current re	egulations of the Fede	28-20. Leak an eral Aviation
Stephen	R Schilling AP333 Aircraft Services	0755LA	25	date 05/14/2	



DESCRIPTION OF WORK PERFORMED

OR APPROVED DATA USED

DATE OF COMPLETION MAKE: Cirrus

IN SERVICE MODEL: SR22T

AIRCRAFT TIME

Gryphon Aircraft Services, LLC.

DATE: 6/29/2021 A/C TSN: 668.3

TACH: 668.3

WO

REG. NO: N22CW WORK ORDER: Murrieta10924-06-2021

S/N: 0601

#602

37680 Sky Canyon Drive

Murrieta, CA 92563 Phone: 951-698-4260

Airframe Entries

Replaced right outboard wheel pant bolt.... Installed stainless steal screws on the stall sensor.... Installed BlueMax Flight Data P/N 4370-2730 S/N 01344, Installed under A EASA minor change approval # 10076563 Performed A functional check with no defects noted. No change in weight and balance.... Updated G1000 software to v0764.38 IAW SB2X-42-19. Installed customer unlocks AFCS, SVS, TAWS, & Charts... Replaced A/C drive shaft with new, Adjusted belt tension to spec. Secured attaching hardware

I Certify that with respect to only the work performed on the above identified Aircraft, Engine, Propeller or Appliance was repaired and inspected in accordance with current FAA regulations and is APPROVED for return to service All work performed IAW applicable service manuals or other approved documentation. Pertinent details of the repair are on file at this repair facility under Work Order No. Murrieta10924-06-2021. FAA CDS #28 DR271B.

DATE: 6/29/2021

Work Order: Murrieta10924-06-2021 SIGNED:

MAKE: Cirrus MODEL: SR22T S/N: 0601 REG. NO: N22CW WORK ORDER: Murrieta11100-09-2021



#602

Gryphon Aircraft Services, LLC.

37680 Sky Canyon Drive Murrieta, CA 92563 Phone: 951-698-4260

A/C TSN: 725.8 TACH: 725.8

DATE: 9/16/2021

Avionics Entries

Performed Pitot-Static and Transponder certs (FAR 91.411 & 91.413) IAW FAR 43 appendix E & F. Tested static system up to 25K feet.

ALTIMETER AND STATIC SYSTEMS REQUIRED BY F.A.R. 91.411. F.A.R. Part 43 Appendix E: PERFORMED ON THIS AIRCRAFT. **DATE 9/16/2021** FEET CERTIFIED TO: TYPE ADCALLENC POSITION 3m2 10/47 S/N 42024 12 REG# N22CW CERT ONLY: SIGNED:

THE TRANSPONDER AND ALTITUDE REPORTING SYSTEM IN THIS AIRCRAFT WERE TESTED AND INSPECTED AS REQUIRED IN F.A.R. 91.413 F.A.R. 43 APPENDIX F. W/O# Murrieta11100-09-2024

MANUFE TYSXY MODEL CHANGE for &SDR271B Date: 9/16/2021 INSPECTOR

DATE: 9/16/2021

SIGNED:

Work Order: Murrieta11100-09-2021

Printed by FRis 3 (datcomedia.com)

MAKE: Cirrus MODEL: SR22T S/N: 0601 REG. NO: N22CW WORK ORDER: Murrieta11407-03-2022



Gryphon Aircraft Services, LLC.

37680 Sky Canyon Drive Murrieta, CA 92563 Phone: 951-698-4260

DATE: 3/22/2022 A/C TSN: 753.8 TACH: 753.8

MEI URNED TO C

Airframe Entries

Removed CHT #4 & replaced with new probe PN# 24584-001... Cleaned and Checked LH & RH TIT probes, Performed Arun up, Checked RH magneto timing, No adjustment needed at this time. IAW Cirrus AMM>... ReInstalled pilot cup holder IAW Cirrus AMM... Performed TKS flow checks with no defects noted.

I Certify that with respect to only the work performed on the above identified Aircraft, Engine, Propeller or Appliance was repaired and inspected in accordance with current FAA/regulations and is APPROVED for return to service. All work performed IAW applicable service manuals or other approved documentation. Pertinent details of the repair are on file at this repair facility under Work Order No. Murrieta11407-03-2022. FAA CKS #26DR

	N22CW	AIRFRAME LOG BOOK ENTRY				8/11/2022	
_	Cirrus	SR22 T	S/N 0601	Flight	780.9	Hobbs	991.1
AVIATION RESOURCES	Continental	TSIO 550K1	S/N 1008884	Flight	780.9	Hobbs	991.1
101 Airport Ave, Hangar7 Cumberland, WI 54829	Hartzell	PHC-J3Y1F-1N	S/N NJ791B	Flight	780.9	Hobbs	991.1

Removed all wheel pants and wheels. Performed conformity inspection IAW Beringer SensAIR Service Bulletin SB-023. Installed Beringer SensAIR P/N TP-005 and TP-006 IAW installation manual MM-08-001 and ICA per STC SA003372NY. Added portion of STC SA03372NY for SensAIR System only. See FAA Form 337 dated 8/11/2022. Installed wheels. Nose sensor ID 03991, Left 03B0D, Right 03C90; application password BG-SA-020. Replaced left fuel tank vent panel inboard forward nut plate with new #8 put plate. (Refer to Job #22CW3 for details.) THIS AIRCRAFT ENGINE/PROPELLER COMBINATION WAS INSPECTED AND/OR WAS REPAIRED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FAX, AND IS APPROVED FOR RETURN TO SERVICE.

JIM BARKER A&P/IA 2755069 Cell (715) 491-1303

Email jim@aviationvibes.com

WISTRA

2755069

AVIATION RESOURCES, LLC Hangar (715) 822-5787 www.aviationvibes.com

DESCRIPTION OF WORK PERFORMED

OR APPROVED DATA USED

MAKE: Cirrus MODEL: SR22T S/N: 0601 REG. NO: N22CW

DATE OF

COMPLETION

AIRCRAFT TIME

IN SERVICE



Gryphon Aircraft Services, LLC. 37920 Sky Canyon drive **Suite 1001**

Murrieta, CA 92563 Phone: 951-698-4260

Airframe Entries

Murrieta11768-10-2022

WORK ORDER:

Removed Ballast PN:LSM-SCD-019-5 Rev J SN:63391 Installed new ballast PN:LSM-SCD-019-5 SN:069388 See 8130 #: CR20221026-2... Cleaned all GIA #2 & GRS 77 #1 connectors and applied Stabilant 22 IRW Cirrus AMM.

I Cortify that with respect to only the work performed on the above identified Aircraft, Engine. Propeller or Appliance was


AGENC

WORK PERFOR

DATE: 10/27/2022

A/C TSN: 843.5

TACH: 843.5



TIDAL AVIATION

DATE: 10-16-2014. **TAIL #: N52VS.**

A/C S#: 0601.

ENG: TSiO-550K(1B). ENG. S#: 1008884.

DATE

HOBBS: 202.8 Hrs. FLIGHT: 167.8 Hrs.

Performed an Airframe 100 hrs/annual Inspection using Cirrus M.M. & F.A.R. Part 43, Appendix D as reference for scope of Inspection, serviced L/H, R/H M.L.G. & N.G. tire pressures using Cirrus M.M. (ATA12-10-D), lubricated airframe & components using Cirrus M.M. (12-20) all applicable service bulletins & airworthiness directives are in compliance at the time of

inspection, airframe & components operational checks satisfactory for return to service, I certified that this Aircraft has been inspected in accordance with an Annual Inspection, and was found to be in Airworthy condition on this date.

LEONARD F, FIRTH.

A&P #:1943822 I.A.