

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-C34R-1F/F7693F(B)

PROPELLER S/N A 8554B

LOGBOOK # 2

MAINTENANCE RELEASE

Part No: F210761 Description: WOODWARD GOVERNOR Serial No: 2247748F

was REPAIRED (describe) _____

OVERHAULED per the following documents (include revision levels):

Manuals 33201

Service Bulletins THRU 33594

Service Letters N/A

Service Instructions N/A

Service Advisories N/A

The following Airworthiness Directives have been complied with:

A.D.	Method of Compliance:	Rekurs at: Date or Hours
<u>N/A</u>		

equipment is
th and become a

Time Since New: Brought forward Time Since Overhaul/Major: -0-

The item(s) identified above were repaired or overhauled (as indicated) and inspected in accordance with current FAA regulations and are approved for return to service. Pertinent details of this repair or overhaul are on file at

this repair station under work order # L17015

Date February 1, 2007 Signed *Walter B. Witt*

For Repair Station #QV9R194N
SENENICH PROPELLER SERVICE, INC.

519 East Airport Road, Lititz, PA 17543

Prrnellr

A/C

Description of all operations pertaining to Airworthiness Directives, Missions, and Inspections.

PROP MODEL: HC-C3YR-1F/F7693F(B)
PROP S/N: A8554B
REG. NO: N2804W
WORK ORDER: 1469

Dulles Aviation, Inc.
Repair Station No. IBIR931E
10501 Observation Road
Manassas, Virginia 20110
Phone: 703-361-2171

DATE: 5/4/2007
A/C TSN: 1835.1
PROP TT: 0
HOBBS: 1835.1

Prop Entries

(3) Removed propeller assy. HC-C2YK-1BF, S/N CH 32382A. Installed new Propeller assy. HC-C3YR-1F/F7693F(B), S/N A8554B, with new slinger ring P/N C-2294-16P, S/N JY-0211 per STC SA01192CH installation instructions. POH supplement inserted. Weight and Balance revised. Reinstalled prop governor P/N F210761, S/N 2247748F after overhaul by Sensenich Propeller Service.

Maintenance Release

The aircraft and/or component(s) on N2804W was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 1469

DATE: 5/4/2007

SIGNED

Charles Edward Schoenduby
Certified Repair Station No. IBIR931E

Work Order: 1469

Printed by EBis 3 (datcomedia.com)

PROP MODEL: HC-C3YR-1F/F7693F(B)
PROP S/N: A8554B
REG. NO: N2804W
WORK ORDER: 1922



Dulles Aviation, Inc.
Repair Station No. IBIR931E
10501 Observation Road
Manassas, Virginia 20110
Phone: 703-361-2171

DATE: 12/12/2007
A/C TSN: 1921
PROP TT: 85.9
HOBBS: 1921

Prop Entries

(3) Performed 130 hr. Propeller inspection per FAR 43, appendix D. Applicable AD's have been checked and complied with thru 2007-24

Maintenance Release

The aircraft and/or component(s) on N2804W was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 1922

DATE: 12/12/2007

SIGNED

Charles Edward Schoenduby
Certified Repair Station No. IBIR931E

Work Order: 1922

Printed by EBis 3 (datcomedia.com)

PROP MODEL: HC-C3YR-1F/F7693F(B)
PROP S/N: A8554B
REG. NO: N2804W
WORK ORDER: 2774



Dulles Aviation, Inc.
Repair Station No. IBIR931E
10501 Observation Road
Manassas, Virginia 20110
Phone: 703-361-2171

DATE: 3/9/2009
A/C TSN: 2774
PROP TT: 115.3
HOBBS: 2774

Prop Entries

(3) Performed 130 hr. Propeller inspection per FAR 43, appendix D. Applicable AD's have been checked and complied with thru 2009-14

Maintenance Release

The aircraft and/or component(s) on N2804W was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 2774

DATE: 3/9/2009

SIGNED

Charles Edward Schoenduby
Certified Repair Station No. IBIR931E

Work Order: 2774

Printed by EBis 3 (datcomedia.com)

PROP MODEL: HC-C3YR-1F/F7693F(B)
PROP S/N: A8554B
REG. NO: N2804W
WORK ORDER: 3426



Dulles Aviation, Inc.
Repair Station No. IBIR931E
10501 Observation Road
Manassas, Virginia 20110
Phone: 703-361-2171

DATE: 3/18/2010
A/C TSN: 3426
PROP TT: 124.1
HOBBS: 3426

Prop Entries

(3) Performed 130 hr. Propeller inspection per FAR 43, appendix D. Applicable AD's have been checked and complied with thru 2010-14

Work Order: 3426
The aircraft and/or component(s) on N2804W was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 3426

DATE: 3/18/2010

SIGNED

Charles Edward Schoenduby
Certified Repair Station No. IBIR931E

Work Order: 3426

Printed by EBis 3 (datcomedia.com)