AD NOTES COMPLIANCE RECORD

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
83-13-01	Placard - fuel cap sealing		N/A by S/N	X			Craig Easter 3555683
83-17-06	Aileron balance weights		N/A by S/N	X			Craig Easter 3555683
83-22-06	Aileron hinge pin	4-9-84	pcw	X			Craig Easter 3555683
84-10-01 R1	Bladder fuel cells		N/A - not installed	X			Craig Easter 3555683
86-24-07	Engine controls installation		N/A by S/N	X			Craig Easter 3555683
87-20-03 R2	Seat tracks		Superceded	X			Craig Easter 3555683
97-01-13	Fuel, oil, or hydraulic hose	6/7/97	pcw	X			Craig Easter 3555683
98-16-04	Angle stiffener		N/A - not installed	X			Craig Easter 3555683
2000-06-01	Prevent foreign material from entering the fuel system	4/4/20	pcw	X			Craig Easter 3555683
2004-19-01	CORRECTION - Prevent slippage of the pilot/co-pilot shoulder harness		N/A by model	X			Craig Easter 3555683
2008-10-02	To prevent erroneous indications from the altimeter, airspeed, and vertical speed indicators	7/18/09	pcw	X			Craig Easter 3555683
2008-26-10	Correction - Prevent erroneous indications from the altimeter, airspeed, and vertical speed indicators	7/18/09	pcw		X	Replacment	Craig Easter 3555683
2011-10-09	To prevent seat slippage or the seat roller housing from departing from the seat rail	4/23/24 TT 6841..9	Inspect tracks and rollers		X	100hr annual	Craig Easter 3555683
2020-18-01	Forward Cabin Doorpost Bulkhead Cracking	4/23/24 TT 6841..9	Inspect for cracks and none found		X	36 month 1000 hr	Craig Easter 3555683
59-10-07	Cylinder baffle clamps		N/A	X			Craig Easter 3555683
63-14-03	Oil pump drive shaft		N/A	X			Craig Easter 3555683
64-16-05	Oil seal failure		N/A	X			Craig Easter 3555683
66-20-04	Oil filter adaptor gasket		N/A	X			Craig Easter 3555683
73-23-01	Piston pin failures		N/A	X			Craig Easter 3555683
75-08-09	Oil pump		N/A	X			Craig Easter 3555683
81-18-04 R2	Oil pump		superceded	X			Craig Easter 3555683

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
87-10-06 R1	Rocker arm assemblies		N/A	X			Craig Easter 3555683
91-14-22	Crankshaft gear retaining bolt		Superceded	X			Craig Easter 3555683
93-05-21	AC, Textron, Rajay fuel pumps		superceded	X			Craig Easter 3555683
93-11-11	AC, Textron, Rajay fuel pumps		N/A	X			Craig Easter 3555683
94-14-13	Low octane detonation		superceded	X			Craig Easter 3555683
95-07-01	Connecting rod bolts		N/A	X			Craig Easter 3555683
95-26-02	Low octane detonation		NA by N#	X			Craig Easter 3555683
96-09-10	Oil Pumps		N/A	X			Craig Easter 3555683
PL2000-18-53	Loss of engine oil and subsequent seizing of the engine and possible fire		Superceded	X			Craig Easter 3555683
2002-12-07	Prevent complete loss of engine oil	12/1/20	si1456	X			Craig Easter 3555683
PL2002-20-51	Prevent loss of all engine power and possible forced landing		superceded	X			Craig Easter 3555683
2002-23-06	CORRECTION - Prevent loss of all engine power and possible forced landing		superceded	X			Craig Easter 3555683
2004-05-24	Prevent loss of all engine power and possible forced landing	4/28/04	pcw Par c 4	X			Craig Easter 3555683
2004-10-14	CORRECTION - Prevent loosening or failure of the crankshaft gear retaining bolt		not due at this time		X	strike overhaul	Craig Easter 3555683
2005-19-11	Prevent failure of the crankshaft		NA not in affected period	X			Craig Easter 3555683
2005-26-10	To prevent loss of engine power due to cracks in the cylinder assemblies		Superceded	X			Craig Easter 3555683
2006-12-07	To prevent loss of engine power due to cracks in the cylinder assemblies		N/A - not installed	X			Craig Easter 3555683
2006-20-09	To prevent failure of the crankshaft		superceded	X			Craig Easter 3555683
2008-19-05	To prevent loss of engine power due to cracks at the head-to-barrel interface in the cylinder assemblies and possible engine failure caused by separation of a cylinder head		Superceded	X			Craig Easter 3555683
2009-26-12	To prevent loss of engine power due to cracks at the head-to-barrel interface and possible engine failure caused by separation of a cylinder head		na ECI not installed	X			Craig Easter 3555683

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
2012-03-07	To address a "machined-from-billet" HA-6 carburetor having a loose mixture control sleeve that rotated in the carburetor body		N/A - not installed	X			Craig Easter 3555683
2012-19-01	To prevent failure of the crankshaft		N/A by S/N	X			Craig Easter 3555683
2015-02-07	Propeller Governor Idler Shaft Set Screw		Replaced at overhaul		X	Overhaul	Craig Easter 3555683
2017-16-11	Engine Connecting Rod Assemblies Integrity		Not installed	X			Craig Easter 3555683
77-12-06 R2	Prop blade	4/2/21 TT 6813.2	N/A prop overhauled	X			Craig Easter 3555683
89-22-05	Propeller hub failure	4/2/21 TT 6813.2	Prop overhauled	X			Craig Easter 3555683
93-16-14	Prop hub cracks		superceded	X			Craig Easter 3555683
94-17-13	Prop hub failure	4/2/21 TT 6813.2	na prop overhauled	X			Craig Easter 3555683
2001-07-03	CORRECTION - Prevent propeller failure of the propellers returned to service by BASCO	4/2/21 TT 6813.2	Na prop overhauled	X			Craig Easter 3555683
2002-09-08	Prevent failure of the propeller blade from fatigue cracks		superceded	X			Craig Easter 3555683
2003-13-17	Maintenance by T&W Propellers Inc.		N a no work by T&W	X			Craig Easter 3555683
2005-14-11	Maintenance by Southern California Propeller Service		Na no work by CPS	X			Craig Easter 3555683
2006-24-07	To detect unsafe conditions that could result in a propeller blade separating from the hub and loss of control of the airplane	4/2/21 TT 6813.2	NA prop overhauled	X			Craig Easter 3555683
2007-26-09	To prevent failure of the propeller blade from fatigue cracks in the blade shank radius	4/2/21 TT 6813.2	NA prop overhauled	X			Craig Easter 3555683
2008-13-28	To prevent failure of the propeller hub	4/2/21 TT 6813.2	N/A prop overhauled	X			Craig Easter 3555683