Piper PA-32-300

Airworthiness Directives Compliance Report

Date: 6/23/2026	**Tail #:** N3011K	
Airframe: Piper PA-32-300	**S/N:** 32-7940023	**Hours:**
Engine: Lycoming IO-540-K1G5	**S/N:** L-2810-48A	**Hours:** TTE: Tach + 2244.8 TSMOH: Tach + 244.8
Propeller: Hartzell HC-C2Y Series	**S/N:** NS576B	**Hours:** TSMOH: Tach + 1054.9

Airframe: Piper PA-32-300

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
67-16-02 Airframe	Superseded By 67-26-03		Superseded By 67-26-03				Jeffrey Holstein AP3180354IA
67-20-04 09/27/67 Airframe	Main Landing Gear Link		N/A by date of manufacture				Jeffrey Holstein AP3180354IA
67-26-02 05/22/68 Airframe	Fuel Selector Valve		N/A by date of manufacture				Jeffrey Holstein AP3180354IA
67-26-03 04/12/68 Airframe	Fuel System Screens and Filters		N/A by S/N				Jeffrey Holstein AP3180354IA
67-30-06 12/22/67 Airframe	Engine Air Induction System		N/A by S/N				Jeffrey Holstein AP3180354IA
69-15-01 07/21/69 Airframe	Control Wheel Retaining Pin		N/A by S/N				Jeffrey Holstein AP3180354IA
69-22-02 07/30/79 Airframe	Failure of Control Wheel		N/A by S/N				Jeffrey Holstein AP3180354IA
70-18-05 09/07/70 Airframe	Landing Gear Link Bolts		N/A by S/N				Jeffrey Holstein AP3180354IA
70-26-04 06/24/71 Airframe	Stabilizer Balance Weight Tube		N/A by S/N				Jeffrey Holstein AP3180354IA
71-09-05 04/30/71 Airframe	Front Seat Belt Attaching Hardware		N/A by S/N				Jeffrey Holstein AP3180354IA
72-04-03 Airframe	Superseded By 76-25-06		Superseded By 76-25-06				Jeffrey Holstein AP3180354IA
72-08-06 04/14/72 Airframe	Landing Gear Torque Links		N/A - New style torque links installed				Jeffrey Holstein AP3180354IA
72-14-07 07/07/72 Airframe	Stabilator Hinge Attachment Fittings		N/A by S/N				Jeffrey Holstein AP3180354IA
72-17-05 08/15/72 Airframe	Electric Trim Switch		N/A by S/N				Jeffrey Holstein AP3180354IA
74-09-02 04/18/74 Airframe	Stall Warning Light		N/A by S/N				Jeffrey Holstein AP3180354IA
74-18-13 09/03/74 Airframe	Nose Gear Vibration		N/A by S/N				CAM Staff None
74-19-01 09/07/74 Airframe	Outer Wing Spar Lightening Hole		N/A by S/N				CAM Staff None
75-02-03 11/26/74 Airframe	Nose Wheel Fork Assembly		N/A - STC not installed				Jeffrey Holstein AP3180354IA
75-10-03 05/12/75 Airframe	Forward Baggage Door Delamination		N/A by S/N				Jeffrey Holstein AP3180354IA
75-24-02 11/21/75 Airframe	Quick-Disconnect Seats Rear Legs Inspection		N/A by S/N				Jeffrey Holstein AP3180354IA
76-18-04 09/10/76 Airframe	Fuel Valve Leakage		N/A by S/N				Jeffrey Holstein AP3180354IA
76-25-06 Airframe	Superseded By 95-26-13		Superseded By 95-26-13				Jeffrey Holstein AP3180354IA
77-01-01 01/07/77 Airframe	Erroneous Fuel Quantity Gauge		N/A by S/N				Jeffrey Holstein AP3180354IA

Scanned with CamScanner

77-12-01 06/10/77 Airframe	Fuel System Malfunction		N/A by S/N				Jeffrey Holstein AP3180354IA
77-23-03 11/14/77 Airframe	Engine Control Rod End Bearings		N/A by S/N				Jeffrey Holstein AP3180354IA
78-23-01 11/03/78 Airframe	Fuel Drain Lever Cover Door	12/15/2025; ACTT:6981.4	complied wit AD per AD para. (a)1.2,3, inspection and functional check of fuel drain		Yes	ACTT: 7081.4	Jeffrey Holstein AP3180354IA
80-14-01 07/10/80 Airframe	Fuel Tank Vent Modification	6/27/1980; Tach 578.0	PCW				Jeffrey Holstein AP3180354IA
80-14-02 07/10/80 Airframe	Throttle Control Cable Rod End		N/A by S/N				Jeffrey Holstein AP3180354IA
80-14-03 07/01/80 Airframe	Radio Muting Relay Plug		N/A - By radios installed				Jeffrey Holstein AP3180354IA
80-24-03 Airframe	Superseded By 86-17-01		Superseded By 86-17-01				Jeffrey Holstein AP3180354IA
86-17-01 08/21/86 Airframe	Ammeter Replacement	9/14/2012 Tach 244.1	PCW - OH ammeter gauge installed				Jeffrey Holstein AP3180354IA
87-08-08 R1 Airframe	Per FAA Rescinded in 1989, Service Documentation still applicable		Rescinded				Jeffrey Holstein AP3180354IA
87-08-08 R3 05/22/89 Airframe	Rescission of 87-08-08 and Subsequent Revisions		Rescinded				Jeffrey Holstein AP3180354IA
95-26-13 Airframe	Superseded By 17-14-04		Superseded By 17-14-04				Jeffrey Holstein AP3180354IA
96-10-03 06/14/96 Airframe	Flap Handle Bolt	10/13/2014; Tach 333.1	PCW Per Para b-d, new devis bolt and bushing				Jeffrey Holstein AP3180354IA
99-05-09 03/19/99 Airframe	Induction Air Filter		N/A - not installed				Jeffrey Holstein AP3180354IA
2010-15-10 08/31/10 Airframe	Control Wheel Shafts	4/14/2011; ACTT 5241.9	PCW - By visual inspection				Jeffrey Holstein AP3180354IA
2013-02-13 03/11/13 Airframe	Stabilator Control System	2/15/23; Tach 1285.8	PCW - Stabilator control cables and turnbuckles removed and replaced with new		Yes	2/28/2030 or Tach 3285.8	Jeffrey Holstein AP3180354IA
2017-14-04 08/15/17 Airframe	Oil Cooler Hose Assemblies	9/1/2017; Tach 1142.7	PCW TSO-C53a Type "D" hoses installed				Jeffrey Holstein AP3180354IA
2020-24-05 12/28/20 Airframe	Main Wing Spar Corrosion		N/A by S/N				Jeffrey Holstein AP3180354IA
2020-26-16 02/16/21 Airframe	Wing Separation by Main Spar Cap Fatigue Cracking	11/22/2021; Tach 1142.7, ACTT 6227.9	Wing spar integrity calculated with AD formula in 2021 to be 1308 Factored Hours. Calculations for 5/13/2024 = 1432 Factored Hours.		Yes	5000 Factored Hours	Jeffrey Holstein AP3180354IA

Engine: Lycoming IO-540-K1G5

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
63-14-03 07/06/63 Engine	Oil Pump Drive Shaft		N/A by S/N				Jeffrey Holstein AP3180354IA
66-20-04 08/27/66 Engine	Oil Filter Adapter Gasket		N/A by date of manufacture				Jeffrey Holstein AP3180354IA
75-08-09 08/18/77 Engine	Oil Pump Drive Shaft and Impeller	7/1/2005	PCW AT OVH Installed gears 18109 & 18110				Jeffrey Holstein AP3180354IA
75-09-15 04/30/75 Engine	Bendix Fuel Injector Flow Divider Cover Gasket	7/1/2000	N/A by OH date				Jeffrey Holstein AP3180354IA
78-23-10 11/07/78 Engine	Bendix RSA Series Fuel Injector Bellows Seal		N/A - Affected injector not installed				Jeffrey Holstein AP3180354IA
79-04-05 09/26/79 Engine	Bendix RSA Series Fuel Injectors Diaphragm		N/A - Affected injector not installed				Jeffrey Holstein AP3180354IA
81-18-04 R2 Engine	Superseded By 96-09-10		Superseded By 96-09-10				Jeffrey Holstein AP3180354IA

Scanned with CamScanner

83-22-04 11/04/83 Engine	Bendix Fuel Injector Fuel Diaphragm Stem		N/A - Affected diaphragm stem not installed				Jeffrey Holstein AP3180354IA
91-14-22 Engine	Superseded By 04-10-14		Superseded By 04-10-14				Jeffrey Holstein AP3180354IA
92-12-05 07/10/92 Engine	Piston Pin Failure	7/1/2005	N/A by OH date				Jeffrey Holstein AP3180354IA
92-20-07 Engine	Superseded By 93-05-21		Superseded By 93-05-21				Jeffrey Holstein AP3180354IA
93-02-05 Engine	Superseded By 02-26-01		Superseded By 02-26-01				Jeffrey Holstein AP3180354IA
93-05-21 Engine	Superseded By 93-11-11		Superseded By 93-11-11				Jeffrey Holstein AP3180354IA
93-05-22 Engine	Superseded By 02-26-01		Superseded By 02-26-01				Jeffrey Holstein AP3180354IA
93-11-11 06/21/93 Engine	Diaphragm Fuel Pumps Overhauled (by AAI) - Remove Affected Pump and Replace		N/A - Affected pump not installed not installed				Jeffrey Holstein AP3180354IA
94-14-13 Engine	Superseded By 95-26-02		Superseded By 95-26-02				Jeffrey Holstein AP3180354IA
95-07-01 04/12/95 Engine	Superior Air Parts Connecting Rod Bolts		N/A - Affected Rod Bolt not installed not installed				Jeffrey Holstein AP3180354IA
95-26-02 01/24/96 Engine	Detonation Due To Low Octane		N/A by N number				Jeffrey Holstein AP3180354IA
96-09-10 07/15/96 Engine	Oil Pump Impeller Failure	7/01/2005	PCW AT OVH Installed gears 18109 & 18110				Jeffrey Holstein AP3180354IA
96-23-03 12/17/96 Engine	High Pressure Fuel Pumps		N/A - Affected fuel pump not installed not installed				Jeffrey Holstein AP3180354IA
97-01-03 Engine	Superseded By 97-15-11		Superseded By 97-15-11				Jeffrey Holstein AP3180354IA
97-15-11 08/12/97 Engine	Piston Pin Failure		N/A - Affected Piston Pins not installed				Jeffrey Holstein AP3180354IA
98-17-11 10/19/98 Engine	Crankshafts Installed by Nelson Balancing Service		N/A - Affected Crankshaft not installed				Jeffrey Holstein AP3180354IA
98-18-12 Engine	Superseded By 03-14-03		Superseded By 03-14-03				Jeffrey Holstein AP3180354IA
99-04-04 02/25/99 Engine	Magneto magneto Model numbers 6251, 6252, 6255, 6351 and 6355 - Magneto Impulse Coupling	11/142/2024; Tach 1763.0	PCW - 500-hour inspection		Yes	Tach 2013.0	Jeffrey Holstein AP3180354IA
2002-04-51 Engine	Superseded By 02-17-53		Superseded By 02-17-53				Jeffrey Holstein AP3180354IA
2002-17-53 Engine	Superseded By 02-19-03		Superseded By 02-19-03				Jeffrey Holstein AP3180354IA
2002-19-03 09/20/02 Engine	Crankshaft Failure		N/A - Affected Crankshaft not installed				Jeffrey Holstein AP3180354IA
2002-20-51 Engine	Superseded By 02-23-06		Superseded By 02-23-06				Jeffrey Holstein AP3180354IA
2002-23-06 Engine	Superseded By 04-05-24		Superseded By 04-05-24				Jeffrey Holstein AP3180354IA
2002-26-01 Engine	Superseded By 08-14-07		Superseded By 08-14-07				Jeffrey Holstein AP3180354IA
2003-14-03 08/14/03 Engine	Rotary Fuel Pump Leaks		N/A - Affected fuel pump not installed				Jeffrey Holstein AP3180354IA
2004-05-24 03/30/04 Engine	Crankshaft Gear Retaining Bolts		N/A - Affected Crank Gear Bolt not installed				Jeffrey Holstein AP3180354IA
2004-10-14 06/25/04 Engine	Crankshaft Gear Retaining Bolt		Due at prop strike or overhaul. no action at this time		Yes		Jeffrey Holstein AP3180354IA
2005-19-11 10/21/05 Engine	Crankshaft Failures		N/A by S/N				Jeffrey Holstein AP3180354IA
2006-20-09 Engine	Superseded By 12-19-01		Superseded By 12-19-01				Jeffrey Holstein AP3180354IA
2008-08-14 Engine	Superseded By 09-02-03		Superseded By 09-02-03				Jeffrey Holstein AP3180354IA
2008-14-07 Engine	Superseded By 11-26-04		Superseded By 11-26-04				Jeffrey Holstein AP3180354IA
2009-02-03 02/09/09 Engine	RSA-5 or RSA-10 Series - Fuel Injection Servo Plug Gasket		N/A - Gasket not installed after effective date				Jeffrey Holstein AP3180354IA

Scanned with CamScanner

2011-15-10 Engine	Superseded By 12-03-06		Superseded By 12-03-06				Jeffrey Holstein AP3180354IA
2011-26-04 Engine	Superseded By 15-19-07		Superseded By 15-19-07				Jeffrey Holstein AP3180354IA
2012-03-06 02/24/12 Engine	AVStar Fuel Servo Diaphragm		N/A by P/N				Jeffrey Holstein AP3180354IA
2012-19-01 10/24/12 Engine	Crankshaft Replacement		N/A by S/N				Jeffrey Holstein AP3180354IA
2015-19-07 11/03/15 Engine	Fuel Injector Fuel Lines and Clamps	12/11/2025; 1878.2	CW - by inspection		Yes	Tach 1988.2	Jeffrey Holstein AP3180354IA
2017-16-11 08/15/17 Engine	Connecting Rod Failure		N/A by Date				Jeffrey Holstein AP3180354IA
2022-16-03 08/15/22 Engine	S-1200 Series Magneto Roller Bearings		N/A by Model				Jeffrey Holstein AP3180354IA
2024-21-02 12/05/24 Engine	Connecting Rod Failure		Affected parts not installed per sudden stop inspection parts list		Yes* (Terminating Action)	Sudden Engine Stop	Jeffrey Holstein AP3180354IA
2026-04-11 04/08/26 Engine	Connecting Rod Failure		NA by overhaul date Affected parts not installed.		Yes* (Terminating Action)		Jeffrey Holstein AP3180354IA

Propeller: Hartzell HC-C2Y Series

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
64-20-01 08/28/64 Propeller	Pitch Change Blocks		N/A by Model				Jeffrey Holstein AP3180354IA
70-02-01 Propeller	Superseded By 73-10-03		Superseded By 73-10-03				Jeffrey Holstein AP3180354IA
70-16-03 Propeller	Superseded By 77-12-06 R2		Superseded By 77-12-06 R2				Jeffrey Holstein AP3180354IA
73-10-03 Propeller	Superseded By 77-12-06		Superseded By 77-12-06				Jeffrey Holstein AP3180354IA
74-15-02 Propeller	Superseded By 77-12-06		Superseded By 77-12-06				Jeffrey Holstein AP3180354IA
75-07-05 Propeller	Superseded By 77-12-06		Superseded By 77-12-06				Jeffrey Holstein AP3180354IA
77-12-06 R2 Propeller	Superseded By 2002-09-08		Superseded By 2002-09-08				Jeffrey Holstein AP3180354IA
90-02-23 Propeller	Superseded By 01-23-08		Superseded By 01-23-08				Jeffrey Holstein AP3180354IA
2001-07-03 06/04/01 Propeller	BASCO Serviced Propellers		N/A - Not serviced by vendor				Jeffrey Holstein AP3180354IA
2001-23-08 12/24/01 Propeller	Hub Fillet Radius Crack Inspection	9/5/2012; 244.1 Tach	PCW - Terminating action (e) New Hub S/N NS576B installed				Jeffrey Holstein AP3180354IA
2002-09-08 Propeller	Superseded By 2007-26-09		Superseded By 2007-26-09				Jeffrey Holstein AP3180354IA
2003-01-03 01/23/03 Propeller	Propeller Assembly Removal		N/A by Hub S/N				Jeffrey Holstein AP3180354IA
2003-03-20 03/11/03 Propeller	Hartzell Propeller Hub and Blades		N/A by Model				Jeffrey Holstein AP3180354IA
2003-06-02 04/29/03 Propeller	TKS Anti-Ice Boots		N/A - Anti-ice boots not installed				Jeffrey Holstein AP3180354IA
2003-13-17 07/18/03 Propeller	T and W Serviced Propellers		N/A - Not serviced by vendor				Jeffrey Holstein AP3180354IA
2005-14-11 08/17/05 Propeller	Southern California Propeller Serviced Propellers		N/A - Not serviced by vendor				Jeffrey Holstein AP3180354IA
2006-18-15 Propeller	Superseded By 09-22-03		Superseded By 09-22-03				Jeffrey Holstein AP3180354IA
2006-24-07 01/03/07 Propeller	Oxford Aviation/CSE Aviation Serviced Propellers		N/A - Not serviced by vendor				Jeffrey Holstein AP3180354IA
2007-26-09 01/30/08 Propeller	Fatigue Cracks		N/A - S/N D63861 & D63895 Blades installed				Jeffrey Holstein AP3180354IA

Scanned with CamScanner

2008-13-28 07/17/08 Propeller	Hub Blade Socket Lubrication Hole Cracks		N/A - Not left-hand rotating				Jeffrey Holstein AP3180354IA
2009-22-03 11/12/09 Propeller	Propeller Hub Crack Inspection	9/5/2012	N/A New hub installed at OH				Jeffrey Holstein AP3180354IA

Appliance: Avionics Altimeters

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
74-24-13 12/05/74 Appliance	United P/N 5932 ( ), 5934,( ) - Deprived of Altimeter Readings		N/A by S/N				Jeffrey Holstein AP3180354IA

Appliance: Avionics Auto Pilots

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
2024-14-03 08/20/24 Appliance	GFC 500 - Autopilot Pitch Trim System	11/14/2024; Tach 1763.0	PCW - by software update				Jeffrey Holstein AP3180354IA

Appliance: Avionics Transponders

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
2005-01-19 02/23/05 Appliance	GTX 33, GTX 33D, GTX 330, and GTX 330D Mode S - Software Upgrade		N/A by Model				Jeffrey Holstein AP3180354IA

Appliance: Power Plant Filters, Air

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
84-26-02 01/29/85 Appliance	All Paper Induction Air Filters - Engine Ingestion of Fragments	12/15/2025; ACTT:6981.4	Replaced induction air filter with new		Yes	ACTT: 7081.4	Jeffrey Holstein AP3180354IA

Appliance: Power Plant Ignition - Switches

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
76-07-12 08/30/77 Appliance	10-357XXX, 10-126XXX, 10-157XXX - Switch Repair or Replacement		N/A by manufacture date				Jeffrey Holstein AP3180354IA

Scanned with CamScanner