OWNER: COLEMAN JET SOLUTIONS, LLC
ADDRESS: 559 ROGER WILLIAMS AVE, #2
HIGHLAND PARK IL 60035
OFFICE: 847-748-8333
FAX:

OPERATOR: COLEMAN JET SOLUTIONS, LLC
ADDRESS: 559 ROGER WILLIAMS AVE, #2
HIGHLAND PARK IL 60035
OFFICE: 847-748-8333
FAX:

ANALYST: SHAWN SCROGGINS
EMAIL: SSCROGGINS@CAMPSYSTEMS.COM
316-462-2452 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM
800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).

FILTER CRITERIA : Group by ATA Chapter:YES; Profile Filter:AIRFRAME , ENGINE NO. 1, ENGINE NO. 2; Mode:WITH COMPLIANCE OR NEXT DUE; Group by Profile or Bulletin:PROFILE TYPE;

AIRCRAFT

SERIAL/REGNO: FL-922/N130BD MODEL: SUPER KING AIR B300 (350ER) MANUFACTURER: TEXTRON AVIATION INC.

CERTIFICATION DATE: 15-MAY-2014

LAST ACTUALS:
1208.1 A/C HRS as of 02-SEP-2026
550 AFL as of 02-SEP-2026

ENGINE NO. 1

SERIAL/PART: PCE-PK1818/3102700-01 MODEL: PT6A-60A MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 15-MAY-2014
0 ENG. HRS 0 A/C HRS
0 ENC

LAST ACTUALS:
1208.1 ENG. HRS as of 02-SEP-2026
550 ENC as of 02-SEP-2026

ENGINE NO. 2

SERIAL/PART: PCE-PK1804/3102700-01 MODEL: PT6A-60A MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 15-MAY-2014
0 ENG. HRS 0 A/C HRS
0 ENC

LAST ACTUALS:
1208.1 ENG. HRS as of 02-SEP-2026
550 ENC as of 02-SEP-2026

PROPELLER NO. 1

SERIAL/PART: 170711/MTV-27-1-E-C-F-R(P)/CFR260-65B MODEL: MTV-27-1-E-C-F-R(P)/CFR260-65 MANUFACTURER: MT-PROPELLER

INSTALLED ON: 19-DEC-2017
0 PROP HRS 616.4 A/C HRS
0 PRC

LAST ACTUALS:
591.7 PROP HRS as of 02-SEP-2026

PROPELLER NO. 2

SERIAL/PART: 170710/MTV-27-1-E-C-F-R(P)/CFR260-65B MODEL: MTV-27-1-E-C-F-R(P)/CFR260-65 MANUFACTURER: MT-PROPELLER

INSTALLED ON: 19-DEC-2017
0 PROP HRS 616.4 A/C HRS
0 PRC

LAST ACTUALS:
591.7 PROP HRS as of 02-SEP-2026

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
AIRCRAFT - AD - SUPER KING AIR B300 (350ER) FL-922/N130BD							
ATA - -- - GENERAL							
FAA 1993-25-07	1993-25-07 AMEND 39-8773					SUPERSEDED	- C/W AT MANUFACTURER
Eff. Date: 15-FEB-1994		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 1996-17-10	1996-17-10 AMEND 39-9719					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 24-SEP-1996		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 1998-15-13	1998-15-13 AMEND 39-10664					SUPERSEDED	- C/W AT MANUFACTURER
Eff. Date: 28-AUG-1998		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
ATA - 21 - AIR CONDITIONING							
FAA 1997-23-17	TO PREVENT A LOSS OF VACUUM TO DEPRESSURIZE THE AIRPLANE CABIN					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 29-DEC-1997		MOS					
		HRS/MSC	-				
2676							
FAA 1997-25-01	TO PREVENT OUTFLOW/SAFETY VALVE CRACKING AND CONSEQUENT FAILURE					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 11-JAN-1998		MOS					
		HRS/MSC	-				
ATA - 22 - AUTO FLIGHT							
FAA 1992-06-11	TO PREVENT INCORRECT PILOT DECISIONS BASED ON UNDETECTED ERRONEIOUS ATTITUDE INFORMATION DISPLAYED BY THE COLLINS EFIS-85/86B (14) SYSTEM OR UNDERSIRED AUTOPILOT MOVEMENT OF THE AIRPLANE					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 30-MAR-1992		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
ATA - 25 - EQUIPMENT/FURNISHINGS							
FAA 1994-01-01	TO PREVENT SEPARATION OF THE SEAT FROM ITS BASE CAUSED BY CRACKS AROUND THE WELDED-IN BUSHINGS					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 11-FEB-1994		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
2443							
FAA 2006-19-09	TO PREVENT THE PASSENGER SEATS FROM FAILING DURING EMERGENCY LANDING CONDITIONS WHEN HIGH INERTIAL LOADINGS OCCUR					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 24-OCT-2006		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
25-3640 R01							
ATA - 27 - FLIGHT CONTROLS							
FAA 1997-25-03	TO PREVENT NOSE DOWN PITCH AND A DESCENT RATE					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 21-JAN-1998		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 1999-02-16	TO PREVENT JAMMING OF THE ELEVATOR TRIM TAB ACTUATOR CAUSED BY ICE FORMATIONS					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 12-MAR-1999		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
2620							

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 1999-09-15	TO PREVENT AND COMPONENTS OR WIRING FROM INTERFERING WITH THE FLIGHT CONTROL MECHANISM CAUSED BY INADEQUATE CLEARANCE					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 18-MAY-1999		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
27-3232							
FAA 2002-23-11	TO PREVENT THE BALANCE WEIGHT ATTACHMENT SCREWS FROM BECOMING LOOSE					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 10-JAN-2003		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
27-3187 R01							
FAA 2006-23-02	TO DETECT AND CORRECT IMPROPERLY ASSEMBLED OR DAMAGED FLIGHT CONTROLS					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 13-DEC-2006		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2007-12-06	TO DETECT AND CORRECT IMPROPERLY ASSEMBLED OR DAMAGED FLIGHT CONTROLS					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 16-JUL-2007		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
27-3761							
FAA 2022-03-23	RUDDER CONTROL SYSTEM - GSA 9000 YAW SERVO - SOFTWARE UPDATE					MANDATORY	Not Applicable - AIRCRAFT IS NOT AFFECTED DUE TO SUPPLEMENTAL TYPE CERTIFICATE NO. SA01535WI-D HAS NOT BEEN COMPLIED WITH.
Eff. Date: 22-FEB-2022		DAYS		22-FEB-2022			
		HRS/MSC	-	1181.18	-		
		AFL		544			
FAA 2025-20-11 PARA (G)(1)	VISUAL INSPECTION OF THE ATTACHING RIVETS OF THE PILOT AND COPILOT RUDDER CONTROL PUSHRODS FOR INCORRECT RIVETS					MANDATORY	
Eff. Date: 17-OCT-2025		DAYS					
		HRS/MSC	-	-	-		
ATA - 30 - ICE AND RAIN PROTECTION							
FAA 1998-04-24	TO MINIMIZE THE POTENTIAL HAZARDS ASSOCIATED WITH OPERATING THESE AIRPLANES IN SEVERE ICING CONDITIONS					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 13-MAR-1998		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2008-07-10	TO PREVENT COLLAPSED PNEUMATIC SUPPLY TUBES					SUPERSEDED	- SUPERSEDED
Eff. Date: 10-APR-2008		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
30-3889							
FAA 2008-07-10 PARA E(1)	INSTALL TO PREVENT COLLAPSED PNEUMATIC SUPPLY TUBES					SUPERSEDED	- SUPERSEDED
Eff. Date: 10-APR-2008		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2008-07-10 PARA E(2)	REPLACE TO PREVENT COLLAPSED PNEUMATIC SUPPLY TUBES					SUPERSEDED	- SUPERSEDED
Eff. Date: 10-APR-2008		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2010-26-03	REPLACE THE PNEUMATIC SUPPLY TUBING FROM THE REAR SPAR						Complied With - AT MANUFACTURE
Eff. Date: 20-DEC-2010		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
30-3889 R01							

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2010-26-03 PARA F.(1)	INSTALL REPLACE THE PNEUMATIC SUPPLY TUBING FROM THE REAR SPAR PLACARD					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 20-DEC-2010		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2010-26-03 PARA F.(2)	REPLACE REPLACE THE PNEUMATIC SUPPLY TUBING FROM THE REAR SPAR					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 20-DEC-2010		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
ATA - 31 - INDICATING/RECORDING SYSTEMS							
FAA 2010-05-10	OPERATIONAL CHECK OF THE LEFT AND RIGHT PITOT HEAT ANNUNCIATORS FOR ILLUMINATION					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 08-APR-2010		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
31-3948							
FAA 2010-05-10 PARA (A)	OPERATIONAL CHECK OPERATIONAL CHECK OF THE LEFT AND RIGHT PITOT HEAT ANNUNCIATORS FOR ILLUMINATION					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 08-APR-2010		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2010-05-10 PARA (B)	INSPECT OPERATIONAL CHECK OF THE LEFT AND RIGHT PITOT HEAT ANNUNCIATORS FOR ILLUMINATION					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 08-APR-2010		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
ATA - 32 - LANDING GEAR							
FAA 1998-21-35	TO PREVENT FAILURE OF THE ACTUATOR CLEVIS ASSEMBLY IN THE MAIN LANDING GEAR CAUSED BY FATIGUE CRACKING OF THE ORIGINAL DESIGN PART					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 23-NOV-1998		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
2728 R01 LT							
FAA 1999-09-10	TO PREVENT THE INABILITY TO EXTEND THE LANDING GEAR WITH THE HAND PUMP CAUSED BY DEBRIS ENTERING THE LANDING GEAR HAND PUMP					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 07-JUN-1999		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
32-3073 R01							
FAA 1999-18-15	TO DETECT ANY IMPROPERLY MACHINED LANDING GEAR EMERGENCY HAND PUMPS					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 27-SEP-1999		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
ATA - 34 - NAVIGATION							
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	Not Applicable - N/A DUE TO INSTALLATION CONFIGURATION AND EQUIPMENT STRAPPING SEE PAGE 2 OF AD
Eff. Date: 14-OCT-2014		MOS		05-OCT-2016			
		HRS/MSC	-	221.4	-		
		AFL		102			
FAA 2015-10-51	AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS					MANDATORY	Not Applicable - DUE TO EQUIPMENT NOT INSTALLED IN AIRCRAFT.
Eff. Date: 01-JUL-2015		MOS		23-JUN-2015			
		HRS/MSC	-	20.3	-		
		AFL		16			

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2019-12-09	NAVIGATION - FDSA-6500 TCAS - AFM OR AFMS LIMITATIONS SECTION - REVISION / PLACARD INSTALLATION (SUPERSEDED BY FAA AD 2021-05-17)					MANDATORY	Not Applicable - NOT APPLICABLE
Eff. Date: 23-JUL-2019		DAYS HRS/MSC	 -	22-AUG-2019			
FAA 2020-10-05	NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS					MANDATORY	Complied With
Eff. Date: 24-JUN-2020		MOS HRS/MSC AFL	 - 	16-DEC-2021 1172.2 542	 -		
FAA 2021-05-17	NAVIGATION - ROCKWELL COLLINS FDSA-6500 FLIGHT DISPLAY SYSTEM - OPERATING LIMITIATIONS / SOFTWARE UPGRADE					MANDATORY	Not Applicable - NOT APPLICABLE, PROLINE 21 INSTALLED
Eff. Date: 29-APR-2021		MOS HRS/MSC AFL	 - 	16-DEC-2021 1172.2 542	 -		
FAA 2021-05-17 PARA (G)(1) & (	REVISE THE AIRCRAFT FLIGHT MANUAL (AFM) OR AFM SUPPLEMENT (AFMS), FABRICATE A PLACARD FOR EACH PRIMARY FLIGHT DISPLAY AND INSTALL THE PLACARD ON THE BOTTOM OF EACH PRIMARY FLIGHT DISPLAY BEZEL (RESTATEMENT OF FAA AD 2019-12-09)					MANDATORY	Not Applicable - NOT APPLICABLE, PROLINE 21 INSTALLED
Eff. Date: 23-JUL-2019		MOS HRS/MSC AFL	 - 	16-DEC-2021 1172.2 542	 -		
FAA 2021-05-17 PARA (G)(3)	UPGRADE THE FDSA-6500 FIELD LOADABLE SOFTWARE					MANDATORY	Not Applicable - NOT APPLICABLE, PROLINE 21 INSTALLED
Eff. Date: 29-APR-2021		MOS HRS/MSC AFL	 - 	16-DEC-2021 1172.2 542	 -		
FAA 2021-05-17 PARA (G)(5)	AS OF THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL A ROCKWELL COLLINS FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 P/N 810-0234-1H0001, 810-0234-1H0002, 810-0234-1H0003, 810-0234-2H0001, 810-0234-2C0001, 810-0234-2C0002, OR 810-0234-4B0001 ON ANY AIRPLANE					MANDATORY	Not Applicable - NOT APPLICABLE, PROLINE 21 INSTALLED
Eff. Date: 29-APR-2021		MOS HRS/MSC AFL	 - 	16-DEC-2021 1172.2 542	 -		
FAA 2025-07-01	THOMMEN AIRCRAFT EQUIPMENT AG (THOMMEN) AC32 DIGITAL AIR DATA COMPUTERS (ADCS)					MANDATORY	Not Applicable - DUE TO COLLINS ADC INSTALLED
Eff. Date: 15-MAY-2025		MOS HRS/MSC AFL	 - 	25-AUG-2026 1181.6 544	 -		
ATA - 35 - OXYGEN							
FAA 2015-08-07	OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES					MANDATORY	Not Applicable - DUE TO EQUIPMENT NOT INSTALLED
Eff. Date: 16-JUN-2015		MOS HRS/MSC AFL	 - 	23-JUN-2015 20.3 16	 -		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011					MANDATORY	Not Applicable - DUE TO EQUIPMENT NOT INSTALLED
Eff. Date: 16-JUN-2015		MOS		23-JUN-2015			
		HRS/MSC	-	20.3	-		
		AFL		16			
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES					MANDATORY	Not Applicable - DUE TO EQUIPMENT NOT INSTALLED
Eff. Date: 16-JUN-2015		MOS		23-JUN-2015			
		HRS/MSC	-	20.3	-		
		AFL		16			
ATA - 52 - DOORS							
FAA 2003-02-03	TO ASSURE THAT CLEAR AND COMPLETE OPERATING INSTRUCTIONS ARE VISIBLE FOR OPENING THE AIRSTAIR DOOR AND EMERGENCY EXITS					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 07-MAR-2003		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
52-3096 R01							
ATA - 53 - FUSELAGE							
FAA 2005-01-18 CORRECTION	TO DETECT AND CORRECT ANY CRACKED FUSELAGE STRINGERS IN THE REAR PRESSURE BULKHEAD AREA						- C/W AT MANUFACTURER
		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
ATA - 57 - WINGS							
FAA 2026-15-05	REVISE THE LIMITATIONS SECTION OF THE EXISTING AIRCRAFT MAINTENANCE MANUAL OR INSTRUCTIONS FOR CONTINUED AIRWORTHINESS AND THE EXISTING MAINTENANCE OR INSPECTION PROGRAM					MANDATORY	
		DAYS		10-AUG-2026			
		HRS/MSC	3800	1181.6	4981.6		
ATA - 71 - POWER PLANT							
FAA 1992-15-01	TO PREVENT UNDETECTED FAILURE OF ENGINE TRUSS-TO-FIREWALL BOLTS					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 21-AUG-1992		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
2432							
ATA - 73 - ENGINE FUEL AND CONTROL							
FAA 2004-17-02	TO DETECT AND CORRECT LOOSE BOLTS NOT SECURING THE PEDESTAL CROSS SHAFT					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 04-OCT-2004		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2004-17-02 PARA (I)	INSPECT TO DETECT AND CORRECT LOOSE BOLTS NOT SECURING THE PEDESTAL CROSS SHAFT						- C/W AT MANUFACTURER
		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2004-17-02 PARA (II)	MODIFY TO DETECT AND CORRECT LOOSE BOLTS NOT SECURING THE PEDESTAL CROSS SHAFT					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 04-OCT-2004		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2005-01-04 CORRECTION	TO PREVENT FUEL FLOW INTERRUPTION					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 22-FEB-2005		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
2718 R02							
ATA - 91 - -							
FAA 1991-20-14 R01	TO ENSURE THAT THE AFFECTED AIRPLANES ACHIEVE REQUIRED MINIMUM TAKEOFF AND CLIMB PERFORMANCE FOR EACH APPROVED COMBINATION OF TAKEOFF CONFIGURATION, WEIGHT, PRESSURE ALTITUDE, AND TEMPERATURE					AIRWORTHINESS DIRECTIVE	- C/W AT MANUFACTURER
Eff. Date: 12-SEP-1994		MOS					
		HRS/MSC	-				
FAA 2011-15-05	TO CORRECT THE PUBLISHED DATA IN THE AIRPLANE FLIGHT MANUAL AND THE PILOT'S OPERATING HANDBOOK AND ENSURE IT CORRESPONDS WITH THE PUBLISHED DATA IN THE PILOT'S CHECKLIST					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 19-AUG-2011		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
APPLIANCE - SUPER KING AIR B300 (350ER) FL-922/N130BD							
ATA - 22 - AUTO FLIGHT							
FAA 1998-08-20	APPLIANCE AD - AUTOPILOT - REPLACMENT OF ALLIEDSIGNAL AEROSPACE BENDIX/KING MODEL KSA 470 AUTOPILOT SERVO ACTUATORS PN 065-0076-10 THROUGH 065-0076-15					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 02-JUN-1998		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
22-3180 R01							
ATA - 25 - EQUIPMENT/FURNISHINGS							
FAA 1998-25-10	APPLIANCE AD - TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM DUE TO THE BUCKLE ASSEMBLY (BUCKLE) LOCKING MECHANISM NOT ENGAGING PROPERLY					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 24-DEC-1998		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 1998-25-10 R01	APPLIANCE AD - TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM, DUE TO THE BUCKLE ASSEMBLY (BUCKLE) LOCKING MECHANISM NOT ENGAGING PROPERLY					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 14-JAN-2000		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2017-09-09	APPLIANCE AD - PASSENGER COMPARTMENT EQUIPMENT - REPLACEMENT OF ZODIAC SEATS CALIFORNIA LLC SEATING SYSTEMS					MANDATORY	Not Applicable - FAA AD 2017-09-09 APPLIANCE-PASSENGER COMPARTMENT EQUIPMENT-REPLACEMENT OF ZIODIC SEAT, FOUND NOT APPLICABLE DUE TO PART NUMBER AND TYPE NOT INSTALLED TI THIS AIRCRAFT
Eff. Date: 28-JUN-2017		MOS		17-OCT-2018			
		HRS/MSC	-	867.1	-		
		AFL		407			
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS					MANDATORY	Not Applicable - By Part:
Eff. Date: 24-OCT-2017		MOS					
		HRS/MSC	-	-	-		
		AFL					

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2017-16-01 PARA (G)	APPLIANCE ADP - PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS						Not Applicable - By Part:
		MOS HRS/MSC AFL	-	-	-		
FAA 2017-16-01 PARA (J)	APPLIANCE ADP - OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT					MANDATORY	Not Applicable - By Part:
Eff. Date: 24-OCT-2017		MOS HRS/MSC AFL	-	-	-		
FAA 2017-16-04	APPLIANCE AD - ROMTEX ANJOU AERONAUTIQUE (ROMTEX) TORSO RESTRAINT SYSTEMS ROTARY BUCKLE ASSEMBLY INSPECTION AND REPLACEMENT					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 22-SEP-2017		MOS HRS/MSC AFL	-	-	-		
FAA 2017-16-04 PARA (E.1)	APPLIANCE ADP - INSPECT EACH RESTRAINT SYSTEM FOR CORRECT OPERATION					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 22-SEP-2017		MOS HRS/MSC AFL	-	-	-		
FAA 2017-16-04 PARA (E.1.I) &	APPLIANCE ADP - REPLACE THE BUCKLE ASSEMBLY WITH A BUCKLE ASSEMBLY NOT IDENTIFIED IN PARAGRAPH (A) OF THIS AD AND PLACARD THE SEAT AS INOPERATIVE IF THE STRAPS DO NOT RELEASE FROM BUCKLE ASSEMBLY					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 22-SEP-2017		MOS HRS/MSC AFL	-	-	-		
FAA 2017-16-04 PARA (E.2)	APPLIANCE ADP - DO NOT INSTALL A RESTRAINT SYSTEM WITH A BUCKLE ASSEMBLY IDENTIFIED IN PARAGRAPH (A) OF THIS AD ON ANY HELICOPTER					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 22-SEP-2017		MOS HRS/MSC AFL	-	-	-		
FAA 2017-22-02	APPLIANCE AD - FLIGHT COMPARTMENT EQUIPMENT - IPECO HOLDINGS LTD. -MODIFICATION AND REIDENTIFICATION OF PILOT'S AND CO-PILOT'S SEATS					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 12-DEC-2017		MOS HRS/MSC AFL	-	-	-		
FAA 2017-22-02 PARA (F)	APPLIANCE ADP - MODIFY AND RE-IDENTIFY AFFECTED EACH PILOT AND CO-PILOT SEAT					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 12-DEC-2017		MOS HRS/MSC AFL	-	-	-		
FAA 2017-22-02 PARA (G)	APPLIANCE ADP - DO NOT INSTALL ANY PILOT OR CO-PILOT SEAT IDENTIFIED IN PARAGRAPH (C) OF THIS AD UNLESS THE SEAT IS MODIFIED AND REIDENTIFIED AS SPECIFIED IN PARAGRAPH (F)(2) OF THIS AD					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 12-DEC-2017		MOS HRS/MSC AFL	-	-	-		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2018-16-01	APPLIANCE AD - APPLIANCE AD - EQUIPMENT / FURNISHINGS - SEAT ENERGY ABSORBER ASSEMBLY - REPLACEMENT					MANDATORY	Not Applicable - FAA AD 2018-16-01 APPLIANCE EQUIPMENT FURNISHING SEAT ENERGY ABSORBER ASSEMBLY, FOUND NOT APPLICABLE DUE TO PART NUMBER AND TYPE NOT INSTALLED TO THIS AIRCRAFT
Eff. Date: 31-AUG-2018		MOS HRS/MSC AFL	- 	17-OCT-2018 867.1 407	- 		
FAA 2018-16-01 PARA (G)	APPLIANCE ADP - REVIEW EACH AFFECTED ATTENDANT SEAT NG AND PILOT SEAT 120/335, REMOVE AND REPLACE THE EA ASSEMBLIES ON EACH AFFECTED PILOT SEAT, AND REMOVE EACH AFFECTED ATTENDANT SEAT AND REPLACE WITH A REWORKED SEAT IN ACCORDANCE WITH B/E AEROSPACE FISCHER ASB NO. SB 9911-001, ISSUE B, DATED NOVEMBER 4, 2016					MANDATORY	Not Applicable - FAA AD 2018-16-01 APPLIANCE EQUIPMENT FURNISHING SEAT ENERGY ABSORBER ASSEMBLY, FOUND NOT APPLICABLE DUE TO PART NUMBER AND TYPE NOT INSTALLED TO THIS AIRCRAFT
Eff. Date: 31-AUG-2018		MOS HRS/MSC AFL	- 	17-OCT-2018 867.1 407	- 		
FAA 2018-16-01 PARA (H)	APPLIANCE ADP - AFTER THE EFFECTIVE DATE OF THIS AD, DO NOT INSTALL AN AFFECTED SEAT ON AN AIRCRAFT UNLESS, PRIOR TO INSTALLATION, THE EA ASSEMBLIES ON THE SEAT HAVE BEEN REPLACED IN ACCORDANCE WITH B/E AEROSPACE FISCHER ASB NO. SB 9911-001, ISSUE B, DATED NOVEMBER 4, 2016					MANDATORY	Not Applicable - FAA AD 2018-16-01 APPLIANCE EQUIPMENT FURNISHING SEAT ENERGY ABSORBER ASSEMBLY, FOUND NOT APPLICABLE DUE TO PART NUMBER AND TYPE NOT INSTALLED TO THIS AIRCRAFT
Eff. Date: 31-AUG-2018		MOS HRS/MSC AFL	- 	17-OCT-2018 867.1 407	- 		
FAA 2018-16-13	APPLIANCE AD - EQUIPMENT/FURNISHINGS - INSPECT THE SAFETY BELT WEBBING, AND MODIFY AND RE-MARKING EACH AFFECTED CABIN ATTENDANT SEAT					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 26-OCT-2018		MOS HRS/MSC AFL	- 	- 	- 		
FAA 2018-16-13 PARA (G)	APPLIANCE ADP - INSPECT SAFETY BELT WEBBING, MODIFY AND RE-MARK EACH AFFECTED CABIN ATTENDANT SEAT USING ZODIAC SEATS FRANCE SERVICE INFORMATION LETTER 537-01					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 26-OCT-2018		MOS HRS/MSC AFL	- 	- 	- 		
FAA 2018-16-13 PARA (H)	APPLIANCE ADP - DO NOT INSTALL ANY AFFECTED ZODIAC SEATS FRANCE CABIN ATTENDANT SEAT ON ANY AIRCRAFT					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 26-OCT-2018		MOS HRS/MSC AFL	- 	- 	- 		
FAA 2018-19-15	APPLIANCE AD - EQUIPMENT / FURNISHINGS - SAFETY BELT ATTACHMENT BOLTS - INSPECTION / TORQUE VERIFICATION / MODIFICATION					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 14-NOV-2018		MOS HRS/MSC AFL	- 	- 	- 		
FAA 2018-23-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CABIN ATTENDANT SEAT - INSPECTION AND REPLACEMENT					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 28-DEC-2018		MOS HRS/MSC AFL	- 	- 	- 		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2018-23-01 PARA (G)	APPLIANCE ADP - INSPECT THE SEAT PAN STRUCTURE IN BOTH DEPLOYED AND STOWED POSITIONS (IF CRACKS ARE FOUND, REPLACE WITH REINFORCED SEAT PAN P/N F0511530 AND REMARK THE SEAT) (IF NO CRACKS ARE FOUND, REMARK THE SEAT AND REINSPECT OR REPLACE THE SEAT PAN WITH REINFORCED SEAT PAN P/N F0511530)					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 28-DEC-2018		MOS HRS/MSC AFL	- 	- 	- 		
FAA 2018-23-01 PARA (H)	APPLIANCE ADP - INSTALLATION OF A REINFORCED SEAT PAN, P/N F0511530, USING PARAGRAPH 2.B., ACCOMPLISHMENT INSTRUCTIONS, OF ZODIAC SEATS FRANCE SB NO. 536-25-003, REV. 3, DATED JUNE 2, 2017, IS TERMINATING ACTION TO THIS AD					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 28-DEC-2018		MOS HRS/MSC AFL	- 	- 	- 		
FAA 2018-23-12	APPLIANCE AD - EQUIPMENT / FURNISHINGS - INSPECTION AND REPLACEMENT OF ZODIAC AERO (ALSO KNOWN AS AIR CRUISERS COMPANY) EVACUATION SYSTEMS FUSIBLE PLUGS					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 28-DEC-2018		MOS HRS/MSC AFL	- 	- 	- 		
FAA 2018-23-12 PARA (G)	APPLIANCE ADP - ACCOMPLISH AN INSPECTION TO DETERMINE IF ANY PLUG HAS PART NUMBER (P/N) B13984-3, STAMPLED WITH LOT PA-21 OR PA-22					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 28-DEC-2018		MOS HRS/MSC AFL	- 	- 	- 		
FAA 2018-23-12 PARA (H)	APPLIANCE ADP - REPLACE FUSIBLE PLUG WITH A SERVICEABLE FUSIBLE PLUG P/N B13984-3 THAT IS NOT STAMPED WITH LOT PA-21 OR PA-22					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 28-DEC-2018		MOS HRS/MSC AFL	- 	- 	- 		
FAA 2018-23-12 PARA (I)	APPLIANCE ADP - NO PERSON SHAL INSTALL ON ANY AIRPLANE ANY FUSIBLE PLUG HAVING P/N B13984-3, STAMPLED WITH LOT PA-21 OR PA-22					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 28-DEC-2018		MOS HRS/MSC AFL	- 	- 	- 		
ATA - 26 - FIRE PROTECTION							
FAA 2003-26-14	APPLIANCE AD - KIDDE AEROSPACE PART NUMBER (P/N) 898052 HAND-HELD HALON FIRE EXTINGUISHERS					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 20-FEB-2004		MOS HRS/MSC	- 	15-MAY-2014 -	- 		
FAA 2010-01-03	APPLIANCE AD - REPLACE PORTABLE HALON 1211 (BCF) FIRE EXTINGUISHERS MANUFACTURED BY FIRE FIGHTING ENTERPRISES LIMITED WITH SERVICEABLE FIRE EXTINGUISHERS					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 20-JAN-2010		MOS HRS/MSC	- 	15-MAY-2014 -	- 		
FAA 2017-19-05	APPLIANCE AD - APPLIANCE AD - FIRE PROTECTION - OPTICAL AND AMBIENT SMOKE DETECTORS - IDENTIFICATION / REPLACEMENT					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 31-OCT-2017		MOS HRS/MSC AFL	- 	- 	- 		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2017-19-05 PARA (F)(1)	APPLIANCE ADP - INSPECT EACH SIEMENS SMOKE DETECTOR, OR REVIEW YOUR MAINTENANCE RECORDS, TO DETERMINE IF AN AFFECTED DETECTOR IS INSTALLED					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 31-OCT-2017		DAYS HRS/MSC AFL	 - 	 - 	 - 		
FAA 2017-19-05 PARA (F)(2.1)	APPLIANCE ADP - REPLACE CARGO COMPARTMENT SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (C)(1), SPECIFIED IN FIGURES 2 AND 3					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 31-OCT-2017		MOS HRS/MSC AFL	 - 	 - 	 - 		
FAA 2017-19-05 PARA (F)(2.2)	APPLIANCE ADP - REPLACE PASSENGER, CABIN OR ANY OTHER LOCATION SMOKE DETECTORS, IDENTIFIED IN PARAGRAPH (C)(1), SPECIFIED IN FIGURE 4					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 31-OCT-2017		MOS HRS/MSC AFL	 - 	 - 	 - 		
FAA 2017-19-05 PARA (F)(2.3)	APPLIANCE ADP - REPLACE REPAIRED SMOKE DETECTOR IDENTIFIED IN PARAGRAPH (C)(2), SPECIFIED FIGURE 1					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 31-OCT-2017		MOS HRS/MSC AFL	 - 	 - 	 - 		
FAA 2017-19-05 PARA (G)	APPLIANCE ADP - DO NOT INSTALL ON ANY AIRPLANE A SMOKE DETECTOR WITH A MANUFACTURING DATE AND P/N LISTED IN FIGURE 2 OR 3 OR LISTED IN FIGURE 4 TO PARAGRAPH (F) OF THIS AD UNLESS THE DETECTOR IS MARKED "SIL PMC-26-002"					MANDATORY	Not Applicable - Not Equipped:
Eff. Date: 31-OCT-2017		MOS HRS/MSC AFL	 - 	 - 	 - 		
ATA - 30 - ICE AND RAIN PROTECTION							
FAA 2005-18-20	APPLIANCE AD - TO PREVENT GOODRICH "FASTPROP" PROPELLER DE-ICERS FROM DETACHING FROM THE PROPELLER BLADE					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 14-OCT-2005		MOS HRS/MSC	 DAILY	15-MAY-2014 -	 -		
ATA - 31 - INDICATING/RECORDING SYSTEMS							
FAA 2023-10-02	APPLIANCE AD - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION					MANDATORY	Complied With
Eff. Date: 26-MAY-2023		MOS HRS/MSC AFL	 - 	25-AUG-2026 1181.6 544	 -		
FAA 2023-10-02 PARA (H)	APPLIANCE ADP - REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30--JUNE- 2023 - SATISFIED BY FAA 2021-23-12)					MANDATORY	Complied With
Eff. Date: 26-MAY-2023		MOS HRS/MSC AFL	 - 	25-AUG-2026 1181.6 544	 -		
FAA 2023-10-02 PARA (I)	APPLIANCE ADP - REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)					MANDATORY	Complied With
Eff. Date: 26-MAY-2023		MOS HRS/MSC AFL	 - 	25-AUG-2026 1181.6 544	 -		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2026-13-02 PARA (H)	APPLIANCE ADP - AIRPLANE FLIGHT MANUAL (AFM) REVISION					MANDATORY	
Eff. Date: 01-JUL-2026		MOS					
		HRS/MSC	BF/F				
ATA - 34 - NAVIGATION							
FAA 1993-04-02	APPLIANCE AD - TO PREVENT A MID-AIR COLLISION OR A NEAR-MISS SITUATION CUASED BY FAILURE OF THESE MODE S TRANSPONDERS					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 26-MAR-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 1994-01-06	APPLIANCE AD - TO PREVENT COLLISIONS OR NEAR MISSES CAUSED BY INCOMPATIBILITY BETWEEN THE TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) II PROCESSORS AND THE CURRENT AIR TRAFFIC CONTROL SYSTEM					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 04-FEB-1994		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 1998-25-02	APPLIANCE AD - TO PREVENT THE DISPLAY OF TARGET INDICATORS ON THE WRONG SIDE OF THE AIRCRAFT CAUSED BY AN INTERNAL COMPONENT FAILURE IN THE SKY497 INSTALLATIONS WITH A TOP-MOUNTED ANTENNA					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 22-DEC-1998		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2001-15-17	APPLIANCE AD - TO PREVENT SUCH ERRONEOUS ALTITUDE INTERPRETATIONS					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 20-AUG-2001		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2002-06-06	APPLIANCE AD - TDR-94 MODE S TRANSPONDERS (COLLINS PART NUMBER (CPN) 622-9352-004) AND TDR-94D MODE S TRANSPONDERS (CPN 622-9210-004)						- C/W AT MANUFACTURER
		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2002-14-19	APPLIANCE AD - TO PREVENT AN UNWARRANTED DISPLAY OF THE ADC FLAG WHEN SWITCHING STATIC AIR SOURCES					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 23-AUG-2002		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2003-13-08	APPLIANCE AD - TO PREVENT THE LOADING OF THE BARO SET POTENTIOMETER					SUPERSEDED	- C/W AT MANUFACTURER
Eff. Date: 21-JUL-2003		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2004-08-15	APPLIANCE AD - TO PREVENT THE LOADING OF THE BARO SET POTENTIOMETER					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 07-JUN-2004		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2005-01-19	APPLIANCE AD - TO PREVENT INTERROGATING AIRCRAFT FROM POSSIBLY RECEIVING INACCURATE REPLIES					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 23-FEB-2005		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2006-16-18	APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 25-SEP-2006		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2006-16-18 PARA (F)	APPLIANCE ADP - INSTALL SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS PLACARD					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 25-SEP-2006		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2006-16-18 PARA (G)	APPLIANCE ADP - REVISE SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS AIRPLANE FLIGHT MANUAL (AFM)					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 25-SEP-2006		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2006-16-18 PARA (H)	APPLIANCE ADP - UPDATE SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS SOFTWARE					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 25-SEP-2006		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2006-16-18 R01	APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 18-JUL-2008		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2006-16-18 R01 PARA (F)	APPLIANCE ADP - INSTALL SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS PLACARD					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 18-JUL-2008		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2006-16-18 R01 PARA (G)	APPLIANCE ADP - REVISE SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS AIRPLANE FLIGHT MANUAL (AFM)					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 18-JUL-2008		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2006-16-18 R01 PARA (H)	APPLIANCE ADP - UPDATE SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI) UNITS SOFTWARE					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 18-JUL-2008		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
FAA 2017-11-11	APPLIANCE AD - NAVWORX, INC, AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST (ADS-B) UNIVERSAL ACCESS TRANSCEIVER UNITS - REMOVE, DISABLE, OR REVISE SOFTWARE TO BROADCAST A SIL OF 0					MANDATORY	Not Applicable - By Part:
Eff. Date: 11-JUL-2017		MOS					
		HRS/MSC	-	-	-		
		AFL					
FAA 2017-22-14	APPLIANCE AD - NAVIGATION - INSTALLATION OF THE TSSA-4100 FLS UPGRADES ON THE ROCKWELL COLLINS, INC. TSS-4100 TRAFFIC SURVEILANCE SYSTEM PROCESSING UNITS					MANDATORY	Not Applicable - FAA AD 2017-22-14 APPLIANCE - NAVIGATION-INSTALLATION OF TH TSSA-4100 FLS UPGRADES FOUND NOT APPLICABLE DUE TO PART NUMBER AND TYPE NOT INSTALLED TI THIS AIRCRAFT
Eff. Date: 20-DEC-2017		MOS		17-OCT-2018			
		HRS/MSC	-	867.1	-		
		AFL		407			

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2018-03-04	APPLIANCE AD - NAVIGATION - REPLACEMENT OF ROSEMOUNT AEROSPACE INC. MODEL 851AK PITOT PROBES REPAIRED BY CSI AEROSPACE INC					MANDATORY	Not Applicable - FAA AD 2018-03-04 APPLIANCE - REPLACEMENT OF ROSEMOUNT AEROSPACE INC. MODEL 851AK PITOT PROBES, FOUND NOT APPLICABLE DUE TO PART NUMBER AND TYPE NOT INSTALLED TO THIS AIRCRAFT
Eff. Date: 16-MAR-2018		MOS HRS/MSC AFL	- 	17-OCT-2018 867.1 407	- 		
FAA 2018-03-04 PARA (G)	APPLIANCE ADP - DETERMINE NUMBER OF AFFECTED PITOT PROBES INSTALLED					MANDATORY	Not Applicable - FAA AD 2018-03-04 APPLINACE - REPLACEMENT OF ROSEMOUNT AEROSPACE INC. MODEL 851AK PITOT PROBES, FOUND NOT APPLICABLE DUE TO PART NUMBER AND TYPE NOT INSTALLED TI THIS AIRCRAFT
Eff. Date: 16-MAR-2018		DAYS HRS/MSC AFL	- 	17-OCT-2018 867.1 407	- 		
FAA 2018-03-04 PARA (H)(1)	APPLIANCE ADP - REPLACE AFFECTED PITOT PROBES					MANDATORY	Not Applicable - FAA AD 2018-03-04 APPLINACE - REPLACEMENT OF ROSEMOUNT AEROSPACE INC. MODEL 851AK PITOT PROBES, FOUND NOT APPLICABLE DUE TO PART NUMBER AND TYPE NOT INSTALLED TI THIS AIRCRAFT
Eff. Date: 16-MAR-2018		MOS HRS/MSC AFL	- 	17-OCT-2018 867.1 407	- 		
FAA 2018-03-04 PARA (H)(2)	APPLIANCE ADP - DO NOT INSTALL ON ANY AIRPLANE A PITOT PROBE HAVING A SERIAL NUMBER LISTED IN PARA (C)(1) OF THIS AD, UNLESS IT HAS BEEN PROPERLY REPAIRED, AND IF REPAIRED BY CSI AEROSPACE, INC., HAS A REPAIR DATE OF AUGUST 1, 2014, OR LATER					MANDATORY	Not Applicable - FAA AD 2018-03-04 APPLINACE - REPLACEMENT OF ROSEMOUNT AEROSPACE INC. MODEL 851AK PITOT PROBES, FOUND NOT APPLICABLE DUE TO PART NUMBER AND TYPE NOT INSTALLED TI THIS AIRCRAFT
Eff. Date: 16-MAR-2018		MOS HRS/MSC AFL	- 	17-OCT-2018 867.1 407	- 		
ATA - 35 - OXYGEN							
FAA 1999-08-21	APPLIANCE AD - TO PREVENT REDUCED OXYGEN CONSUMPTION WHEN PASSENGERS ARE REQUIRED TO USE DEFECTIVE OXYGEN MASKS					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 02-JUN-1999		MOS HRS/MSC	- 	15-MAY-2014 -	- 		
FAA 2023-13-11	APPLIANCE AD - OXYGEN - OXYGEN VALVE ASSEMBLIES / OXYGEN CYLINDER AND VALVE ASSEMBLIES - INSPECTION/REPLACEMENT					MANDATORY	Not Applicable - ALPHASTAR FLEET IS NOT AFFECTED BY THIS AD, AS LISTED SN'S IN REF. /B/, /C/, AND /D/ ARE NOT INSTALLED ON THE FLEET.
Eff. Date: 05-SEP-2023		MOS HRS/MSC AFL	- 	22-AUG-2023 - 	- 		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2023-13-11 PARA (H)	APPLIANCE ADP - INSPECT THE OXYGEN VALVE ASSEMBLIES AND OXYGEN CYLINDER AND VALVE ASSEMBLIES					MANDATORY	Not Applicable - ALPHASTAR FLEET IS NOT AFFECTED BY THIS AD, AS LISTED SN'S IN REF. /B/, /C/, AND /D/ ARE NOT INSTALLED ON THE FLEET.
Eff. Date: 05-SEP-2023		DAYS HRS/MSC	 -	22-AUG-2023			
FAA 2023-13-11 PARA (J)	APPLIANCE ADP - REPORT THE RESULTS OF THE INSPECTION AND RETURN PARTS (AS REQUIRED)					MANDATORY	Not Applicable - ALPHASTAR FLEET IS NOT AFFECTED BY THIS AD, AS LISTED SN'S IN REF. /B/, /C/, AND /D/ ARE NOT INSTALLED ON THE FLEET.
		DAYS HRS/MSC	 -	22-AUG-2023			
FAA 2025-25-02	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - OPERATIONAL INSTRUCTIONS					MANDATORY	
Eff. Date: 24-DEC-2025		DAYS HRS/MSC	 -				
FAA 2025-26-06	APPLIANCE AD - INCORRECT USAGE OF PORTABLE BREATHING EQUIPMENT					MANDATORY	Not Applicable - DUE TO P8E'S NOT INSTALLED ON AIRCRAFT
Eff. Date: 14-JAN-2026		DAYS HRS/MSC AFL	 - 	25-AUG-2026 1181.6 544	 -		
FAA 2026-03-09	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - REMOVAL FROM SERVICE					MANDATORY	Not Applicable - DUE TO P8E'S NOT INSTALLED ON AIRCRAFT
Eff. Date: 12-MAR-2026		MOS HRS/MSC AFL	 - 	25-AUG-2026 1181.6 544	 -		
FAA 2026-03-09 PARA (G) EASA (	APPLIANCE ADP - LIFE LIMIT: REMOVE FROM SERVICE					MANDATORY	Not Applicable - DUE TO P8E'S NOT INSTALLED ON AIRCRAFT
		MOS HRS/MSC AFL	 - 	25-AUG-2026 1181.6 544	 -		
ATA - 44 - CABIN SYSTEMS							
FAA 2017-04-06	APPLIANCE AD - CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016					MANDATORY	Not Applicable - AD CHECK WITH UNITED INSTRUMENT INC, SB NO.13 DATED MAR 25, 2016 AND FOUND NOT APPLICABLE DUE TO THE SERIES ALTIMETER NOT FITTED TO THE AIRCRAFT
Eff. Date: 07-APR-2017		MOS HRS/MSC AFL	 - 	04-APR-2018 711.8 340	 -		
AIRCRAFT - SB - SUPER KING AIR B300 (350ER) FL-922/N130BD							
ATA - 05-00 - TIME LIMITS/MAINTENANCE CHECKS							
CEO BRQ-05-001 R01	GENERAL VISUAL INSPECTION (GVI) OF THE EXTERIOR OF THE AIRCRAFT, CUSTOMER ENGINEERING ORDER						Complied With
Eff. Date: 31-MAY-2023		DAYS HRS/MSC	 -	28-OCT-2022			
ATA - 11 - PLACARDS AND MARKINGS							

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 11-3211	PLACARDS & MARKINGS - MAIN AND AUXILIARY FUEL TANK USEABLE AND TOTAL FUEL QUANTITY DECAL INSTALLATION, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-NOV-1998		MOS					
		HRS/MSC	-				

ATA - 21 - AIR CONDITIONING

SB 21-3303 R01	AIR CONDITIONING - INSTALLATION OF NEW COMPRESSOR DRIVE QUILL SHAFT, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-JUN-2000		MOS					
		HRS/MSC	-				
SB 21-3838	ENVIRONMENTAL SYSTEMS - INTRODUCTION OF IMPROVED ENVIRONMENTAL CONTROLLER, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-MAY-2008		MOS					
		HRS/MSC	-				
SB 21-3890	AIR CONDITIONING - ENVIRONMENTAL CONTROL SYSTEM FLOW MODIFICATION, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-APR-2008		MOS					
		HRS/MSC	-				
SB 21-3932	AIR CONDITIONING - IMPROVED AIR CONDITIONER COMPRESSOR MOUNTING BRACKETS, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-MAR-2009		MOS					
		HRS/MSC	-				
SB 2484 R01	ENVIRONMENTAL/AIR CONDITIONING - OUTFLOW/SAFETY VALVE INSPECTION/REPLACEMENT, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-OCT-1995		MOS					
		HRS/MSC	-				
SB 2676	ENVIRONMENTAL/AIR CONDITIONING - PRESSURIZATION CONTROL SYSTEM PNEUMATIC TUBING INSPECTION/REPAIR, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-JAN-1997		MOS					
		HRS/MSC	-				
SL MTL-21-03	AIR CONDITIONING - COCKPIT FOOT WARMER DUCT INSPECTION, SERVICE LETTER					RECOMMENDED	
Eff. Date: 08-AUG-2023		MOS	12		08-AUG-2024		
		HRS/MSC	200	-	1429.92		

ATA - 22 - AUTO FLIGHT

SB 22-3180 R01	AUTO FLIGHT - ANNOUNCEMENT OF AN AIRWORTHINESS DIRECTIVE AGAINST ALLIED SIGNAL AEROSPACE BENDIX/KING MODEL KSA 470 AUTOPILOT SERVO ACTUATORS, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-JUL-1998		MOS					
		HRS/MSC	-				
SB 2423	AUTO FLIGHT - MODIFICATION OF COLLINS EFIS-85B (14) ELECTRONIC FLIGHT INSTRUMENT SYSTEM AND APS-65H AUTOPILOT WIRING, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-DEC-1991		MOS					
		HRS/MSC	-				
SL MTL-22-02	AUTO FLIGHT - TRANSMITTAL OF INNOVATIVE SOLUTIONS AND SUPPORT INC RECALL NOTICE RN2203, SERVICE LETTER					MANDATORY	
Eff. Date: 10-MAY-2022		MOS					
		HRS/MSC	-	-	-		

ATA - 23 - COMMUNICATIONS

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 2715	COMMUNICATIONS - REPLACEMENT OF THE A017 COMPONENT PRINTED CIRCUIT BOARD, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-MAY-1997		MOS					
		HRS/MSC	-				
ATA - 24 - ELECTRICAL POWER							
SB 24-3058 R01	ELECTRICAL POWER - GROUND INTERPHONE AMPLIFIER, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-AUG-1998		MOS					
		HRS/MSC	-				
SB 24-3245	ELECTRICAL POWER - RELOCATION OF THE LANDING GEAR 60 AMP CIRCUIT BREAKER AND IMPROVEMENTS TO THE INBOARD WING LEADING EDGE INLET DUCT, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-APR-1999		MOS					
		HRS/MSC	-				
SB 24-3363	ELECTRICAL - INSTALLATION OF EXTERNAL DC POWER SWITCH TRANSIENT SUPPRESSION KIT, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-OCT-2000		MOS					
		HRS/MSC	-				
SB 24-3546	REPLACEMENT OF THE "00" AWG WIRE HARNESS ASSEMBLY, SERVICE BULLETIN					MANDATORY	Not Applicable
		MOS					
		HRS/MSC	-				
SB 24-3681	ELECTRICAL POWER - INSPECTION OF EXTERNAL POWER RELAY, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-AUG-2004		MOS					
		HRS/MSC	-				
SB 24-3937	ELECTRICAL POWER - DISCHARGE OF MAIN AIRPLANE BATTERY, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-JUN-2009		MOS					
		HRS/MSC	-				
SB 24-4017	ELECTRICAL POWER - INSPECTION / REPLACEMENT OF EXTERNAL POWER CONTROL CIRCUIT BREAKER, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-MAY-2010		MOS					
		HRS/MSC	-				
SB 2611	ELECTRICAL POWER - FLIGHT CONTROL SYSTEM (FCS) CIRCUIT BREAKER REPLACEMENT FOR AIRPLANES EQUIPPED WITH A COLLINS APS-65 AUTOPILOT SYSTEM, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-JUN-1995		MOS					
		HRS/MSC	-				
ATA - 25 - EQUIPMENT/FURNISHINGS							
SB 2443	EQUIPMENT/FURNISHINGS - INSPECTION/MODIFICATION OF CABIN SEAT FRAMES, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-JUL-1993		MOS					
		HRS/MSC	-				
SB 25-3418	EQUIPMENT/FURNISHINGS - EMERGENCY LOCATOR TRANSMITTER (ELT) PLACARD, SERVICE BULLETIN						Not Applicable
		MOS					
		HRS/MSC	-				
SB 25-3640	EQUIPMENT/FURNISHINGS - CABIN SWIVELING CHAIR FRAME MODIFICATION, SERVICE BULLETIN					SUPERSEDED	Not Applicable
Eff. Date: 01-MAY-2005		MOS					
		HRS/MSC	-				

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 25-3640 R01	EQUIPMENT/FURNISHINGS - CABIN SWIVELING CHAIR FRAME MODIFICATION, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-JAN-2006		MOS					
		HRS/MSC	-				
SB 25-3919	EQUIPMENT/FURNISHINGS - CREW SEAT INERTIAL REEL WEB STOP INSTALLATION, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-JUL-2009		MOS					
		HRS/MSC	-				
SB 25-4020	EQUIPMENT/FURNISHINGS - INSPECTION/REPLACEMENT OF CREW CHAIR FRAME ASSEMBLIES, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-JUN-2010		MOS					
		HRS/MSC	-	-	-		
SB 25-4031	EQUIPMENT/FURNISHINGS - INSTALLATION OF OMITTED INSERTS AND WASHERS IN AFT BAGGAGE PARTITION, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-DEC-2011		MOS					
		HRS/MSC	-	-	-		
SB 25-4055	EQUIPMENT/FURNISHINGS - INSPECTION / REPLACEMENT OF CABIN SEAT SWIVEL ASSEMBLIES, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 05-JAN-2010		MOS					
		HRS/MSC	-				
SB 2598 R02	EQUIPMENT/FURNISHINGS - EMERGENCY LOCATOR PLACARD INSTALLATION, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-JUN-2000		MOS					
		HRS/MSC	-				
SL MTL-25-05	EQUIPMENT/FURNISHINGS- SURFACE PREPARATION AND APPLICATION OF NEW FASTENER TAPE TO SECURE THE COMPASS COVER ASSEMBLY, SERVICE LETTER					RECOMMENDED	
Eff. Date: 13-AUG-2026		MOS					
		HRS/MSC	-				
ATA - 26 - FIRE PROTECTION							
SL MTL-26-01	FIRE PROTECTION - FUSELAGE BLEED AIR WARNING LINE INSPECTION, SERVICE LETTER					MANDATORY	
Eff. Date: 30-OCT-2024		MOS					
		HRS/MSC	-	-	-		
SL MTL-26-01 R01	FIRE PROTECTION - FUSELAGE ONLY BLEED AIR ETHYLENE VINYL ACETATE (EVA) INSPECTION, SERVICE LETTER					MANDATORY	
Eff. Date: 30-OCT-2024		MOS	12		30-OCT-2025		
		HRS/MSC	200	-	1561.42		
SL MTL-26-02	FIRE PROTECTION - CENTER WING AND NACELLE BLEED AIR WARNING LINE INSPECTION, SERVICE LETTER					MANDATORY	
Eff. Date: 07-OCT-2025		MOS					
		HRS/MSC	-	-	-		
SL MTL-26-03	FIRE PROTECTION - BLEED LEAK SENSE LINE PRO SEAL INSPECTION, SERVICE LETTER					RECOMMENDED	
Eff. Date: 03-JUL-2025		MOS					
		HRS/MSC	-				
ATA - 27 - FLIGHT CONTROLS							
SC 149 R01	LOSS OF AILERON AND ELEVATOR CONTROL, SAFETY COMMUNIQUE					INFORMATIONAL	Not Applicable
Eff. Date: 01-NOV-1998		MOS					
		HRS/MSC	-				

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SC 185	FLIGHT CONTROLS - VISUAL/INSPECT CONTROL COLUMN/185-, SAFETY COMMUNIQUE						Not Applicable
		MOS					
		HRS/MSC	-				
SC 225	AILERON SYSTEM CONTROL SPROCKET, SAFETY COMMUNIQUE					RECOMMENDED	Not Applicable
Eff. Date: 20-JUN-2003		MOS					
		HRS/MSC	-				
SB 2620	FLIGHT CONTROLS - ELEVATOR TRIM TAB ACTUATOR MODIFICATION, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-NOV-1996		MOS					
		HRS/MSC	-				
SB 2629	FLIGHT CONTROLS - FLAP RIB REPLACEMENT, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-FEB-1996		MOS					
		HRS/MSC	-				
SC 265	INSPECTION OF FLIGHT CONTROL SYSTEM AND RIGGING, SAFETY COMMUNIQUE					RECOMMENDED	Not Applicable
Eff. Date: 01-NOV-2005		MOS					
		HRS/MSC	-				
SB 27-3038	STABILIZERS - INSP OF RUDDER TORQUE SHAFT SUPPORT BEARING RETENTION NUT FOR THREAD ENGAGEMENT, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-MAR-2000		MOS					
		HRS/MSC	-				
SB 27-3044	FLIGHT CONTROLS - TRIM ACTUATOR LUBRICATION PLACARD, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-APR-2000		MOS					
		HRS/MSC	-				
SB 27-3095	FLIGHT CONTROLS - ADDITION OF JUMPER WIRE TO STALL WARNING LIFT COMPUTER, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-NOV-2001		MOS					
		HRS/MSC	-				
SB 27-3187 R01	FLIGHT CONTROLS - ELEVATOR ADJUSTMENT WEIGHTS INSTALLATION/MODIFICATION, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-SEP-2001		MOS					
		HRS/MSC	-				
SB 27-3232	FLIGHT CONTROLS - INSPECTION FOR CONTROL COLUMN INTERFERENCE WITH WIRING BEHIND THE INSTRUMENT PANEL, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-MAR-1999		MOS					
		HRS/MSC	-				
SB 27-3459	FLIGHT CONTROL - FLIGHT CONTROL GUST LOCK INSPECTION/REPLACEMENT, SERVICE BULLETIN					MANDATORY	Complied With - COMPLIED WITH GUST LOCK PN 101-590016-9 INSTALLED
Eff. Date: 01-SEP-2002		MOS		17-MAY-2016			
		HRS/MSC	-	194.4	-		
		AFL		87			

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 27-3459 R01	FLIGHT CONTROLS - FLIGHT CONTROL (GUST) LOCK INSPECTION / REPLACEMENT, SERVICE BULLETIN					MANDATORY	Complied With - GUST LOCK INSPECTED WITH REF TO BEECHCRAFT SB 27-3459 R1 AND FOUND TO BE INCOMPLIANCE WITH SB SECTION 2(C) AND 3(A).FOUND GUST LOCK P/N 101-590016-9 FITTED.NEXT DUE AT PHASE 1 INSP.
Eff. Date: 01-NOV-2016		MOS		04-NOV-2016			
		HRS/MSC	-	248.2	-		
		AFL		120			
SB 27-3459 R02	FLIGHT CONTROLS - FLIGHT CONTROL (GUST) LOCK INSPECTION / REPLACEMENT, SERVICE BULLETIN					MANDATORY	Complied With
Eff. Date: 01-NOV-2016		MOS	12	16-DEC-2021	16-DEC-2022	RECURRING	
		HRS/MSC	-	1172.2	-		
		AFL		542			
SB 27-3472 R01	FLIGHT CONTROLS - ELEVATOR TRIM TAB ACTUATOR MODIFICATION, SERVICE BULLETIN						Not Applicable
		MOS					
		HRS/MSC	-				
SB 27-3492	CONTROL COLUMN INSPECTION/MODIFICATION, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-OCT-2001		MOS					
		HRS/MSC	-				
SB 27-3668 R01	FLIGHT CONTROLS - INSPECTION/MODIFICATION OF AILERON OUTBOARD HINGE FITTING, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-SEP-2004		MOS					
		HRS/MSC	-				
SB 27-3761	FLIGHT CONTROLS - INSPECTION OF FLIGHT CONTROL SYSTEM AND RIGGING, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-FEB-2006		MOS					
		HRS/MSC	-				
SB 27-3761 R01	FLIGHT CONTROLS - INSPECTION OF FLIGHT CONTROL SYSTEM AND RIGGING, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-DEC-2006		MOS					
		HRS/MSC	-				
SB 27-4082	FLIGHT CONTROLS - INSPECTION / REPLACEMENT OF IMPROPER HARDWARE ON OUTBOARD AILERON BELLCRANK, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-DEC-2011		MOS					
		HRS/MSC	-				
SL MTL-27-01 R01	FLIGHT CONTROLS - CONTROL COLUMN MASTER LINK AILERON INTERCONNECT CHAIN INSPECTION, SERVICE LETTER					MANDATORY	Complied With
Eff. Date: 04-OCT-2017		MOS		13-JAN-2019			
		HRS/MSC	-	962.2	-		
		AFL		451			
SL MTL-27-05 R02	FLIGHT CONTROLS - ELEVATOR BELLCRANK INSPECTION, SERVICE LETTER					MANDATORY	
		MOS					
		HRS/MSC	30000	-	30000		
SL MTL-27-06	FLIGHT CONTROLS - RUDDER PEDAL PUSHROD LINKAGE INSPECTION, SERVICE LETTER					MANDATORY	
Eff. Date: 06-FEB-2025		MOS					
		HRS/MSC	-				

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SL MTL-27-07 INSPECTION	ACCOMPLISH FLIGHT CONTROLS - PILOT AND COPILOT RUDDER PEDAL PUSHROD LINKAGE INSPECTION, SERVICE LETTER INSPECT THE PILOTS AND COPILOT'S RUDDER PUSHRODS FOR THE CORRECT RIVETS					MANDATORY	
Eff. Date: 25-JUL-2025		DAYS HRS/MSC	- -	- -	- -		
ATA - 28 - FUEL							
SB 2718 R02	FUEL - REPLACEMENT OF MIL-H-6000B HOSE MANUFACTURED BY BUCKEYE RUBBER PRODUCTS INC., SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-APR-2000		MOS HRS/MSC	- -				
SB 28-3401	FUEL CELL COVER AND GASKET INSTALLATION, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-DEC-2001		MOS HRS/MSC	- -				
SB 28-3825	FUEL - INSPECTION/REPLACEMENT OF P/N 101-389020-1 FLOAT VALVES, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-AUG-2007		MOS HRS/MSC	- -				
SB 28-3986	FUEL - REPLACEMENT OF FUEL LINE VENT TUBE ASSEMBLIES IN LEFT AND RIGHT MAIN LANDING GEAR WHEEL WELLS, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-AUG-2009		MOS HRS/MSC	- -				
SB 28-4059	FUEL - INTRODUCTION OF IMPROVED FUEL CELL GASKET, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-AUG-2011		MOS HRS/MSC	- -				
SB 28-4059 R01	FUEL - INTRODUCTION OF IMPROVED FUEL CELL GASKET, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-SEP-2015		MOS HRS/MSC	- -	- -	- -		
SB 28-4128	FUEL - INSPECTION FOR CONDITION OF WING FUEL SYSTEM, SERVICE BULLETIN					MANDATORY	Not Applicable - BY AIRCRAFT SERIAL NUMBER
Eff. Date: 01-MAR-2014		MOS HRS/MSC AFL	- -	23-JUN-2015 20.3 16	- -		
ATA - 30 - ICE AND RAIN PROTECTION							
SB 30-3471	ICE & RAIN PROTECTION - CABIN/COCKPIT WINDOW DEFROST SYSTEM, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-OCT-2001		MOS HRS/MSC	- -				
SB 30-3889	ICE AND RAIN PROTECTION - REPLACEMENT OF TAIL DEICE BOOT PNEUMATIC SUPPLY TUBES, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-MAR-2008		MOS HRS/MSC	- -				
SB 30-3889 R01	ICE AND RAIN PROTECTION - REPLACEMENT OF TAIL DEICE BOOT PNEUMATIC SUPPLY TUBING, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-OCT-2010		MOS HRS/MSC	- -				

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB MTB-30-02	ICE AND RAIN PROTECTION- LEFT AND RIGHT ENGINE AFT INERTIAL INLET VANE DOOR BONDING JUMPER REMOVAL, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 17-AUG-2026		MOS HRS/MSC	- -				
SL MTL-30-03	ICE AND RAIN PROTECTION - TRANSMITTAL OF COLLINS AEROSPACE SERVICE BULLETIN (SB) 8752-30-001 REVISION 1, BLACK STANDARD, STANDARD SILVER URETHANE, FASTBOOT® SILVER URETHANE, AND FASTBOOT® PNEUMATIC DE-ICE BOOTS, SERVICE LETTER					RECOMMENDED	
Eff. Date: 15-APR-2025		MOS HRS/MSC	- -				
ATA - 31 - INDICATING/RECORDING SYSTEMS							
SB 31-3948	INDICATING/RECORDING SYSTEMS - INSPECTION/CORRECTION OF PITOT HEAT ANNUNCIATION WIRING, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-APR-2009		MOS HRS/MSC	- -				
ATA - 32 - LANDING GEAR							
SB 2386	LANDING GEAR - REPLACEMENT OF ALLEN AIRCRAFT MAIN LANDING GEAR ACTUATORS, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-DEC-1992		MOS HRS/MSC	- -				
SB 2407	LANDING GEAR - REPLACEMENT OF AIRIGHT HYDRAULIC POWER PACKS, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-SEP-1991		MOS HRS/MSC	- -				
SB 2658 R02 LT	LANDING GEAR - MAIN LANDING GEAR ACTUATOR BEARING SUPPORT BRACKET REPLACEMENT, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-MAY-1999		MOS HRS/MSC	- -				
SB 2658 R02 RT	LANDING GEAR - MAIN LANDING GEAR ACTUATOR BEARING SUPPORT BRACKET REPLACEMENT, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-MAY-1999		MOS HRS/MSC	- -				
SB 2728 R01 LT	LANDING GEAR - MAIN LANDING GEAR ACTUATOR CLEVIS REPLACEMENT, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-FEB-1998		MOS HRS/MSC	- -				
SB 2728 R01 RT	LANDING GEAR - MAIN LANDING GEAR ACTUATOR CLEVIS REPLACEMENT, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-FEB-1998		MOS HRS/MSC	- -				
SB 32-3057	LANDING GEAR - INSTALLATION OF THE LANDING GEAR HORN SILENCE SWITCH TO THE LEFT HAND POWER LEVER, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-JUL-1998		MOS HRS/MSC	- -				
SB 32-3073 R01	LANDING GEAR - HAND PUMP INLET FILTER INSTALLATION, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-JUL-1998		MOS HRS/MSC	- -				

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 32-3340	LANDING GEAR - LANDING GEAR HYDRAULIC HAND PUMP REPLACEMENT, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-JAN-2000		MOS					
		HRS/MSC	-				
SB 32-3662 LEFT	LANDING GEAR - MAIN LANDING GEAR (MLG) PISTON ASSEMBLY REPLACEMENT, SERVICE BULLETIN						Not Applicable
		MOS					
		HRS/MSC	-				
SB 32-3662 RT	LANDING GEAR - MAIN LANDING GEAR (MLG) PISTON ASSEMBLY REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-JUN-2004		MOS					
		HRS/MSC	-				
SB 32-3881	LANDING GEAR - INSPECTION / REPLACEMENT OF NOSE LANDING GEAR (NLG) FORKS WITH IMPROPER HEAT TREATMENT, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-MAY-2008		MOS					
		HRS/MSC	-				
SB 32-3881 R01	LANDING GEAR - INSPECTION / REPLACEMENT OF NOSE LANDING GEAR (NLG) FORKS WITH IMPROPER HEAT TREATMENT, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-APR-2009		MOS					
		HRS/MSC	-				
SB 32-4010	LANDING GEAR - INTRODUCTION OF REMOTE CONTROL CIRCUIT BREAKER KIT, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-MAY-2012		MOS					
		HRS/MSC	-				
SL MTL-32-01 R01	LANDING GEAR - INSPECT THE STEERING SUPPORT BRACKET FOR INCORRECT BOLTS, SERVICE LETTER					RECOMMENDED	Complied With - LANDING GEAR INSPECTION OF INSTALLED PIN (CORRECT LENGHT) FROM STEERING SUPPORT BRACKET ATTACHMENT BOLTS PERFORMED I.A.W. SL MTL 32-01 R01 .FOUND CORRECT BOLTS ALREADY INSTALLED. SL MTL 32-01 R1 INCORPORATED
Eff. Date: 24-JUL-2019		MOS		20-MAY-2020			
		HRS/MSC	-	1151	-		
		AFL		537			
SL MTL-32-03	LANDING GEAR - LANDING GEAR CONTROL SWITCH INSPECTION, SERVICE LETTER					MANDATORY	
Eff. Date: 18-NOV-2022		MOS					
		HRS/MSC	-	-	-		
SL MTL-32-03 R01	LANDING GEAR - LANDING GEAR CONTROL SWITCH INSPECTION, SERVICE LETTER					MANDATORY	
Eff. Date: 02-DEC-2022		MOS					
		HRS/MSC	-	-	-		
SL MTL-32-04	LANDING GEAR - POWER PACK REMOTE CONTROL CIRCUIT BREAKER WIRING INSPECTION, SERVICE LETTER					MANDATORY	
Eff. Date: 01-MAR-2023		MOS	12		01-MAR-2024		
		HRS/MSC	200	-	1395.72		
ATA - 33 - LIGHTS							
SB 2635	LIGHTS - A125 ANNUNCIATOR CONTROL MODULE ASSEMBLY REPLACEMENT, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-JUN-1997		MOS					
		HRS/MSC	-				

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 33-3410	LIGHTS - FLASHING BEACON HARDWARE KIT IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-NOV-2000		MOS					
		HRS/MSC	-				
SB 33-3799	LIGHTS - CABIN INDIRECT LIGHTING MODIFICATION, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-JUL-2006		MOS					
		HRS/MSC	-				
ATA - 34 - NAVIGATION							
SB 2519	NAVIGATION/PITOT STATIC - COCKPIT VOICE RECORDER AUDIO INPUT INTERFACE STANDARDIZATION, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-SEP-1994		MOS					
		HRS/MSC	-				
SB 34-3355	NAVIGATION / PITOT STATIC - AIR DATA FLAG WITH STATIC SOURCE SWITCHING, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-MAY-2002		MOS					
		HRS/MSC	-				
SB 34-3435	NAVIGATION - MODIFICATION OF COLLINS TDR-94/94D STATUS -004 TRANSPONDER, SERVICE BULLETIN						Not Applicable
		MOS					
		HRS/MSC	-				
SB 34-3507 R05	AIR DATA COMPUTER (COLLINS ADC-85A) INCREASED ACCURACY (RVSM) STC ST01070SE, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-OCT-2003		MOS					
		HRS/MSC	-				
SB 34-3673	NAVIGATION - FLUX VALVE MOUNTING NUTPLATE INSPECTION/REPLACEMENT, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-AUG-2004		MOS					
		HRS/MSC	-				
SB 34-3679 R01	NAVIGATION - MAINTENANCE DIAGNOSTICS COMPUTER (MDC-3110) UPDATE, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-OCT-2004		MOS					
		HRS/MSC	-				
SB 34-3728	NAVIGATION - AVIONICS NOSE SHELF IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-SEP-2005		MOS					
		HRS/MSC	-				
SB 34-3738	NAVIGATION - ELECTRONIC STANDBY INSTRUMENT SYSTEM CIRCUIT BREAKER MODIFICATION, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-SEP-2005		MOS					
		HRS/MSC	-				
SL MTL-34-05	NAVIGATION - TRANSMITTAL OF COLLINS AEROSPACE SERVICE BULLETIN (SB) GPS-4X00()-34-515 FOR THE GPS -4000S GLOBAL POSITIONING SYSTEM, SERVICE LETTER					RECOMMENDED	
Eff. Date: 09-JAN-2026		MOS					
		HRS/MSC	-	-	-		
ATA - 36 - PNEUMATIC							
SC 290	TAIL DE-ICE BOOT PNEUMATIC SUPPLY TUBES, SAFETY COMMUNIQUE					INFORMATIONAL	Not Applicable
Eff. Date: 01-FEB-2008		MOS					
		HRS/MSC	-				
ATA - 39 - ELECTRICAL PANELS, PARTS AND INSTRUMENTS							

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 39-3103	EDGELIGHT/OVERHEAD LIGHT CONTROL PANEL, SERVICE BULLETIN						Not Applicable
		MOS					
		HRS/MSC	-				
ATA - 44 - CABIN SYSTEMS							
SB 44-4115	VENUE SYSTEM SOFTWARE UPGRADE, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-AUG-2012		MOS					
		HRS/MSC	-				
ATA - 52 - DOORS							
SC 251	AIRSTAIR/CABIN DOOR HOOK ANNUNCIATORS SWITCH CHECK, SAFETY COMMUNIQUE					INFORMATIONAL	Not Applicable
Eff. Date: 01-NOV-2004		MOS					
		HRS/MSC	-				
SB 52-3096 R01	NEW EXTERNAL DOOR OPERATING INSTRUCTIONS PLACARD, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-JUN-2002		MOS					
		HRS/MSC	-				
SB 52-3701	DOORS - CABIN/AIRSTAIR DOOR HOOK SWITCH INSTALLATION INSPECTION/MODIFICATION, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-DEC-2004		MOS					
		HRS/MSC	-				
SL MTL-52-03	DOORS - CARGODOORANDAIRSTAIRS LATCHING PLATE INSPECTION, SERVICE LETTER					RECOMMENDED	
Eff. Date: 06-JAN-2026		MOS					
		HRS/MSC	-	-	-		
SB MTL-52-04	DOORS - CARGO DOOR AND AIR STAIRS LATCHING PLATE WASHER INSPECTION, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 06-JAN-2026		MOS					
		HRS/MSC	-	-	-		
ATA - 53 - FUSELAGE							
SB 2472 R04	FUSELAGE - INSPECTION/MODIFICATION OF AFT FUSELAGE STRINGERS, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-JUL-2003		MOS					
		HRS/MSC	-				
SB 53-2472 R04	INSPECTION/MODIFICATION OF AFT FUSELAGE STRINGERS, SERVICE BULLETIN						Not Applicable
		MOS					
		HRS/MSC	-				
SB 53-3400 R01	WING-TO-FUSELAGE FUEL QUANTITY WIRING CONDUIT SEALING MODIFICATION, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-JUL-2003		MOS					
		HRS/MSC	-				
SB 53-3592	INSPECTION/INSTALLATION OF MISSING STRINGER CLIPS, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-JUL-2003		MOS					
		HRS/MSC	-				
SB 53-3855	FUSELAGE - INSPECTION/INSTALLATION OF MISSING RIVETS IN FUSELAGE NOSE SECTION, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-FEB-2008		MOS					
		HRS/MSC	-	-	-		
SB 53-4029	FUSELAGE - REPLACEMENT OF FUSELAGE FRAME CLIPS, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-FEB-2011		MOS					
		HRS/MSC	-				

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 53-4074	FUSELAGE - INSPECTION / INSTALLATION OF RIVETS IN MAIN ENTRY DOOR FRAME, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-JUN-2011		MOS					
		HRS/MSC	-				
SL MTL-53-03	FUSELAGE - CROSS TIE FASTENER INSPECTION AT FUSELAGE STATION 158.00, SERVICE LETTER					MANDATORY	
Eff. Date: 31-JAN-2023		MOS					
		HRS/MSC	-	-	-		
SL MTL-53-04	FUSELAGE - FORWARD FUSELAGE FASTENER INSPECTION, SERVICE LETTER					MANDATORY	
Eff. Date: 08-MAY-2023		MOS					
		HRS/MSC	-				
SL MTL-53-04 R03	FUSELAGE - FORWARD FUSELAGE FASTENER INSPECTION, SERVICE LETTER					MANDATORY	
Eff. Date: 08-MAY-2023		MOS	12		15-MAY-2024		
SL MTL-53-05	FUSELAGE - FILLER SHIM OR FASTENER INSTALLATION AT FUSELAGE STATION 207, SERVICE LETTER					MANDATORY	
Eff. Date: 15-AUG-2023		MOS					
		HRS/MSC	-	-	-		
SL MTL-53-06	FUSELAGE - CROSSTIE REINFORCEMENT INSTALLATION AT STA 179.525 AND STA 201.775, SERVICE LETTER					MANDATORY	
Eff. Date: 08-NOV-2024		MOS					
		HRS/MSC	-	-	-		
STC SA00263WI	INSTALLATION OF CARGO POD, SUPPLEMENTAL TYPE CERTIFICATE						Complied With
		MOS		20-MAY-2020			
		HRS/MSC	-	1151	-		
		AFL		537			
STC SA5151NM	DUAL AFT BODY STRAKES, SUPPLEMENTAL TYPE CERTIFICATE						Complied With
		MOS		23-JUN-2015			
		HRS/MSC	-				
ATA - 54 - NACELLES/PYLONS							
SB 2547	NACELLES/PYLONS - ANNOUNCEMENT OF FORWARD COWLING ATTACHMENT KITS, SERVICE BULLETIN					OPTIONAL	Not Applicable
Eff. Date: 01-NOV-1994		MOS					
		HRS/MSC	-				
SB 54-3970	NACELLES - INTRODUCTION OF FAIRING IMPROVEMENT KIT, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-JUL-2009		MOS					
		HRS/MSC	-				
SB 54-3970 R01	NACELLES - INTRODUCTION OF FAIRING IMPROVEMENT KIT, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-NOV-2009		MOS					
		HRS/MSC	-				
ATA - 55 - STABILIZERS							
SB 55-3082	STABILIZERS - INSPECTION OF THE VERTICAL STABILIZER REAR SPAR ASSEMBLY, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-FEB-1998		MOS					
		HRS/MSC	-				
SB 55-3551	ELEVATOR TRIM TAB ASSEMBLY RIVET INSPECTION/REPAIR, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-FEB-2003		MOS					
		HRS/MSC	-				

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 55-3552	RUDDER TRIM TAB ASSEMBLY RIVET INSPECTION/REPAIR, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-FEB-2003		MOS					
		HRS/MSC	-				
SB 55-3835	STABILIZERS - INSTALLATION OF EMPENNAGE INSPECTION ACCESS PANELS, SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 01-JUN-2008		MOS					
		HRS/MSC	-				
SB 55-4004	STABILIZERS - INSPECTION OF RUDDER ASSEMBLY FOR PROPER DRAINAGE, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-NOV-2009		MOS					
		HRS/MSC	-				
SB 55-4106	INSPECTION / INSTALLATION OF RIVETS ON THE VERTICAL STABILIZER AFT SPAR CAP, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-AUG-2012		MOS					
		HRS/MSC	-				
SB 55-4106 R01	INSPECTION / INSTALLATION OF RIVETS ON THE VERTICAL STABILIZER AFT SPAR CAP, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-MAR-2013		MOS					
		HRS/MSC	-				
SB 55-4106 R01 (INSPECT)	INSPECT INSPECTION / INSTALLATION OF RIVETS ON THE VERTICAL STABILIZER AFT SPAR CAP, SERVICE BULLETIN VERTICAL STABILIZER AFT SPAR CAP FASTENER EDGE DISTANCE					MANDATORY	Not Applicable
Eff. Date: 01-MAR-2013		MOS					
		HRS/MSC	-				
SB 55-4106 R01 (REPAIR)	REPAIR INSPECTION / INSTALLATION OF RIVETS ON THE VERTICAL STABILIZER AFT SPAR CAP, SERVICE BULLETIN IF NO RIVET INSTALLED AND/OR MISSING					MANDATORY	Not Applicable
Eff. Date: 01-MAR-2013		MOS					
		HRS/MSC	-				
ATA - 56 - WINDOWS							
SB 2273 R02	WINDOWS - INSTALLATION OF REPLACEMENT COCKPIT SIDE WINDOWS, WINDOW DEFROST KITS, AND WINDOW SHUTOFF VALVE KITS, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-NOV-1994		MOS					
		HRS/MSC	-				
ATA - 57 - WINGS							
SB 57-3867	WINGS - AILERON DRAIN HOLE INSPECTION, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-OCT-2007		MOS					
		HRS/MSC	-				
SB 57-3867 R01	WINGS - AILERON DRAIN HOLE INSPECTION, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-APR-2008		MOS					
		HRS/MSC	-	-	-		
SB 57-4126	WINGS - INSPECTION / REPLACEMENT OF INCORRECT RIVETS INSTALLED BY KIT P/N 101-4045, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-MAY-2013		MOS					
		HRS/MSC	-	-	-		
SB 57-4144	WINGS - AILERON HINGE SCREW INSPECTION, SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 01-FEB-2015		MOS		24-SEP-2015			
		HRS/MSC	-	31.6	-		
		AFL		24			

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB MTB-57-01	WINGS - INSPECT THE AFT UPPER AND LOWER WING BOLTS FOR CORRECT WASHER AND REPLACE IF NEEDED, SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 05-MAR-2020		MOS		20-MAY-2020			
		HRS/MSC	-	1151	-		
		AFL		537			
SB MTB-57-01 R01	WINGS - INSPECT THE AFT UPPER AND LOWER WING BOLTS FOR CORRECT WASHER AND REPLACE IF NEEDED, SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 14-APR-2020		MOS		20-MAY-2020			
		HRS/MSC	-	1151	-		
		AFL		537			
SB MTB-57-01 R01 LEFT	ACCOMPLISH WINGS - INSPECT THE AFT UPPER AND LOWER WING BOLTS FOR CORRECT WASHER AND REPLACE IF NEEDED, SERVICE BULLETIN INSPECT THE LEFT AFT UPPER AND LOWER WING BOLTS FOR CORRECT WASHER AND REPLACE IF NEEDED					RECOMMENDED	Complied With - INSTALLED 4X NEW WASHERS P/N 95-110025-7
Eff. Date: 14-APR-2020		MOS		20-MAY-2020			
		HRS/MSC	-	1151	-		
		AFL		537			
SB MTB-57-01 R01 RIGHT	ACCOMPLISH WINGS - INSPECT THE AFT UPPER AND LOWER WING BOLTS FOR CORRECT WASHER AND REPLACE IF NEEDED, SERVICE BULLETIN INSPECT THE RIGHT AFT UPPER AND LOWER WING BOLTS FOR CORRECT WASHER AND REPLACE IF NEEDED					RECOMMENDED	Complied With - WASHER REPLACED WITH PN 95-110025-7
Eff. Date: 14-APR-2020		MOS		20-MAY-2020			
		HRS/MSC	-	1151	-		
		AFL		537			
SL MTL-57-04	WINGS - CRACK INSPECTION - WING ATTACH FITTINGS AND OUTBOARD WING SPAR CAPS FOR HEAVYWEIGHT MODEL B300/B300C, SERVICE LETTER					MANDATORY	
Eff. Date: 21-FEB-2025		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
SL MTL-57-04 R01	WINGS - CRACK INSPECTION - WING ATTACH FITTINGS AND OUTBOARD WING SPAR CAPS FOR HEAVYWEIGHT MODEL B300/B300C, SERVICE LETTER					MANDATORY	
		MOS					
		HRS/MSC	3800	-	3800		
FAA 2026-15-05							
ATA - 61 - PROPELLERS/PROPULSORS							
SL MTL-61-01	PROPELLER - TRANSMITTAL OF MCCAULEY SERVICE LETTER SL2026-1 PROPELLER COUNTERWEIGHT ATTACH BOLT TORQUE VERIFICATION, SERVICE LETTER					MANDATORY	
Eff. Date: 03-APR-2026		MOS					
		HRS/MSC	25	-	1557.38		
ATA - 71 - POWER PLANT							
SB 2432	POWER PLANT - INSPECTION/REPLACEMENT OF THE ENIGNE MOUNT ASSEMBLY ATTACHMENT BOLTS, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-FEB-1992		MOS					
		HRS/MSC	-				
ATA - 72 - ENGINE							
SB 72-4117	ENGINE - ENGINE TRUSS INSPECTION / REPAIR, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-NOV-2013		MOS					
		HRS/MSC	-	-	-		
ATA - 73 - ENGINE FUEL AND CONTROL							

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 73-3634 PART I	ENGINE CONTROLS CROSS SHAFT/PEDESTAL MODIFICATION, SERVICE BULLETIN						Not Applicable
		MOS					
		HRS/MSC	-				
SB 73-3634 PART II	ENGINE CONTROLS CROSS SHAFT/PEDESTAL MODIFICATION, SERVICE BULLETIN					MANDATORY	Not Applicable
Eff. Date: 01-SEP-2003		MOS					
		HRS/MSC	-				
SL MTL-73-02	ENGINE FUEL AND CONTROL - INSPECTION OF FUEL PRESSURE SWITCH O-RING, SERVICE LETTER					MANDATORY	
Eff. Date: 02-MAY-2024		MOS					
		HRS/MSC	-	-	-		
ATA - 76 - ENGINE CONTROLS							
SC 196	INERTIAL VANE LINKAGE INSPECTION, SAFETY COMMUNIQUE					RECOMMENDED	Not Applicable
		MOS					
		HRS/MSC	-				
SC 196A	INERTIAL VANE LINKAGE REPLACEMENT, SAFETY COMMUNIQUE					RECOMMENDED	Not Applicable
		MOS					
		HRS/MSC	-				
ATA - 78 - EXHAUST							
STC SA8986SW	EXHAUST GAS EXTRACTOR EXHAUST INSTALLATION, SUPPLEMENTAL TYPE CERTIFICATE						Complied With
		MOS		20-MAY-2020			
		HRS/MSC	-	1151	-		
		AFL		537			
ENGINE NO. 1 - AD - PT6A-60A PCE-PK1818/3102700-01							
ATA - 61 - PROPELLERS/PROPULSORS							
FAA 2004-25-18	NO. 1 ENGINE - PROPELLER GOVERNOR - WOODWARD PROPELLER GOVERNOR ASSEMBLIES, P/N 8210-212H - REPLACE					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 18-JAN-2005		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
ATA - 72 - ENGINE							
FAA 2012-09-10	NO. 1 ENGINE - REMOVE FROM SERVICE PMA REPLACEMENT TAATI FIRST STAGE SUN GEAR AND THE PLANET GEARS FROM THE PROPELLERREDUCTION GEARBOX ASSEMBLY					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 23-MAY-2012		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
ATA - 75 - AIR							
FAA 1997-04-12	NO. 1 ENGINE - ENGINE - COMPRESSOR BLEED-VALVES (BOV'S) - INSPECT / REPLACE					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 14-MAR-1997		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
PT6A-72-13287 R01							
ATA - 78 - EXHAUST							
FAA 2002-23-13	NO. 1 ENGINE - EXHAUST - INSPECT TURBINE EXHAUST DUCTS FOR LOW-QUALITY WELDS AND CRACKS					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 31-DEC-2002		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ENGINE NO. 2 - AD - PT6A-60A PCE-PK1804/3102700-01							
ATA - 61 - PROPELLERS/PROPULSORS							
FAA 2004-25-18	NO. 2 ENGINE - PROPELLER GOVERNOR - WOODWARD PROPELLER GOVERNOR ASSEMBLIES, P/N 8210-212H - REPLACE					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 18-JAN-2005		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
ATA - 72 - ENGINE							
FAA 2012-09-10	NO. 2 ENGINE - REMOVE FROM SERVICE PMA REPLACEMENT TAATI FIRST STAGE SUN GEAR AND THE PLANET GEARS FROM THE PROPELLERREDUCTION GEARBOX ASSEMBLY					MANDATORY	Complied With - AT MANUFACTURE
Eff. Date: 23-MAY-2012		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
ATA - 75 - AIR							
FAA 1997-04-12	NO. 2 ENGINE - ENGINE - COMPRESSOR BLEED-VALVES (BOV'S) - INSPECT / REPLACE					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 14-MAR-1997		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
PT6A-72-13287 R01							
ATA - 78 - EXHAUST							
FAA 2002-23-13	NO. 2 ENGINE - EXHAUST - INSPECT TURBINE EXHAUST DUCTS FOR LOW-QUALITY WELDS AND CRACKS					MANDATORY	- C/W AT MANUFACTURER
Eff. Date: 31-DEC-2002		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
ENGINE NO. 1 - SB - PT6A-60A PCE-PK1818/3102700-01							
ATA - 72 - ENGINE							
SB 13006 R01	NO. 1 ENGINE - MODIFICATION OF OIL FILTER HOUSING CHECK VALVE, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 15-FEB-1984		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13008	NO. 1 ENGINE - INTRODUCTION OF IMPROVED NO. 3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY AND NEW NO. 4 BEARING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 20-OCT-1983		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13009	NO. 1 ENGINE - INTRODUCTION OF PROPELLER SHAFT OIL SEAL IMPROVED SUPPORT (SUPERSEDED BY SB PT6A-72-13173 R2), SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 09-APR-1984		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13010	NO. 1 ENGINE - REPLACEMENT OF GUIDE PIN REVERSING LEVER BRACKET ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 30-APR-1984		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13011 R02	NO. 1 ENGINE - REPLACEMENT OF OIL PRESSURE INDICATOR RESTRICTOR, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 15-SEP-1987		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13015	NO. 1 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE SHROUD HOUSING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 16-AUG-1983		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13018	NO. 1 ENGINE - MODIFICATION OF TORQUEMETER CYLINDER, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 04-OCT-1984		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13019	NO. 1 ENGINE - INTRODUCTION OF IMPROVED POWER TURBINE SHROUD AND NO. 2 BEARING HOUSING COVER FLANGE, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 20-JAN-1984		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13021 R01	NO. 1 ENGINE - MODIFICATION OF PROPELLER REVERSING LEVER, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 14-APR-1987		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13023	NO. 1 ENGINE - REPLACEMENT OF OIL TEMPERATURE BULB ADAPTER, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 28-NOV-1983		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13025 R01	NO. 1 ENGINE - MODIFICATION OF OUTER COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 10-APR-1987		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13026	NO. 1 ENGINE - INTRODUCTION OF NEW COMPRESSOR BEARING OIL NOZZLE AND STRAINER, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 09-APR-1984		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13028 R01	NO. 1 ENGINE - INTRODUCTION OF NEW NO. 3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 15-SEP-1987		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13032	NO. 1 ENGINE - REPLACEMENT OF REAR STATOR AIR SEAL ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 11-MAY-1984		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13034	NO. 1 ENGINE - INTRODUCTION OF NEW FUEL CONTROL UNIT INCORPORATING A SMALLER FUEL INLET FILTER, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 09-APR-1984		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13038 R01	NO. 1 ENGINE - INTRODUCTION OF T5 SINGLE THERMOCOUPLE AND DUAL BUS-BAR, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 20-AUG-1985		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13043	NO. 1 ENGINE - MODIFICATION OF COMPRESSOR TURBINE STATOR ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 28-FEB-1985		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13046 R01	NO. 1 ENGINE - INTRODUCTION OF POWER TURBINE HOUSING ASSEMBLY WITH FLOATING GROMMET, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 18-NOV-1986		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13047 R01	NO. 1 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE BLADES, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 28-FEB-1985		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13048 R02	NO. 1 ENGINE - INTRODUCTION OF NEW FUEL PUMP UNIT, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 18-FEB-1987		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13050	NO. 1 ENGINE - INTRODUCTION OF OIL TRANSFER PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 05-NOV-1984		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13052 R02	NO. 1 ENGINE - INTRODUCTION OF COMPRESSOR REAR HUB WITH INCREASED CYCLIC FATIGUE LIFE, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 21-JUN-1988		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13053	NO. 1 ENGINE - INTRODUCTION OF IMPROVED FIRST-STAGE COMPRESSOR BLADES, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 11-OCT-1984		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13055	NO. 1 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR STATOR ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 15-MAR-1985		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13058	NO. 1 ENGINE - INTRODUCTION OF IMPROVED FIRST-STAGE COMPRESSOR BLADES, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 19-SEP-1985		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13059	NO. 1 ENGINE - INTRODUCTION OF NEW THIRD-STAGE TURBINE VANE RING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 30-APR-1985		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13062 R2	NO. 1 ENGINE - INTRODUCTION OF NEW IMPROVED SWING CHECK VALVE ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 25-MAR-1986		MOS HRS/MSC ENC	 -	15-MAY-2014 -	 -		
SB 13065 R06	NO. 1 ENGINE - REPLACEMENT OF SHROUD HOUSING ASSEMBLY AND SMALL EXIT DUCT ASSEMBLY, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 25-JAN-1993		MOS HRS/MSC ENC	 -	15-MAY-2014 -	 -		
SB 13066	NO. 1 ENGINE - INTRODUCTION OF FINE MESH OIL FILTER ELEMENT, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 19-SEP-1985		MOS HRS/MSC ENC	 -	15-MAY-2014 -	 -		
SB 13067 R3	NO. 1 ENGINE - INTRODUCTION OF OUTER COMBUSTION CHAMBER LINER WITH IMPROVED SEALING FEATURE, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 29-JUN-1988		MOS HRS/MSC ENC	 -	15-MAY-2014 -	 -		
SB 13068 R1	NO. 1 ENGINE - MODIFICATION OF COMPRESSOR AIR SEALS, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 27-NOV-1990		MOS HRS/MSC ENC	 -	15-MAY-2014 -	 -		
SB 13069	NO. 1 ENGINE - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX HOUSING ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 30-APR-1985		MOS HRS/MSC ENC	 -	15-MAY-2014 -	 -		
SB 13071 R1	NO. 1 ENGINE - MODIFICATION OF TACHOMETER DRIVE BEVEL GEARSHAFT, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 08-JUL-1989		MOS HRS/MSC ENC	 -	15-MAY-2014 -	 -		
SB 13072 R1	NO. 1 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE DISK, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 15-SEP-1987		MOS HRS/MSC ENC	 -	15-MAY-2014 -	 -		
SB 13080 R01	NO. 1 ENGINE - INTRODUCTION OF NO. 3 BEARING COVER ANTIROTATION FEATURE, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 03-NOV-1986		MOS HRS/MSC ENC	 -	15-MAY-2014 -	 -		
SB 13082	NO. 1 ENGINE - INTRODUCTION OF IMPROVED SPARK IGNITERS, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 24-SEP-1985		MOS HRS/MSC ENC	 -	15-MAY-2014 -	 -		
SB 13086 R01	NO. 1 ENGINE - INTRODUCTION OF IMPROVED NO. 1 BEARING OUTER HOUSING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 27-AUG-1987		MOS HRS/MSC ENC	 -	15-MAY-2014 -	 -		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13089 R01	NO. 1 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE BLADES, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 17-MAR-1986		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13093 R02	NO. 1 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN					GROUP/CODE B4	Complied With - AT MANUFACTURE
Eff. Date: 12-MAR-1990		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13096 R01	NO. 1 ENGINE - INTRODUCTION OF IMPROVED REDUCTION GEARBOX REAR HOUSING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 02-SEP-1987		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13105	NO. 1 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE SHROUD HOUSING AND COMPRESSOR TURBINE SHROUD SEGMENTS, SERVICE BULLETIN					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 11-AUG-1987		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13108 R01	NO. 1 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE STATOR AIR SEAL WITH CLASSIFIED DIAMETER, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 02-JUN-1987		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13109 R02	NO. 1 ENGINE - INTRODUCTION OF IMPROVED NO. 1 BEARING AIR SEALS, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 18-SEP-1991		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13115	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 22-SEP-1987		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13116 R02	NO. 1 ENGINE - INTRODUCTION OF PROPELLER FLANGE SHIM, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 11-MAR-1988		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13121	NO. 1 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE SHROUD RETAINING RING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 27-AUG-1987		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13124 R02	NO. 1 ENGINE - MODIFICATION OF NO. 2 BEARING HOUSING COVER FLANGE, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 06-DEC-1991		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13126	NO. 1 ENGINE - INTRODUCTION OF PROPELLER SHAFT OIL SEAL RUNNER, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 02-AUG-1989		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13128	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE SHROUD SEGMENT RETAINING RING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 28-JAN-1988		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13129 R01	NO. 1 ENGINE - INRODUCTION OF IMPROVED THERMOSTATIC BY-PASS VALVE, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 26-APR-1991		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13130	NO. 1 ENGINE - REPLACEMENT OF NO. 3 BEARING COVER ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 25-JAN-1989		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13131	NO. 1 ENGINE - INTRODUCTION OF BLEED AIR CASE ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 31-MAR-1988		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13135	NO. 1 ENGINE - INTRODUCTION OF LOCKING WASHERS FOR ITT TERMINAL BOLTS, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 19-DEC-1988		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13136 R01	NO. 1 ENGINE - INTRODUCTION OF NEW COMPRESSOR TURBINE BOLT, SERVICE BULLETIN					GROUP/CODE B5	Complied With - AT MANUFACTURE
Eff. Date: 21-SEP-1990		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13144	NO. 1 ENGINE - INTRODUCTION OF IMPROVED NO. 4 BEARING OIL SUPPLY SYSTEM, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 19-OCT-1989		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13155 R02	NO. 1 ENGINE - INTRODUCTION OF IMPROVED GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 11-MAY-1992		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13159 R01	NO. 1 ENGINE - INTRODUCTION OF MODIFIED PROPELLER SHAFT AND SLEEVE SET, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 06-MAR-1992		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13163 R05	NO. 1 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX CENTER BEARING SUPPORT SLEEVE, SERVICE BULLETIN					CODE 4	Complied With - AT MANUFACTURE
Eff. Date: 31-MAY-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13173 R01	NO. 1 ENGINE - INTRODUCTION OF PROPELLER SHAFT OIL SEAL DUST SEAL, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 25-NOV-1991		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13174	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF NUMBER 3 & 4 BEARING PRESSURE OIL TUBE ASSEMBLY, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 06-MAR-1991		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13181	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE STATOR ASSEMBLY AND SHROUD HOUSING, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 06-NOV-1991		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13188 R1	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ROTOR ASSEMBLY, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 29-MAR-1993		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13189	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 13-DEC-1991		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13190 R01	NO. 1 ENGINE - REPLACEMENT OF OIL-TO-FUEL HEATER, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 12-MAY-1992		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13191	NO. 1 ENGINE - INTRODUCTION OF PROPELLER GEARBOX FRONT ACCESSORY DRIVE BEVEL GEAR AND ADJUSTING SPACER, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 23-MAR-1992		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13193 R01	NO. 1 ENGINE - REPLACEMENT OF T5 IMMERSION THEROCOUPLES, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 01-APR-1992		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13197 R01	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX HOUSING AND DIAPHRAGM ASSEMBLIES, KEYWASHERS AND CENTER BEARING RETAINING BOLTS, SERVICE BULLETIN					CODE 5	Complied With - AT MANUFACTURE
Eff. Date: 28-MAY-1992		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13201 R01	NO. 1 ENGINE - REPLACEMENTOF COMPRESSOR ROTOR ASSEMBLY AND NO. 1 BEARING OIL NOZZLE, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 16-OCT-1992		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13208	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE STATOR AIR SEAL AND GASKET, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 29-JUL-1992		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13214	NO. 1 ENGINE - REPLACEMENT OF GASKETS CONTAINING ASBESTOS FIBERS, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 02-DEC-1992		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13217	NO. 1 ENGINE - REPLACEMENT OF NO. 2 BEARING HOUSING COVER FLANGE, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 12-JUL-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13221	NO. 1 ENGINE - REPLACEMENT OF NO. 2 BEARING HOUSING-COVER FLANGE RETAINING BOLTS, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 28-JUN-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13223 R01	NO. 1 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKET, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 07-MAR-1994		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13224	NO. 1 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKET, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 12-AUG-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13225	NO. 1 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKETS, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 19-OCT-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13227	NO. 1 ENGINE - REPLACEMENT OF ASBESTOS FIBER INSULATION AND SHIELDS, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 04-NOV-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13228	NO. 1 ENGINE - REPLACEMENT OF PRIMARY FUEL-PRESSURE-TUBE ASSEMBLY, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 15-SEP-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13232	NO. 1 ENGINE - REPLACEMENT OF POWER-TURBINE ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 21-FEB-1994		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13234	NO. 1 ENGINE - REPLACEMENT OF IGNITION CABLE ASSEMBLY, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 26-NOV-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13235	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR-TURBINE STATOR ASSEMBLY, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 22-DEC-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13241	NO. 1 ENGINE - INTRODUCTION OF COMPRESSOR STATOR ASSEMBLIES, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 21-MAR-1994		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13242	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR BLEED-VALVE ASSEMBLY, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 24-MAR-1994		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13243	NO. 1 ENGINE - REPLACEMENT OF SCAVENGE PUMP HOUSING, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 04-APR-1994		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13001 R15	NO. 1 ENGINE - APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS, SERVICE BULLETIN						
Eff. Date: 08-JUL-2014		MOS					
		HRS/MSC	-				
SB PT6A-72-13031 R02	NO. 1 ENGINE - MODIFICATION OF EXHAUST DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 4	Complied With - AT MANUFACTURE
Eff. Date: 10-OCT-2002		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13134 R01	NO. 1 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE SHROUD SEGMENT RETAINING RING STOP, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 08-OCT-1998		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13141 R03	NO. 1 ENGINE - INTRODUCTION OF NEW COMPRESSOR TURBINE SHROUD SEGMENTS, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 08-OCT-1998		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13148 R2	NO. 1 ENGINE - INTRODUCTION OF NEW COMPRESSOR ROTOR REAR AIR SEAL, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 23-SEP-1997		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13152 R2	NO. 1 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX DRIVE SHAFT COUPLING SPACER, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 08-JUN-2000		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13161 R6	NO. 1 ENGINE - INTRODUCTION OF NEW ACCESSORY GEARBOX COUPLING SHAFT LOCKING FEATURE, SERVICE BULLETIN					CATEGORY 4	Complied With - AT MANUFACTURE
Eff. Date: 22-JAN-2007		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13172 R5	NO. 1 ENGINE - REPLACEMENT\MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLIES, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 08-JUN-2010		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13175 R2	NO. 1 ENGINE - INTRODUCTION OF P3 AIR FILTER HOUSING AND COVER WITH DRAIN VALVE, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 13-JUN-2000		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13177 R5	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF OUTER COMBUSTION - CHAMBER LINER ASSEMBLY, SERVICE BULLETIN					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 04-FEB-2013		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13179 R3	NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 17-FEB-2011		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13192 R1	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX HOUSING AND BEARING SUPPORT SLEEVE, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 04-FEB-2013		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13205 R1	NO. 1 ENGINE - REPLACEMENTOF NON-METALLIC RING SEAL, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 08-JAN-1997		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13206 R3	NO. 1 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX ASSEMBLY WITH SEPARATE COUPLING SHAFT AND DRIVE GEARSHAFT, SERVICE BULLETIN					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 11-JUL-2003		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13207 R2	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF GASKETS CONTAINING ASBESTOS FIBERS AND BLEED VALVE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 14-JUN-1996		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13226 R1	NO. 1 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKETS, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 05-JUN-2001		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13240 R01	NO. 1 ENGINE - COMPRESSOR ROTOR ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 22-JAN-1999		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13249 R2	NO. 1 ENGINE - REPLACEMENTOF THERMOCOUPLE WIRING HARNESS TERMINAL, SERVICE BULLETIN					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 24-NOV-1998		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13252 R1	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SECOND AND THIRD STAGE COMPRESSOR BLADES, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 19-JUL-1995		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13252 R2	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SECOND AND THIRD STAGE COMPRESSOR BLADES, SERVICE BULLETIN					CATEGORY 7	
Eff. Date: 06-NOV-2015		MOS					
		HRS/MSC	-				
SB PT6A-72-13255	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF FUEL CONTROL UNIT (FCU), SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 08-AUG-1994		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13256 R1	NO. 1 ENGINE - REPLACEMENT OF POWER TURBINE BLADES, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 06-JUN-2006		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13258 R1	NO. 1 ENGINE - REPLACEMENT OF VANE-RING RETAINING RING, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 08-JAN-1997		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13263 R1	NO. 1 ENGINE - MODIFICATION/INTRODUCTION OF ELECTRICAL GROUNDING PROVISION ON AGB HOUSING, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 07-SEP-2004		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13266	NO. 1 ENGINE - REPLACEMENT OF MAIN SCAVENGE-PUMP SCREEN ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 03-MAR-1995		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13267	NO. 1 ENGINE - INRODUCTION OF FUEL NOZZLE SHEATH, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 08-FEB-1995		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13268 R1	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR-TURBINE SHROUD-HOUSING, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 15-NOV-2001		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13270	NO. 1 ENGINE - REPLACEMENT OF IGNITION CABLE BRACKET, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 14-MAR-1995		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13274 R2	NO. 1 ENGINE - REPLACEMENT OF NO.3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 25-JUN-1997		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13275 R2	NO. 1 ENGINE - REPLACEMENT AND POWER TURBINE SHROUD MODIFICATION OF TURBINE EXHAUST DUCT , SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 20-JUN-2008		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13277	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY DRIVE PLAIN COVER, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 03-JUN-1996		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13280 R2	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF POWER TURBINE DISK ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 26-NOV-1999		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13282 R1	NO. 1 ENGINE - REPLACEMENT OF NO. 1 BEARING, SERVICE BULLETIN					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 09-OCT-1996		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13287 R01	NO. 1 ENGINE - ENGINE - INSPECT/REPLACE BLEED OFF VALVE COVER VALVE, SERVICE BULLETIN					CATEGORY 3	Complied With - AT MANUFACTURE
Eff. Date: 02-DEC-1996		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13290	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF IDENTIFICATION SUPPORT PLATE, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 20-MAY-1997		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13293	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 18-FEB-1997		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13297 R4	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF POWER TURBINE DISK ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 13-NOV-2003		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13301	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR DISK BALANCING ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-1998		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13302	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLE REVERSING LEVER, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 15-OCT-1998		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13307 R06	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN						Complied With - NO.1 ENGINE INSPECTION OF INSTALLED PIN FROM FUEL NOZZLES AND MANIFOLD ADAPTERS I.A.W. P&WC SB NO.13307 R06 AND R07.TABLE ACCEPTABLE FUEL MANIFOLD NOZZLE ASSEMBLIES. PERFORMED. ALL INSTALLED FUEL MANIFOLD NOZZLE ASSEMBLIES . ACCEPTABLE BY P/N FOR CONTINUOUS OPERATION. FOUND P& WC SB PT6A-72-13307 R06 AND R07 INCORPORATED.TABLE ACCEPTABLE FUEL MANIFOLD NOZZLE ASSEMBLIES. PERFORMED. ALL INSTALLED FUEL MANIFOLD NOZZLE ASSEMBLIES . ACCEPTABLE BY P/N FOR CONTINUOUS OPERATION. FOUND P& WC SB PT6A-72-13310 R04 AND R05 LNCORPORATED
		MOS HRS/MSC ENC	- -	20-MAY-2020 1151 537	- -		
SB PT6A-72-13307 R07	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 3	Complied With - ENGINE INSPECTION OF INSTALLED PIN FROM FUEL-NOZZLES AND MANIFOLDS ADAPTERS IAW PWC SB NO. 72-13307 R7 TABLE 1,ACCEPTABLE FUEL NOZZLE ASSEMBLIES INSTALLED
Eff. Date: 27-AUG-2019		MOS HRS/MSC ENC	- -	20-MAY-2020 1151 537	- -		
SB PT6A-72-13310 R04	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 3	Complied With - NO.1 ENGINE INSPECTION OF INSTALLED PIN FROM FUEL NOZZLES AND MANIFOLD ADAPTERS I.A.W. P&WC SB NO.13310 R04 AND R05.TABLE ACCEPTABLE FUEL MANIFOLD NOZZLE ASSEMBLIES. PERFORMED. ALL INSTALLED FUEL MANIFOLD NOZZLE ASSEMBLIES . ACCEPTABLE BY P/N FOR CONTINUOUS OPERATION. FOUND P& WC SB PT6A-72-13310 R04 AND R05 INCORPORATED
Eff. Date: 02-AUG-2019		MOS HRS/MSC ENC	- -	20-MAY-2020 1151 537	- -		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13310 R05	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 3	Complied With - NO. 1 ENGINE INSPECTION OF INSTALLED P/N FROM FUEL-NOZZLES AND MANIFOLDS ADAPTERS IAW PWC SB NO. 72-13310 R05 TABLE 1,ACCEPTABLE FUEL NOZZLE ASSEMBLIES INSTALLED BY P/N FOR CONTINUOS OPERATION.
Eff. Date: 27-AUG-2019		MOS HRS/MSC ENC	 - 	20-MAY-2020 1151 537	 - 		
SB PT6A-72-13312	NO. 1 ENGINE - REPLACEMENT OF GEARSHAFT FUEL CONTROL DRIVE AND FUEL PUMP, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 19-OCT-1998		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13313 R2	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 05-JAN-2005		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13319 R1	NO. 1 ENGINE - REPLACEMENT OF NO. 2 BEARING SCAVENGE-TUBE SEAL-RETAINING-PLATE, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 13-NOV-2001		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13321 R4	NO. 1 ENGINE - MODIFICATION OF SCAVENGE PUMP HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 13-NOV-2003		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13337	NO. 1 ENGINE - REPLACEMENT OF PROPELLER THRUST COVER ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 08-FEB-2000		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13338 R1	NO. 1 ENGINE - REPLACEMENT OF T-5 TRIM THERMOCOUPLE, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 10-JUL-2000		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13346 R1	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF OUTER/INNER LINER, SERVICE BULLETIN					CATEGORY 4	Complied With - AT MANUFACTURE
Eff. Date: 26-OCT-2000		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13352 R1	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 30-OCT-2001		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13354 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLER GOVERNOR, SERVICE BULLETIN					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 11-JUL-2003		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
FAA 2004-25-18							
SB PT6A-72-13355 R1	NO. 1 ENGINE - REPLACEMENT OF IGNITION EXCITER, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 07-JAN-2008		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13356 R1	NO. 1 ENGINE - MODIFICATION/REPLACEMENT OF OIL TO FUEL HEATER, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 30-NOV-2006		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13357 R1	NO. 1 ENGINE - REPLACEMENT OF PROTECTIVE CAPS AND PLUGS, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 19-FEB-2004		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13359	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SHIPPING CONTAINER SKID BASE, SERVICE BULLETIN					CATEGORY 9	Complied With - AT MANUFACTURE
Eff. Date: 22-AUG-2002		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13360	NO. 1 ENGINE - INTRODUCTION OF NEW OIL-TO-FUEL HEATER TRANSFER TUBE, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 01-FEB-2002		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13365	NO. 1 ENGINE - INTRODUCTION OF NEW THERMOSTATIC-BYPASS-VALVE TRANSFER TUBE, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 13-JUN-2002		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13369 R1	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR INLET CASE DRAIN PLUG, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 23-JAN-2003		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13371	NO. 1 ENGINE - REMOVAL OF AIR INLET SCREEN WASHERS, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 15-MAY-2003		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13379	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 23-OCT-2003		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13385 R1	NO. 1 ENGINE - REPLACEMENT OF PROPELLER SHAFT OIL SEAL RETAINING RINGS, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 31-AUG-2004		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13386	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR INLET CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 08-JUN-2004		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13392	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 17-SEP-2004		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13399 R1	NO. 1 ENGINE - REPLACEMENT OF SEAL PLAIN, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 24-OCT-2005		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13400	NO. 1 ENGINE - REPLACEMENT OF MAIN SCAVENGE PUMP HOUSING AND BODY ASSEMBLIES, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 17-JUN-2005		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13401	NO. 1 ENGINE - REPLACEMENT OF POWER-TURBINE SHAFT HOUSING, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 09-JUN-2006		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13405	NO. 1 ENGINE - REPLACEMENT OF STARTER GENERATOR DRIVE GEARSHAFT, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 31-OCT-2005		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13414 R2	NO. 1 ENGINE - REPLACEMENT P3 AIR-PRESSURE-TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 14-NOV-2006		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13422 R1	NO. 1 ENGINE - AIR INLET SCREEN - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 19-SEP-2007		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13423	NO. 1 ENGINE - THE OIL PRESSURE TUBE OF THE NO.3 & 4 BEARING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 25-SEP-2007		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13425 R2	NO. 1 ENGINE - REPLACEMENT OF CT ROTOR AIR-SEAL, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 18-SEP-2008		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13431	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 27-AUG-2009		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13444	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMPRESSOR INLET CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 04-DEC-2009		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13455	NO. 1 ENGINE - REPLACEMENT OF EXTERNAL COUPLING SCAVENGE OIL TRANSFER, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 29-APR-2011		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13456 R1	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR ROTOR AIR SEAL, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 08-JUL-2011		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13457	NO. 1 ENGINE - NO.2 BEARING OIL PACKING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 14-JUL-2011		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13458 R1	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLER-SHAFT OIL SEAL RETAINING-RING-HALVES, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 03-MAY-2013		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13459	NO. 1 ENGINE - REPLACEMENT OF LOCKWIRE, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 22-MAY-2013		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13487 R3	NO. 1 ENGINE - REPLACEMENT OF FILLER CAP AND OIL GAGE ASSEMBLY, SERVICE BULLETIN					CATEGORY 3	
Eff. Date: 21-JUL-2015		MOS					
		HRS/MSC	-				
SB PT6A-72-13487 R4	NO. 1 ENGINE - REPLACEMENT OF FILLER CAP AND OIL GAGE ASSEMBLY, SERVICE BULLETIN					CATEGORY 3	Complied With
Eff. Date: 16-SEP-2015		MOS		18-JUN-2018			
		HRS/MSC	-	756.7	-		
		ENC		357			
SB PT6A-72-13505	NO. 1 ENGINE - INSPECTION OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	Not Applicable
Eff. Date: 21-DEC-2018		MOS		13-JAN-2019			
		HRS/MSC	-	962.2	-		
		ENC		451			
ATA - 73 - ENGINE FUEL AND CONTROL							
SB PT6A-72-13323 R1	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR DELIVERY AIR PRESSURE INSULATED TUBE ASSEMBLY AND CLAMP, SERVICE BULLETIN					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 30-AUG-2010		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
ATA - 74 - IGNITION							

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13440 R1	NO. 1 ENGINE - REPLACEMENT OF IGNITION EXCITER, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 03-FEB-2010		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

ATA - 76 - ENGINE CONTROLS

SB PT6A-72-13416	NO. 1 ENGINE - REPLACEMENT OF BOLTS AND NUTS OF THE FCU CONNECTOR ROD, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 27-SEP-2007		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13426 R2	NO. 1 ENGINE - REPLACEMENT OF BOLT OF THE FCU CONNECTOR ROD, SERVICE BULLETIN					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 01-OCT-2007		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

ENGINE NO. 2 - SB - PT6A-60A PCE-PK1804/3102700-01

ATA - 72 - ENGINE

SB 13006 R01	NO. 2 ENGINE - MODIFICATION OF OIL FILTER HOUSING CHECK VALVE, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 15-FEB-1984		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13008	NO. 2 ENGINE - INTRODUCTION OF IMPROVED NO. 3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY AND NEW NO. 4 BEARING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 20-OCT-1983		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13009	NO. 2 ENGINE - INTRODUCTION OF PROPELLER SHAFT OIL SEAL IMPROVED SUPPORT (SUPERSEDED BY SB PT6A-72-13173 R2), SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 09-APR-1984		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13010	NO. 2 ENGINE - REPLACEMENT OF GUIDE PIN REVERSING LEVER BRACKET ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 30-APR-1984		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13011 R02	NO. 2 ENGINE - REPLACEMENT OF OIL PRESSURE INDICATOR RESTRICTOR, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 15-SEP-1987		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13015	NO. 2 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE SHROUD HOUSING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 16-AUG-1983		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13018	NO. 2 ENGINE - MODIFICATION OF TORQUEMETER CYLINDER, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 04-OCT-1984		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13019	NO. 2 ENGINE - INTRODUCTION OF IMPROVED POWER TURBINE SHROUD AND NO. 2 BEARING HOUSING COVER FLANGE, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 20-JAN-1984		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13021 R01	NO. 2 ENGINE - MODIFICATION OF PROPELLER REVERSING LEVER, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 14-APR-1987		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13023	NO. 2 ENGINE - REPLACEMENT OF OIL TEMPERATURE BULB ADAPTER, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 28-NOV-1983		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13025 R01	NO. 2 ENGINE - MODIFICATION OF OUTER COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 10-APR-1987		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13026	NO. 2 ENGINE - INTRODUCTION OF NEW COMPRESSOR BEARING OIL NOZZLE AND STRAINER, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 09-APR-1984		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13028 R01	NO. 2 ENGINE - INTRODUCTION OF NEW NO. 3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 15-SEP-1987		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13032	NO. 2 ENGINE - REPLACEMENT OF REAR STATOR AIR SEAL ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 11-MAY-1984		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13034	NO. 2 ENGINE - INTRODUCTION OF NEW FUEL CONTROL UNIT INCORPORATING A SMALLER FUEL INLET FILTER, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 09-APR-1984		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13038 R01	NO. 2 ENGINE - INTRODUCTION OF T5 SINGLE THERMOCOUPLE AND DUAL BUS-BAR, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 20-AUG-1985		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB 13043	NO. 2 ENGINE - MODIFICATION OF COMPRESSOR TURBINE STATOR ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 28-FEB-1985		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13046 R01	NO. 2 ENGINE - INTRODUCTION OF POWER TURBINE HOUSING ASSEMBLY WITH FLOATING GROMMET, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 18-NOV-1986		MOS HRS/MSC ENC		15-MAY-2014 -	 -		
SB 13047 R01	NO. 2 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE BLADES, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 28-FEB-1985		MOS HRS/MSC ENC		15-MAY-2014 -	 -		
SB 13048 R02	NO. 2 ENGINE - INTRODUCTION OF NEW FUEL PUMP UNIT, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 18-FEB-1987		MOS HRS/MSC ENC		15-MAY-2014 -	 -		
SB 13050	NO. 2 ENGINE - INTRODUCTION OF OIL TRANSFER PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 05-NOV-1984		MOS HRS/MSC ENC		15-MAY-2014 -	 -		
SB 13052 R02	NO. 2 ENGINE - INTRODUCTION OF COMPRESSOR REAR HUB WITH INCREASED CYCLIC FATIGUE LIFE, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 21-JUN-1988		MOS HRS/MSC ENC		15-MAY-2014 -	 -		
SB 13053	NO. 2 ENGINE - INTRODUCTION OF IMPROVED FIRST-STAGE COMPRESSOR BLADES, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 11-OCT-1984		MOS HRS/MSC ENC		15-MAY-2014 -	 -		
SB 13055	NO. 2 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR STATOR ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 15-MAR-1985		MOS HRS/MSC ENC		15-MAY-2014 -	 -		
SB 13058	NO. 2 ENGINE - INTRODUCTION OF IMPROVED FIRST-STAGE COMPRESSOR BLADES, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 19-SEP-1985		MOS HRS/MSC ENC		15-MAY-2014 -	 -		
SB 13059	NO. 2 ENGINE - INTRODUCTION OF NEW THIRD-STAGE TURBINE VANE RING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 30-APR-1985		MOS HRS/MSC ENC		15-MAY-2014 -	 -		
SB 13062 R2	NO. 2 ENGINE - INTRODUCTION OF NEW IMPROVED SWING CHECK VALVE ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 25-MAR-1986		MOS HRS/MSC ENC		15-MAY-2014 -	 -		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13065 R06	NO. 2 ENGINE - REPLACEMENT OF SHROUD HOUSING ASSEMBLY AND SMALL EXIT DUCT ASSEMBLY, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 25-JAN-1993		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13066	NO. 2 ENGINE - INTRODUCTION OF FINE MESH OIL FILTER ELEMENT, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 19-SEP-1985		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13067 R3	NO. 2 ENGINE - INTRODUCTION OF OUTER COMBUSTION CHAMBER LINER WITH IMPROVED SEALING FEATURE, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 29-JUN-1988		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13068 R1	NO. 2 ENGINE - MODIFICATION OF COMPRESSOR AIR SEALS, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 27-NOV-1990		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13069	NO. 2 ENGINE - INTRODUCTION OF IMPROVED ACCESSORY GEARBOX HOUSING ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 30-APR-1985		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13071 R1	NO. 2 ENGINE - MODIFICATION OF TACHOMETER DRIVE BEVEL GEARSHAFT, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 08-JUL-1989		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13072 R1	NO. 2 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE DISK, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 15-SEP-1987		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13080 R01	NO. 2 ENGINE - INTRODUCTION OF NO. 3 BEARING COVER ANTIROTATION FEATURE, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 03-NOV-1986		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13082	NO. 2 ENGINE - INTRODUCTION OF IMPROVED SPARK IGNITERS, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 24-SEP-1985		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13086 R01	NO. 2 ENGINE - INTRODUCTION OF IMPROVED NO. 1 BEARING OUTER HOUSING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 27-AUG-1987		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13089 R01	NO. 2 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE BLADES, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 17-MAR-1986		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13093 R02	NO. 2 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN					GROUP/CODE B4	Complied With - AT MANUFACTURE
Eff. Date: 12-MAR-1990		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB 13096 R01	NO. 2 ENGINE - INTRODUCTION OF IMPROVED REDUCTION GEARBOX REAR HOUSING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 02-SEP-1987		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB 13105	NO. 2 ENGINE - INTRODUCTION OF IMPROVED COMPRESSOR TURBINE SHROUD HOUSING AND COMPRESSOR TURBINE SHROUD SEGMENTS, SERVICE BULLETIN					OPTIONAL	Complied With - AT MANUFACTURE
Eff. Date: 11-AUG-1987		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB 13108 R01	NO. 2 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE STATOR AIR SEAL WITH CLASSIFIED DIAMETER, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 02-JUN-1987		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB 13109 R02	NO. 2 ENGINE - INTRODUCTION OF IMPROVED NO. 1 BEARING AIR SEALS, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 18-SEP-1991		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB 13115	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 22-SEP-1987		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB 13116 R02	NO. 2 ENGINE - INTRODUCTION OF PROPELLER FLANGE SHIM, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 11-MAR-1988		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB 13121	NO. 2 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE SHROUD RETAINING RING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 27-AUG-1987		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB 13124 R02	NO. 2 ENGINE - MODIFICATION OF NO. 2 BEARING HOUSING COVER FLANGE, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 06-DEC-1991		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB 13126	NO. 2 ENGINE - INTRODUCTION OF PROPELLER SHAFT OIL SEAL RUNNER, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 02-AUG-1989		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13128	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE SHROUD SEGMENT RETAINING RING, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 28-JAN-1988		MOS HRS/MSC ENC		15-MAY-2014 - 	 - 		
SB 13129 R01	NO. 2 ENGINE - INRODUCTION OF IMPROVED THERMOSTATIC BY-PASS VALVE, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 26-APR-1991		MOS HRS/MSC ENC		15-MAY-2014 - 	 - 		
SB 13130	NO. 2 ENGINE - REPLACEMENT OF NO. 3 BEARING COVER ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 25-JAN-1989		MOS HRS/MSC ENC		15-MAY-2014 - 	 - 		
SB 13131	NO. 2 ENGINE - INTRODUCTION OF BLEED AIR CASE ASSEMBLY, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 31-MAR-1988		MOS HRS/MSC ENC		15-MAY-2014 - 	 - 		
SB 13135	NO. 2 ENGINE - INTRODUCTION OF LOCKING WASHERS FOR ITT TERMINAL BOLTS, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 19-DEC-1988		MOS HRS/MSC ENC		15-MAY-2014 - 	 - 		
SB 13136 R01	NO. 2 ENGINE - INTRODUCTION OF NEW COMPRESSOR TURBINE BOLT, SERVICE BULLETIN					GROUP/CODE B5	Complied With - AT MANUFACTURE
Eff. Date: 21-SEP-1990		MOS HRS/MSC ENC		15-MAY-2014 - 	 - 		
SB 13144	NO. 2 ENGINE - INTRODUCTION OF IMPROVED NO. 4 BEARING OIL SUPPLY SYSTEM, SERVICE BULLETIN						Complied With - AT MANUFACTURE
Eff. Date: 19-OCT-1989		MOS HRS/MSC ENC		15-MAY-2014 - 	 - 		
SB 13155 R02	NO. 2 ENGINE - INTRODUCTION OF IMPROVED GAS GENERATOR CASE ASSEMBLY, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 11-MAY-1992		MOS HRS/MSC ENC		15-MAY-2014 - 	 - 		
SB 13159 R01	NO. 2 ENGINE - INTRODUCTION OF MODIFIED PROPELLER SHAFT AND SLEEVE SET, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 06-MAR-1992		MOS HRS/MSC ENC		15-MAY-2014 - 	 - 		
SB 13163 R05	NO. 2 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX CENTER BEARING SUPPORT SLEEVE, SERVICE BULLETIN					CODE 4	Complied With - AT MANUFACTURE
Eff. Date: 31-MAY-1993		MOS HRS/MSC ENC		15-MAY-2014 - 	 - 		
SB 13173 R01	NO. 2 ENGINE - INTRODUCTION OF PROPELLER SHAFT OIL SEAL DUST SEAL, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 25-NOV-1991		MOS HRS/MSC ENC		15-MAY-2014 - 	 - 		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13174	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF NUMBER 3 & 4 BEARING PRESSURE OIL TUBE ASSEMBLY, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 06-MAR-1991		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13181	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE STATOR ASSEMBLY AND SHROUD HOUSING, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 06-NOV-1991		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13188 R1	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ROTOR ASSEMBLY, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 29-MAR-1993		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13189	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 13-DEC-1991		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13190 R01	NO. 2 ENGINE - REPLACEMENT OF OIL-TO-FUEL HEATER, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 12-MAY-1992		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13191	NO. 2 ENGINE - INTRODUCTION OF PROPELLER GEARBOX FRONT ACCESSORY DRIVE BEVEL GEAR AND ADJUSTING SPACER, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 23-MAR-1992		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13193 R01	NO. 2 ENGINE - REPLACEMENT OF T5 IMMERSION THEROCOUPLES, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 01-APR-1992		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13197 R01	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX HOUSING AND DIAPHRAGM ASSEMBLIES, KEYWASHERS AND CENTER BEARING RETAINING BOLTS, SERVICE BULLETIN					CODE 5	Complied With - AT MANUFACTURE
Eff. Date: 28-MAY-1992		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13201 R01	NO. 2 ENGINE - REPLACEMENTOF COMPRESSOR ROTOR ASSEMBLY AND NO. 1 BEARING OIL NOZZLE, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 16-OCT-1992		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB 13208	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE STATOR AIR SEAL AND GASKET, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 29-JUL-1992		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13214	NO. 2 ENGINE - REPLACEMENT OF GASKETS CONTAINING ASBESTOS FIBERS, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 02-DEC-1992		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13217	NO. 2 ENGINE - REPLACEMENT OF NO. 2 BEARING HOUSING COVER FLANGE, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 12-JUL-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13221	NO. 2 ENGINE - REPLACEMENT OF NO. 2 BEARING HOUSING-COVER FLANGE RETAINING BOLTS, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 28-JUN-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13223 R01	NO. 2 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKET, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 07-MAR-1994		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13224	NO. 2 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKET, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 12-AUG-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13225	NO. 2 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKETS, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 19-OCT-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13227	NO. 2 ENGINE - REPLACEMENT OF ASBESTOS FIBER INSULATION AND SHIELDS, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 04-NOV-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13228	NO. 2 ENGINE - REPLACEMENT OF PRIMARY FUEL-PRESSURE-TUBE ASSEMBLY, SERVICE BULLETIN					CODE 6	Complied With - AT MANUFACTURE
Eff. Date: 15-SEP-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13232	NO. 2 ENGINE - REPLACEMENT OF POWER-TURBINE ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 21-FEB-1994		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13234	NO. 2 ENGINE - REPLACEMENT OF IGNITION CABLE ASSEMBLY, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 26-NOV-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB 13235	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR-TURBINE STATOR ASSEMBLY, SERVICE BULLETIN					CODE 7	Complied With - AT MANUFACTURE
Eff. Date: 22-DEC-1993		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 13241	NO. 2 ENGINE - INTRODUCTION OF COMPRESSOR STATOR ASSEMBLIES, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 21-MAR-1994		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB 13242	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR BLEED-VALVE ASSEMBLY, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 24-MAR-1994		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB 13243	NO. 2 ENGINE - REPLACEMENT OF SCAVENGE PUMP HOUSING, SERVICE BULLETIN					CODE 8	Complied With - AT MANUFACTURE
Eff. Date: 04-APR-1994		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13001 R15	NO. 2 ENGINE - APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS, SERVICE BULLETIN						
Eff. Date: 08-JUL-2014		MOS HRS/MSC	- -				
SB PT6A-72-13031 R02	NO. 2 ENGINE - MODIFICATION OF EXHAUST DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 4	Complied With - AT MANUFACTURE
Eff. Date: 10-OCT-2002		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13134 R01	NO. 2 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE SHROUD SEGMENT RETAINING RING STOP, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 08-OCT-1998		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13141 R03	NO. 2 ENGINE - INTRODUCTION OF NEW COMPRESSOR TURBINE SHROUD SEGMENTS, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 08-OCT-1998		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13148 R2	NO. 2 ENGINE - INTRODUCTION OF NEW COMPRESSOR ROTOR REAR AIR SEAL, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 23-SEP-1997		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13152 R2	NO. 2 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX DRIVE SHAFT COUPLING SPACER, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 08-JUN-2000		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		
SB PT6A-72-13161 R6	NO. 2 ENGINE - INTRODUCTION OF NEW ACCESSORY GEARBOX COUPLING SHAFT LOCKING FEATURE, SERVICE BULLETIN					CATEGORY 4	Complied With - AT MANUFACTURE
Eff. Date: 22-JAN-2007		MOS HRS/MSC ENC	- -	15-MAY-2014 - -	- -		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13172 R5	NO. 2 ENGINE - REPLACEMENT\MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLIES, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 08-JUN-2010		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13175 R2	NO. 2 ENGINE - INTRODUCTION OF P3 AIR FILTER HOUSING AND COVER WITH DRAIN VALVE, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 13-JUN-2000		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13177 R5	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF OUTER COMBUSTION - CHAMBER LINER ASSEMBLY, SERVICE BULLETIN					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 04-FEB-2013		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13179 R3	NO. 2 ENGINE - GAS GENERATOR CASE ASSEMBLY - REPLACEMENT/MODIFICATION OF, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 17-FEB-2011		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13192 R1	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX HOUSING AND BEARING SUPPORT SLEEVE, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 04-FEB-2013		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13205 R1	NO. 2 ENGINE - REPLACEMENTOF NON-METALLIC RING SEAL, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 08-JAN-1997		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13206 R3	NO. 2 ENGINE - INTRODUCTION OF ACCESSORY GEARBOX ASSEMBLY WITH SEPARATE COUPLING SHAFT AND DRIVE GEARSHAFT, SERVICE BULLETIN					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 11-JUL-2003		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13207 R2	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF GASKETS CONTAINING ASBESTOS FIBERS AND BLEED VALVE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 14-JUN-1996		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13226 R1	NO. 2 ENGINE - REPLACEMENT OF ASBESTOS FIBER GASKETS, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 05-JUN-2001		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		
SB PT6A-72-13240 R01	NO. 2 ENGINE - COMPRESSOR ROTOR ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 22-JAN-1999		MOS HRS/MSC ENC	-	15-MAY-2014 -	-		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13249 R2	NO. 2 ENGINE - REPLACEMENTOF THERMOCOUPLE WIRING HARNESS TERMINAL, SERVICE BULLETIN					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 24-NOV-1998		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13252 R1	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF SECOND AND THIRD STAGE COMPRESSOR BLADES, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 19-JUL-1995		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13252 R2	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF SECOND AND THIRD STAGE COMPRESSOR BLADES, SERVICE BULLETIN					CATEGORY 7	
Eff. Date: 06-NOV-2015		MOS					
		HRS/MSC	-				
SB PT6A-72-13255	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF FUEL CONTROL UNIT (FCU), SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 08-AUG-1994		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13256 R1	NO. 2 ENGINE - REPLACEMENT OF POWER TURBINE BLADES, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 06-JUN-2006		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13258 R1	NO. 2 ENGINE - REPLACEMENT OF VANE-RING RETAINING RING, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 08-JAN-1997		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13263 R1	NO. 2 ENGINE - MODIFICATION/INTRODUCTION OF ELECTRICAL GROUNDING PROVISION ON AGB HOUSING, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 07-SEP-2004		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13266	NO. 2 ENGINE - REPLACEMENT OF MAIN SCAVENGE-PUMP SCREEN ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 03-MAR-1995		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13267	NO. 2 ENGINE - INRODUCTION OF FUEL NOZZLE SHEATH, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 08-FEB-1995		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13268 R1	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR-TURBINE SHROUD-HOUSING, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 15-NOV-2001		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13270	NO. 2 ENGINE - REPLACEMENT OF IGNITION CABLE BRACKET, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 14-MAR-1995		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13274 R2	NO. 2 ENGINE - REPLACEMENT OF NO.3 AND NO. 4 BEARING OIL PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 25-JUN-1997		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13275 R2	NO. 2 ENGINE - REPLACEMENT AND POWER TURBINE SHROUD MODIFICATION OF TURBINE EXHAUST DUCT , SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 20-JUN-2008		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13277	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY DRIVE PLAIN COVER, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 03-JUN-1996		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13280 R2	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF POWER TURBINE DISK ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 26-NOV-1999		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13282 R1	NO. 2 ENGINE - REPLACEMENT OF NO. 1 BEARING, SERVICE BULLETIN					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 09-OCT-1996		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13287 R01	NO. 2 ENGINE - ENGINE - INSPECT/REPLACE BLEED OFF VALVE COVER VALVE, SERVICE BULLETIN					CATEGORY 3	Complied With - AT MANUFACTURE
Eff. Date: 02-DEC-1996		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13290	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF IDENTIFICATION SUPPORT PLATE, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 20-MAY-1997		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13293	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 18-FEB-1997		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13297 R4	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF POWER TURBINE DISK ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 13-NOV-2003		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13301	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR DISK BALANCING ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 18-MAR-1998		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13302	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLE REVERSING LEVER, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 15-OCT-1998		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13307 R06	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN						Complied With - NO.2 ENGINE INSPECTION OF INSTALLED PIN FROM FUEL NOZZLES AND MANIFOLD ADAPTERS I.A.W. P&WC SB NO.13307 R06 AND R07.TABLE ACCEPTABLE FUEL MANIFOLD NOZZLE ASSEMBLIES. PERFORMED. ALL INSTALLED FUEL MANIFOLD NOZZLE ASSEMBLIES . ACCEPTABLE BY P/N FOR CONTINUOUS OPERATION. FOUND P& WC SB PT6A-72-13307 R06 AND R07 INCORPORATED
		MOS HRS/MSC ENC	- -	20-MAY-2020 1151 537	- -		
SB PT6A-72-13307 R07	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 3	Complied With - NO. 2 ENGINE INSPECTION OF INSTALLED PIN FROM FUEL-NOZZLES AND MANIFOLDS ADAPTERS IAW PWC SB NO. 72-13307 R7 TABLE 1,ACCEPTABLE FUEL NOZZLE ASSEMBLIES INSTALLED
Eff. Date: 27-AUG-2019		MOS HRS/MSC ENC	- -	20-MAY-2020 1151 537	- -		
SB PT6A-72-13310 R04	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 3	Complied With - NO.2 ENGINE INSPECTION OF INSTALLED PIN FROM FUEL NOZZLES AND MANIFOLD ADAPTERS I.A.W. P&WC SB NO.13310 R04 AND R05.TABLE ACCEPTABLE FUEL MANIFOLD NOZZLE ASSEMBLIES. PERFORMED. ALL INSTALLED FUEL MANIFOLD NOZZLE ASSEMBLIES . ACCEPTABLE BY P/N FOR CONTINUOUS OPERATION. FOUND P& WC SB PT6A-72-13310 R04 AND R05 INCORPORATED
Eff. Date: 02-AUG-2019		MOS HRS/MSC ENC	- -	20-MAY-2020 1151 537	- -		
SB PT6A-72-13310 R05	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 3	Complied With - NO. 2 ENGINE INSPECTION OF INSTALLED P/N FROM FUEL-NOZZLES AND MANIFOLDS ADAPTERS IAW PWC SB NO. 72-13310 R05 TABLE 1,ACCEPTABLE FUEL NOZZLE ASSEMBLIES INSTALLED BY P/N FOR CONTINUOS OPERATION.
Eff. Date: 27-AUG-2019		MOS HRS/MSC ENC	- -	20-MAY-2020 1151 537	- -		
SB PT6A-72-13312	NO. 2 ENGINE - REPLACEMENT OF GEARSHAFT FUEL CONTROL DRIVE AND FUEL PUMP, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 19-OCT-1998		MOS HRS/MSC ENC	- -	15-MAY-2014 - 	- -		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13313 R2	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX DIAPHRAGM ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 05-JAN-2005		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13319 R1	NO. 2 ENGINE - REPLACEMENT OF NO. 2 BEARING SCAVENGE-TUBE SEAL-RETAINING-PLATE, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 13-NOV-2001		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13321 R4	NO. 2 ENGINE - MODIFICATION OF SCAVENGE PUMP HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 13-NOV-2003		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13337	NO. 2 ENGINE - REPLACEMENT OF PROPELLER THRUST COVER ASSEMBLY, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 08-FEB-2000		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13338 R1	NO. 2 ENGINE - REPLACEMENT OF T-5 TRIM THERMOCOUPLE, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 10-JUL-2000		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13346 R1	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF OUTER/INNER LINER, SERVICE BULLETIN					CATEGORY 4	Complied With - AT MANUFACTURE
Eff. Date: 26-OCT-2000		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13352 R1	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 30-OCT-2001		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13354 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLER GOVERNOR, SERVICE BULLETIN					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 11-JUL-2003		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
FAA 2004-25-18							
SB PT6A-72-13355 R1	NO. 2 ENGINE - REPLACEMENT OF IGNITION EXCITER, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 07-JAN-2008		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		
SB PT6A-72-13356 R1	NO. 2 ENGINE - MODIFICATION/REPLACEMENT OF OIL TO FUEL HEATER, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 30-NOV-2006		MOS HRS/MSC ENC	 - 	15-MAY-2014 - 	 - 		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13357 R1	NO. 2 ENGINE - REPLACEMENT OF PROTECTIVE CAPS AND PLUGS, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 19-FEB-2004		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13359	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF SHIPPING CONTAINER SKID BASE, SERVICE BULLETIN					CATEGORY 9	Complied With - AT MANUFACTURE
Eff. Date: 22-AUG-2002		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13360	NO. 2 ENGINE - INTRODUCTION OF NEW OIL-TO-FUEL HEATER TRANSFER TUBE, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 01-FEB-2002		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13365	NO. 2 ENGINE - INTRODUCTION OF NEW THERMOSTATIC-BYPASS-VALVE TRANSFER TUBE, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 13-JUN-2002		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13369 R1	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR INLET CASE DRAIN PLUG, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 23-JAN-2003		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13371	NO. 2 ENGINE - REMOVAL OF AIR INLET SCREEN WASHERS, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 15-MAY-2003		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13379	NO. 2 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 23-OCT-2003		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13385 R1	NO. 2 ENGINE - REPLACEMENT OF PROPELLER SHAFT OIL SEAL RETAINING RINGS, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 31-AUG-2004		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13386	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR INLET CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 08-JUN-2004		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13392	NO. 2 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 17-SEP-2004		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13399 R1	NO. 2 ENGINE - REPLACEMENT OF SEAL PLAIN, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 24-OCT-2005		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13400	NO. 2 ENGINE - REPLACEMENT OF MAIN SCAVENGE PUMP HOUSING AND BODY ASSEMBLIES, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 17-JUN-2005		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13401	NO. 2 ENGINE - REPLACEMENT OF POWER-TURBINE SHAFT HOUSING, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 09-JUN-2006		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13405	NO. 2 ENGINE - REPLACEMENT OF STARTER GENERATOR DRIVE GEARSHAFT, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 31-OCT-2005		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13414 R2	NO. 2 ENGINE - REPLACEMENT P3 AIR-PRESSURE-TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 14-NOV-2006		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13422 R1	NO. 2 ENGINE - AIR INLET SCREEN - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 19-SEP-2007		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13423	NO. 2 ENGINE - THE OIL PRESSURE TUBE OF THE NO.3 & 4 BEARING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 25-SEP-2007		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13425 R2	NO. 2 ENGINE - REPLACEMENT OF CT ROTOR AIR-SEAL, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 18-SEP-2008		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13431	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX HOUSING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 27-AUG-2009		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13444	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMPRESSOR INLET CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 04-DEC-2009		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13455	NO. 2 ENGINE - REPLACEMENT OF EXTERNAL COUPLING SCAVENGE OIL TRANSFER, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 29-APR-2011		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		
SB PT6A-72-13456 R1	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR ROTOR AIR SEAL, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 08-JUL-2011		MOS HRS/MSC ENC	- 	15-MAY-2014 - 	 - 		

© CAMP SYSTEMS

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB PT6A-72-13457	NO. 2 ENGINE - NO.2 BEARING OIL PACKING - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 14-JUL-2011		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13458 R1	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLER-SHAFT OIL SEAL RETAINING-RING-HALVES, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 03-MAY-2013		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13459	NO. 2 ENGINE - REPLACEMENT OF LOCKWIRE, SERVICE BULLETIN					CATEGORY 8	Complied With - AT MANUFACTURE
Eff. Date: 22-MAY-2013		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13487 R3	NO. 2 ENGINE - REPLACEMENT OF FILLER CAP AND OIL GAGE ASSEMBLY, SERVICE BULLETIN					CATEGORY 3	
Eff. Date: 21-JUL-2015		MOS					
		HRS/MSC	-				
SB PT6A-72-13487 R4	NO. 2 ENGINE - REPLACEMENT OF FILLER CAP AND OIL GAGE ASSEMBLY, SERVICE BULLETIN					CATEGORY 3	Complied With
Eff. Date: 16-SEP-2015		MOS		18-JUN-2018			
		HRS/MSC	-	756.7	-		
		ENC		357			
SB PT6A-72-13505	NO. 2 ENGINE - INSPECTION OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 3	Not Applicable
Eff. Date: 21-DEC-2018		MOS		13-JAN-2019			
		HRS/MSC	-	962.2	-		
		ENC		451			
ATA - 73 - ENGINE FUEL AND CONTROL							
SB PT6A-72-13323 R1	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR DELIVERY AIR PRESSURE INSULATED TUBE ASSEMBLY AND CLAMP, SERVICE BULLETIN					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 30-AUG-2010		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
ATA - 74 - IGNITION							
SB PT6A-72-13440 R1	NO. 2 ENGINE - REPLACEMENT OF IGNITION EXCITER, SERVICE BULLETIN					CATEGORY 7	Complied With - AT MANUFACTURE
Eff. Date: 03-FEB-2010		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
ATA - 76 - ENGINE CONTROLS							
SB PT6A-72-13416	NO. 2 ENGINE - REPLACEMENT OF BOLTS AND NUTS OF THE FCU CONNECTOR ROD, SERVICE BULLETIN					CATEGORY 6	Complied With - AT MANUFACTURE
Eff. Date: 27-SEP-2007		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					
SB PT6A-72-13426 R2	NO. 2 ENGINE - REPLACEMENT OF BOLT OF THE FCU CONNECTOR ROD, SERVICE BULLETIN					CATEGORY 5	Complied With - AT MANUFACTURE
Eff. Date: 01-OCT-2007		MOS		15-MAY-2014			
		HRS/MSC	-	-	-		
		ENC					

© CAMP SYSTEMS