Page No. 3

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
~~11/27/21~~	~~4299.96~~	~~1100.34~~		**TOTALS** brought forward from previous page
11/27/21	4299.96	1100.34	4299.96	Drained oil and replaced with 5 quarts Phillips XC 20w50 oil. Replaced CH48111-1 and safety wire. Engine test-run and no leaks noted. Brad Rowser BLR Owner, pilot license # 3261986
8-27-22			4343.83	Changed oil using 5 qts X/C and CH48111-1 filter. Leaks checked, no leaks noted. Comp Check #1 $\frac{75}{80}$ #2 $\frac{66}{80}$ #3 $\frac{73}{80}$ #4 $\frac{74}{80}$. I Certify that this engine has been inspected with ref to FAR 43 Append. X D for a 100hr inspection and it is approved for return to service. DJ Knof A&P 3268335
				SUB-TOTALS this page
				TOTALS-Carry forward to next page