Invoice

Sullivan Propeller Specialists

2156 American Avenue
Hayward, California 94545
tel: 510.782.0920 fax: 510.264.9162
FAA Repair Station No. S5UR963J

Date	Invoice No.
03/27/13	N8987

Bill To:
WEST VALLEY AIRCRAFT SERVICES PO BOX 52044 Palo Alto, CA 94303 wvmaintenance@gmail.com

Ship To
West Valley Aircraft Service 1901 Embarcadero Road Hangar B Palo Alto, CA 94303

PO/WO	Terms	Aircraft	Reg. No.	Ship Via	Model	Serial
WO 8884	Net 20			SPS Delivery	1A100MCM6950	F4291

Item	Description	Quantity	Price Each	Amount
PRec	Completely recondition propeller		607.00	607.00
Misc P&M	Miscellaneous Paint and Materials	1	131.00	131.00
Disc. PLabor	Propeller labor discount		-60.70	-60.70
Disc. PParts	Propeller parts discount		-13.10	-13.10
	Resale		0.00	0.00
			Total	$664.20

SERVICEABLE

PROPELLER — Unit Name
MCCAULEY — Manufacturer

1A100/MCM6950 — Model
F4291 — Serial

The propeller or appliance identified above was ~~repaired/~~overhauled and inspected in accordance with the 730720 overhaul and current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this repair station under:

WEST VALLEY AIRCRAFT SERVICE
Owner Name

8884 — Work Order Number
03/27/2013 — Date

Brian K. Sullivan

SULLIVAN PROPELLER SPECIALISTS
2156 American Avenue
Hayward, CA 94545
tel: 510.782.0920
fax: 510.264.9162
www.sullivanpropeller.com
FAA Repair Station No. S5UR963J

SPS-106 (front)