HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-L3YF-1RF/F8068

PROPELLER S/N FD511B

LOGBOOK #_____

PROPELLER MAINTENANCE RECORD

Position _____

Propeller Model PHC-L3YF-1RF/F8068

Propeller S/N FD511B

Blade Design _____

Blade S/N's

No. 1 K13403

No. 2 K13405

No. 3 K13402

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer _____

Aircraft Model P35

S/N D-7148

Registration N9763Y

Date	Propeller TSN	Propeller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
This propeller was installed in Bonanza N9763Y, S/N: D-7148 on Dec 15, 2004; see Airframe Logbook Entry of Same Date.				

June 13, 2007, Tach: 2522.4, T.S.P.O.H.: 0062.18. Annual Inspection Completed using Beechcraft Form 98 - 32227H and Part 43 Appendix D as a guide. **AD 05–14–11Propeller Work: N/A – No repair or maintenance work** performed by California Propeller on this propeller.

I certify that this **propeller** ***has been inspected in accordance with an Annual inspection and is determined to be in airworthy*** *Condition. AD's checked through 2007-10. Date June 13, 2007*

By Joseph L. Salazar *A&P585940179IA*

15 August, 2008 N9763Y Tach 2554.1
Hartzell PHC-L3YF-1RF S/N FD511B TT 93.9

NORTH VALLEY AVIATION
ALBUQUERUQE, NM

C/W an Annual inspection using the Beechcraft maintenance manual check list as a guide. Lubed hub with AeroShell # 6. I certify that this propeller has been inspected in accordance with an Annual inspection and found to be airworthy for return to service with to the above work performed.

David C Krueger
David C. Krueger A&P 460210305 IA

N9763Y 3-4-2013 Tach time 2575.6
Inspect propeller in accordance with Hartzel manual
David L Robertson
IA2193392

PROPELLER Hartzell PHC-L3YF-1RF, Serial Number: FD511B. February 24, 2020. Tach: 2641.52; TSPOH: 0181.32.
Annual Inspection completed using Raytheon Bonanza Series Maintenance Manual 100/Annual Inspection Form and FAR 43 Appendix (D), as a guide. AD2007-26-09 – "Y" Shank aluminum blades is N/A Due to blade serial numbers.

I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition. AD's checked thru February 24, 2020.

Joseph L. Salazar Joseph L Salazar A&P3497829IA

Date	Propeller TSN	Propeller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
5/24/2021			2652	Annual Inspection Complete
				IA 2143392
9/13/2021			2752	Annual Inspection Complete
				IA 2143392

10-22-25 N9763Y Tach: 2681.83 Prop SMOH: 0227.29

SOUTH DELTA AVIATION
4248 S. School Ave. Fayetteville, AR. 72701
1-479-935-4891

Checked propeller hub, and blades for condition, security, leaks, and dressed blades. Checked spinner and spinner support bulkhead for condition and security. Serviced propeller with Aero Shell #6 grease as per the hub decal, and the Propeller Owner's Manual 115N.

I certify that this propeller was inspected in accordance with an annual/100hr inspection, as per the FAR43 App. D checklist, and has been determined to be in an airworthy condition.

David Baker A&P3135015IA