NEPS

New England Propeller Service, Inc.

PROPELLER LOGBOOK

PROPELLER MAINTENANCE RECORD

~~LEFT ENGINE~~	RIGHT ENGINE
Hub Model 1C160/DTM 7557 M	Hub Model
Blade Design	Blade Design
Diameter	Diameter
Hub Ser. No. 736063	Hub Ser. No.
Blade Ser. Nos.	Blade Ser. Nos.
No. 1	No. 1
No. 2	No. 2
No. 3	No. 3
No. 4	No. 4
No. 5	No. 5
PITCH RANGE	PITCH RANGE
High _____ Low _____	High _____ Low _____
Feather _____ Reverse _____	Feather _____ Reverse _____
Governor Model	Governor Model

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		MAJOR OVERHAUL. BLADES REFINISHED, CHECKED TRACK, BALANCE, ANGLES AND PAINTED. HUB DYE CHECKED	
		AUTHORIZED BY	
		For NEW ENGLAND PROPELLER SERVICE, INC. EAST HADDAM, CT FAA REPAIR STATION # RC2R130L	
		TIME SINCE OVERHAUL -0-	

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
12-26-95	1969.3	INSTALLED THIS PROPELLER ON	
		N4739D / O-320 H2AD S/N L-5345-76.	
		TORQUED & SAFETY BOLTS TRACKED OK	
			Edward P Clauson A+ 36462575
2-6-96	2013.7	REMOVED PROP TO REPLACE BULKHEAD	
		P/N 0550321-10 - REINSTALLED IAW	
		SEC. 13 OF CESSNA MAINT. MANUAL.	
			Edward P. Clauson 36462575 AP
2-6-96	2013.7	AD 95-21-01 N/A	
2-1-97	2264.1	INSPECT / DRESS PROPELLER.	Louis H Allen 1451267
7-21-97	2463.9	INSPECTION.	Louis H Allen A/P 1451267
10-13-97	2563.9	INSPECTION.	Louis H Allen A/P 1451267
1-23-98	2663.0	INSPECTION.	Louis H Allen A/P 1451267

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
1-15-98	2663.0	ANNUAL INSPECTION, INSPECTED &	
TSOH	693.7	DRESSED PROP I CERTIFY THAT THIS	
		PROP HAS BEEN INSPECTED IAW CESSNA 172	
		SERIES SERVICE MANUAL & WAS DETERMINED	
		TO BE IN AN AIRWORTHY COND.	
			Edward P. Clawson AP3646575 AI
4-30-98	2762.1	100 HOUR INSPECTION	Louis H Allen AP1451267
7-31-98	2858.7	100 HOUR INSPECTION	Louis H Allen AP1451267
11-17-98	2958.6	100 HOUR / ANNUAL INSPECTION (TTSOH 989.3)	Edward P Clawson AP3646575 A
5-6-99	3058.5	100 HOUR INSPECTION (TTSOH 1089.2)	Edward Clawson AP3646575
9-29-99	3156.2	100 HOUR INSP.	Robert L. Woods AP1804288
~~7-4-01~~	~~3753.3~~	~~100 HOUR Insp C/W~~	~~Robert L. Woods~~
			~~AP1804288~~