2003 Beechcraft Premier I - Serial Number RB-59 – N230EC

Beechcraft Premier I S/N RB-59

HIGHLIGHTS

"N" Registration / U.S. Based

FAR Part 91 Owners

Engines Enrolled on Williams TAP Blue

Collins Pro Line 21 Avionics Upgrades

Triple Collins AFD-3010E 8x10" Displays

Dual Collins CDU-3000 Control Display Units

Collins GPS-4000S GPS Unit Upgrade

WAAS/LPV Upgrades

Honeywell MK V EGPWS

Collins TTR-4000 TCAS II

Collins DBU-5010 Data Base Unit Upgrade

Dual Collins TDR-94D Transponders

2024 Interior Upholstery & Plating Refurbishment

AIRFRAME

Total Time	3,574 Hours
Landings	2,612

CAMP Maintenance Tracking

Manufacturer's Recommended Inspection Program

Certification Date – March 14, 2003

Placed In Service – June 2, 2003

ENGINES

Williams International FJ44-2A

Enrolled on Williams TAP Blue

	Engine #1	Engine #2
Serial Number	105025	105028
Total Time Since New	3,508 Hours	3,574 Hours
Cycles Since New	2,590	2,612
Check 3 Complied With	2,552.9 Hours	2,552.9 Hours
Check 4 Due	5,000 Hours	5,000 Hours

Beechcraft Premier I S/N RB-59

AVIONICS

Rockwell Collins Pro Line 21 Integrated Avionics Suite
Collins FMC-3000 Flight Management Computer Upgrade
Dual Collins DCP-3030 Display Control Panels Upgrade
Dual Collins IOC 4110 Concentrator Units Upgrade
Collins GPS-4000S GPS Unit Upgrade
Dual Collins VIR-432 VHF Nav. Receivers
Dual Collins AHC-3000 AHRS Computers
Dual Collins VHF-422C VHF Communication Transceivers
Collins ALT-4000 Radio Altimeter
Collins DME-442 Distance Measuring Receiver
Dual Collins TDR-94D Transponders
Honeywell MK V EGPWS Computer
Collins TTR-4000 TCAS Traffic Collision Avoidance System
Electronic Jeppesen Charts Capable
Collins DBU-5010 Data Base Unit Upgrade
Triple Collins AFD-3010E 8”x10” Adaptive Flight Displays
Dual Collins CDU-3000 Control Display Units Upgrade
Collins FGP-3000 Flight Guidance Control Panel
Dual Collins OCM-3100 Options Control Modules Upgrade
Collins CCP-3000 Cursor Control Panel Upgrade
Collins ADC-3000 Air Data Computers
Collins Weather Radar RTA-854 Radar R/T
Collins Standby VHF Comm./Nav. Tuning Panel
Collins ADF-462 ADF Receiver
Bendix King KHF-950 HF Communication Provisioning
Collins MDC-3110 Maintenance Diagnostic Computer
Standby Altimeter / Attitude Indicator / Airspeed Indicators
Artex C406-2 Emergency Locator Transmitter
L3 Harris FA2100 CVR Cockpit Voice Recorder

Beechcraft Premier I S/N RB-59

AVIONICS UPGRADES/CERTIFICATIONS/CAPABILITIES

SBAS / LPV w/Vertical Guidance

WAAS

ADS-B Out (DO-260B)

TCAS II

Class A TAWS

RVSM

ADDITIONAL EQUIPMENT OPTIONS/UPGRADES

Whelan Aerospace LED Wing & Tail Anti-Collision Lights

Enviro Systems Air Conditioning

(2) Crew B/A Aerospace Oxygen Masks

Flight Deck RH & LH Jepp Manual Storage

Dual USB Outlets (USB-A & USB-C Ports) Installation

77 Cubic Foot Oxygen Bottle

AeroLEDs LED Landing Lights STC

(2) Crew Sun Visors

Securaplane XL244D Standby Battery

Galley Heated Refreshment Unit

Flushing Toilet

Beechcraft Premier I S/N RB-59

INTERIOR CONFIGURATION

Six (6) Passenger Cabin Configuration

Aft Two-Place Executive Seating

Right Forward Refreshment Cabinet / Closet

Cabin/Flight Deck Pocket Doors

Aft Lavatory w/Flushing Toilet & Storage

Nose Baggage Compartment

November 2024 Interior Upholstery & Plating Refurbishment

Forward Four-Place Executive Club Seating

Forward Club (2) Executive Tables

Passenger Dual Cupholders

Cabin/Aft Lavatory Pocket Doors

Cabin Seating Leather Custom Diamond Stitching

Aft External Access Baggage Compartment

CUSTOM PAINT

October 2018 Repaint

Matterhorn White Base

Red Lower Fuselage Base & Stripes

Phantom Gray Pearl Stripes

Beechcraft Premier I S/N RB-59

Beechcraft Premier I S/N RB-59

Beechcraft Premier I S/N RB-59

Beechcraft Premier I S/N RB-59

Beechcraft Premier I S/N RB-59

Beechcraft Premier I S/N RB-59

Beechcraft Premier I S/N RB-59

Beechcraft Premier I S/N RB-59

Beechcraft Premier I S/N RB-59

AXIOM
AVIATION

MIKE HERCHICK | OFFICE (216) 261-8934 | MIKE@AXIOMAV.COM

Axiom Aviation, Inc. | Cuyahoga County Airport | Cleveland, Ohio | www.AxiomAv.com

These specifications are presented as introductory information only. They do not constitute representations or warranties of any kind. Accordingly, purchaser should rely on their own inspection of this aircraft. This aircraft availability is subject to prior sale, and/or removal from the market.

IADA
ACCREDITED
DEALER
INTERNATIONAL AIRCRAFT
DEALERS ASSOCIATION