

Model HC-CZYL-1BR Serial # AL 9213

NEW Prop TSMC

Propeller Maintenance Record

Date/Tach		Prop TT/HR	Prop TT/HR	Aircraft TT/HR
12-11-02 100.5	Grassed Prop as per Handbook using Aeroshell #6 R. Brantly #2663284 REPAIRMAN EXPERIMENTAL CERTIFICATE	100.5	100.5	100.5
10-24-03 161.3	Grassed Prop as per MFG Handbook using Aeroshell #6 Robert Brantly R.E.C. 2663284	161.3	161.3	161.3
8/29/04 189.8	Grassed Prop as per MFG Handbook using Aeroshell #6 Robert Brantly REC 2663284	189.8	189.8	189.8
8/24/05 219.1	Grassed Prop as per Handbook using Aeroshell #6 R Brantly R.E.C 2663284	219.1	219.1	219.1
9/16/06 267.2	Grassed Prop as per MFG Handbook using Aeroshell #6 R Brantly R.E.C. 2663284	267.2	267.2	267.2
9/30/07	Grassed Prop as per MFG Handbook using Aeroshell #6 Robert Brantly R.E.C. #2663284	280.0	280.0	280.0
N 988 RP		Total Time		

Date/Tach	Propeller Maintenance Record	Prop TSMO	Prop TT/HR	Aircraft TT/HR
9/28/08 317.8	GREASED PROP AS PER MFG HANDBOOK USING ^{Aeroshell} #6 Grease Robert Brantley REC # 2663284	317.8	317.8	317.8
11/12/09 337.6	GREASED PROP AS PER MFG HANDBOOK USING ^{Aeroshell} #6 Grease Robert Brantley REC 2663284	337.8	337.8	337.8
9/10/10	GREASED PROP AS PER MFG HANDBOOK USING ^{Aeroshell} #6 Grease Robert Brantley REC 2663284	350.6	350.6	350.6
9/28/11	GREASED PROP AS PER MFG HANDBOOK USING ^{Aeroshell} #6 Grease Robert Brantley REC 2663284	359.3	359.3	359.3
9/16/12	GREASED PROP AS PER MFG HANDBOOK USING ^{Aeroshell} #6 Grease Robert Brantley REC. 2663284	368.7	368.7	368.7
N 988RP	Page No. 2	Total Time	368.7	368.7

Date/Tach	Propeller Maintenance Record	Prop TSMO	Prop TT/HR	Aircraft TT/HR
12-21-14 404.0	PROPELLER REMOVED FOR OVERHAUL. Hub & Bol AP 2694769	404.0 NEW	404.0	404.0
2-11-15	PROP O/H BY EAST COAST PROPELLER SERVICE, INC. W/O ER-10930 Hub & Bol AP 2694769			
7-20-16 404.0	PROPELLER INSTALLED ON FALCO F.8L NSIFL I.A.W. ^{AP 2694769} HARTZEL PROPELLER OWNER'S MANUAL 115N. Hub & Bol AP 2694769	- 0 -	404.0	404.0
9-4-17	PROP SERVICED I.A.W. 115N. Hub & Bol AP 2694769.	30.5	434.5	434.5
6-27-18	Balanced Prop to Dyna Vibe Model GX2 (result in rear of book) + woodwrench 2625425 ATP	49.0	453.0	453.0
10-1-18	Prop inspected in accordance to condition inspection	52.97	456.97	456.97
11/12/19	Examined prop for nicks/dents. Lubricated per Hartzel manual	56.6	560.6	560.6
8/24/20	installed new blades in existing Hartzel hub. GT V46 'Spitfire' blades PH GT 2V46-Y-182-FWS-	197.00	601.00	601.00
	1205RTC, 9N P202018, P202019. Minor change	1.0 since new		V46 Blades
N 988RP 51FL	Page No. 3	Total Time		

