

Reg: N14187  
Make: Lycoming  
Model: R-680-4  
Ser. No. 81087

### ENGINE LOG

*Southern Cal Aircraft Inc.*

1880 Joe Crosson Drive  
El Cajon, Ca. 92020  
619-448-5010

Date: 11-01-2018  
TT: 1578.9  
TSMOH: 378.9  
Hobbs: None

OF  
(ES.)

I certify that this Engine has been inspected in accordance with 100 Hr./ Annual Inspection procedure IAW Appendix "D" of Part 43 and determined airworthy this date.

Oil not changed at owners request, removed oil screen and inspected, no metal noted. Removed all spark plugs and cleaned, inspected and tested, installed with new copper gaskets (MS17840-1). Drained carburetor bowl. Removed exhaust stack at the lower engine #5 cylinder and replaced hardware with the correct hardware. Fabricated and replaced fuel supply hose to the carburetor Type "C" hose. Removed rocker covers and lubricated all rocker arms IAW Lycoming Service Manual, checked tappet clearance. Ran engine and charging system was inoperative, trouble shot and flashed the field and system charged properly. Engine serviced with 1 gallon of Aero Shell 60 wt 120 Grade mineral.

No AD's applicable this date.

Compression Test: 1, 74/80 2, 73/80 3, 76 /80 4) 77/80 5, 78/80 6, 76/80 7, 75/80 8, 75/80 9, 76/80

Except as stated above, no other work, inspection, corrective action or determination of airworthiness was made at this time.

Edward Q Hazlewood  
A&P 1655569  
Insp. Auth.



Date: 11-01-2018]