




*The Standard*

# PROPELLER LOG

*ASA-SP-L*



*The Standard*

# **PROPELLER LOG**

***ASA-SP-L***

**Propeller Record** General Information

**Propeller Manufacturer** McCawley

**Model** \_\_\_\_\_ **Type** \_\_\_\_\_

**Hub Series #** S/N 050036 **Blade #** D7292

**Date of Manufacture** 2005 D7291

**Aircraft Installed On:** **Make/Model** Cessna 182P **Serial #** 18262887

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: 2011	Total Time in Service	Description Started Propeller logbook separate from AIF log. Refer to Engine logbook entry dated 20 June 2005 for other info.
Date: 3/20		
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		

Year: _____	Total Time in Service	Description N774J a Cessna 182P S/N 17862887 Date: 03-24-2011 Tach 3815.4 TTAF 3815.4 Checked AD's through Issue 2011-06-11 no new noted I certify that this Propeller has been inspected IAW an annual inspection IAW FAR 43 Apex D and has been determined to be in an airworthy condition at thin time. New A&P 3496744 IA John Swasey
Date: _____	18262887	
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		



Calkins Aero Service Inc.

West Houston Airport  
18000 Groeschke Rd.  
Houston, TX 77084

Date: 4-6-2012 N774J TACH/TTAF:3890.4  
PSMOH:363.2

**ANNUAL INSPECTION**

Performed IAW 14 CFR FAR 43 appendix 'D' and Calkins Aero checklist:

I certify that this **PROP** has been inspected in accordance with **AN ANNUAL** Inspection and was determined to be in an **airworthy** condition.

Calkins Aero Service Inc.

FAA Certified Repair Station

No. GK2R849K

WO#20814

signed

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		

INSPECTIONS, REPAIRS AND ALTERATIONS



Calkins Aero Service Inc.

West Houston Airport  
18000 Groeschke Rd.  
Houston, TX 77084

DATE: 4/16/2013 N774J TACH/TTAF:3957.0

**ANNUAL INSPECTION:**

Performed IAW 14 CFR FAR 43 appendix 'D' and Calkins Aero checklist

I certify that this **PROP** has been inspected in accordance with **AN ANNUAL** Inspection and was determined to be in an **airworthy** condition.

Calkins Aero Service Inc.

FAA Certified Repair Station

No. GK2R849K

WO# 21952

signed

Beard's Aircraft Services, LLC

9852 Robinson Road  
Bell City, LA 70630

July 27<sup>th</sup>, 2014

McCauley

Model# 2A34C203-C

Ser.# 050036 Propeller Total Time: 3987.0 SMOH: 459.8

Completed 100 hour inspection this date in accordance with McCauley service manual and 14 CFR Part 43 Appendix D. Dressed leading edge nicks IAW MM. Checked spinner assembly and reinstalled.

I Certify this **PROPELLER** has been inspected in accordance with a **100 HOUR INSPECTION** and was determined to be in **AIRWORTHY** condition.

*[Signature]* A/P 003247387 7/27/14

Bruce A. Beard A&P 003247387

7/27/14

Bruce A. Beard, Owner-A&P/IA Phone/Fax: 337-598-4773, Mobile: 337-515-5643 Email: brucebeard@wb4me.com



Beard's Aircraft Services, LLC

9852 Robinson Road  
Bell City, LA 70630

August 9<sup>th</sup>, 2015

McCauley

Model# 2A34C203-C

Ser.# 050036 Propeller Total Time: 4018.0 SMOH: 490.8

Completed 100 hour inspection this date in accordance with McCauley service manual and 14 CFR Part 43 Appendix D. Dressed leading edge nicks IAW MM. Checked spinner assembly and reinstalled.

I Certify this **PROPELLER** has been inspected in accordance with a **100 HOUR INSPECTION** and was determined to be in **AIRWORTHY** condition.

*[Signature]* A/P 3247387 8/9/15

Bruce A. Beard A&P 3247387

8/9/15

Bruce A. Beard, Owner-A&P/IA Phone/Fax: 337-598-4773, Mobile: 337-515-5643 Email: brucebeard@wb4me.com



Beard's Aircraft Services, LLC

9852 Robinson Road  
Bell City, LA 70630

August 25<sup>th</sup>, 2016

McCauley

Model# 2A34C203-C

Ser.# 050036 Propeller Total Time: 4053.5 SMOH: 526.3

Completed 100 hour inspection this date in accordance with McCauley service manual and 14 CFR Part 43 Appendix D. Dressed leading edge nicks IAW MM. Painted the propeller as needed. Checked spinner assembly and reinstalled.

I Certify this **PROPELLER** has been inspected in accordance with a **100 HOUR INSPECTION** and was determined to be in **AIRWORTHY** condition.

 A&P 3247387 8/25/16

Bruce A. Beard A&P 3247387 8/25/16

Bruce A. Beard, Owner A&P/IA

Phone/Fax: 337-598-4773, Mobile: 337-515-5645

Email: bruceabeard@wb4me.com



BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Propeller S/N: 050036 has been overhauled on this date: 8/22/2018 I/A/W/ manual(s):

MPC200, SPM100, BOM100

Under W/O #: 17538. The Mechanic making THE INSTALLATION MUST C/W 14 cfr Part 43.9.

Texas Aircraft Propeller & Accessories  
1711 County Road 130, Pearland TX 77581

FAA CRS# 7RDR559C

Signed: 

I  
—  
Yea  
—  
Dat  
—  
Nex  
Due  
  
—  
Yea  
—  
Dat  
—  
Nex  
Due  
  
—  
Yea  
—  
Dat  
—  
Nex  
Due  
  
—  
Yea  
—  
Dat  
—  
Nex  
Due

August 28<sup>th</sup>, 2018

McCauley

Model# 2A34C203-C

Ser.# 050036 Propeller Total Time: 4094.0 SMOH: 0.0

Removed the propeller and sent out for overhaul. Propeller overhauled IAW w/o 17538, dated 8/22/18, Texas Aircraft Propeller & Accessories, CRS #7RDR559C. Installed the propeller and spinner IAW McCauley MM. Performed dynamic balance of propeller. Initial run showed .8 IPS. After adding weight to spinner, final run shows .11 IPS. Anything below .2 IPS is considered smooth by McCauley.

I Certify this **PROPELLER** has been inspected in accordance with a **100 HOUR INSPECTION** and was determined to be in **AIRWORTHY** condition.

 A+P 3247387 8/28/18

Bruce A. Beard A&P 3247387 8/28/18

Bruce A. Beard, Owner-A&P/IA Phone/Fax: 337-598-4773, Mcbile: 337-515-5643 Email: bruceabeard@wb4me.com



Y  
D  
N  
D  
  
Y  
D  
N  
D  
  
Y  
D  
N  
D

Beard's Aircraft Services, LLC

9852 Robinson Road  
Bell City, LA 70630

September 26<sup>th</sup>, 2019


McCauley

Model# 2A34C203-C

Ser.# 050036 Propeller Total Time: 4114.7 SMOH: 20.7

Completed 100 hour inspection this date in accordance with McCauley service manual and 14 CFR Part 43 Appendix D. Checked spinner assembly and reinstalled.

I Certify this **PROPELLER** has been inspected in accordance with a **100 HOUR INSPECTION** and was determined to be in **AIRWORTHY** condition.

 A+P 3247387 9/26/19

Bruce A. Beard A&P 3247387 9/26/19

Bruce A. Beard, Owner-A&P/IA Phone/Fax: 337-598-4773, Mobile: 337-515-5643 Email: bruceabeard@wb4me.com



Beard's Aircraft Services, LLC

9852 Robinson Road  
Bell City, LA 70630

November 1<sup>st</sup>, 2020

McCauley

Model# 2A34C203-C

Ser.# 050036 Propeller Total Time: 4225.1 SMOH: 131.1

Completed 100 hour inspection this date in accordance with McCauley service manual and 14 CFR Part 43 Appendix D. Checked spinner assembly and reinstalled.

I Certify this **PROPELLER** has been inspected in accordance with a **100 HOUR INSPECTION** and was determined to be in **AIRWORTHY** condition.

*Bruce A. Beard* A&P 3247387 11/1/2020

Bruce A. Beard A&P 3247387

11/1/2020

Bruce A. Beard, Owner A&P/IA

Phone/Fax: 337-598-4773, Mobile: 337-515-5643 Email: bruceabeard@wb4me.com



Beard's Aircraft Services, LLC

9852 Robinson Road  
Bell City, LA 70630

November 27<sup>th</sup>, 2021

McCauley

Model# 2A34C203-C

Ser.# 050036 Propeller Total Time: 4328.0 SMOH: 234.0

Completed 100 hour inspection this date in accordance with McCauley service manual and 14 CFR Part 43 Appendix D. Checked spinner assembly and reinstalled. Checked dynamic balance on the engine/propeller assembly. Test run shows .02 IPS @ 37 degrees from the reference blade. Any vibration below .20 IPS is considered smooth by McCauley.

I Certify this **PROPELLER** has been inspected in accordance with a **100 HOUR INSPECTION** and was determined to be in **AIRWORTHY** condition.

*Bruce A. Beard* A&P 3247387 11/27/21

Bruce A. Beard A&P 3247387

11/27/2021

Bruce A. Beard, Owner A&P/IA

Phone/Fax: 337-598-4773, Mobile: 337-515-5643 Email: bruceabeard@wb4me.com

